

Douglas County Surveyor's Record of  
Government Corners Renewed

26 T. S. 4 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Ben B. Irving  
Wit: G. Kohlhaugen  
McNeece  
1928

75  
 $\frac{1}{4}$  Section corner North Side of Section 1.  
South Side Section 36.  
Identified position from Orig. BT's.: One existing as Snag  
bearing proper scribe marks and Stump of O.B.T. in location  
called for in Orig. notes.  
Set a Dead Oak Post 4" x 4" x 36" for corner scribed, from which:  
36" Fir bears N.34°E. 275 lks. 2/1965 - SEARCHED FOR - NOT FOUND  
36" W.Oak bears N.20°W. 302 lks. V.R.T. LL.

James W. Byron  
M. Godfrey  
C. Putnam  
2/8/61  
C.S. File  
No. 49/125

76  
Section Corner to Sections 21 - 22 - 27 - 28.  
Found - Brass Cap "County Surveyor's Office, 1955."  
Renewed Corner No. 48 in this book.  
3 B.T's. as set in 1955. The Fir to the N. E. has been cut.,  
Stump still standing.  
Blaze & Scribe one New B.T.: 7" B.Oak N.5 $\frac{1}{2}$ °E. 30.0 ft. Mkd. "S22 CS BT".

77  
 $\frac{1}{4}$  Section Corner to Sections 16 and 21.  
Checked by Proportion - Fence Corner used for  $\frac{1}{4}$  Corner.  
Set -  $\frac{3}{4}$ " Iron Rod from which:  
27" Pine bears N.25°W. 12.8 ft. scribed  $\frac{1}{4}$  S16 CS BT.  
30" Pine bears S.25°E. 24.7 ft. scribed  $\frac{1}{4}$  S21 CS BT.

78  
Section Corner to Sections 16 - 17 - 20 - 21.  
Renew by Double Proportion.  
Set Brass Cap at Corner Mkd: County Surveyor's Office, 1961  

S17	S16	T26S	R4W
S20	S21		

  
New BT's: 10" B.Oak S.71°E. 53.9 ft. scribed S21 T26S R4W CS BT.  
21" B.Oak N.77°E. 105.4 ft. scribed S16 T26S R4W CS BT.

79  
 $\frac{1}{4}$  Corner to Sections 20 and 21.  
By Proportion.  
Set Brass Cap Mkd:  $\frac{1}{4}$  S20/S21 T26S R4W County Surveyor's Office, 1961.  
New BT's: 8" B.Oak N.33°W. 296.0 ft. scribed  $\frac{1}{4}$  S20 CS BT.  
7" W.Oak N.42°E. 360.0 ft. scribed  $\frac{1}{4}$  S21 CS BT.

80  
Center  $\frac{1}{4}$  Corner Section 16.  
 $\frac{1}{2}$ " I. Pipe Missing, Anchor Post used for Corner.  
Checks BT's. as per C. S. File No. M 13 - 43  
Set  $\frac{3}{4}$ " Iron Rod in N. S. Fence Line & using old BT's.

81  
 $\frac{1}{4}$  Corner to Sections 15 and 22.  
Found - Brass Cap (Bent) at Corner. We straighten & Reset Cap  
at same Location.  
Note - This Corner was renewed by B.B. Irving, 1947 but not recorded.  
We find  $\frac{1}{4}$ " Iron rod 74.0 ft. N.27°40'W., as shown in B.B.I. notes.  
We set  $\frac{3}{4}$ " iron rod South 7.0 ft. in South Fence Line of  
old County Road  
No Bearing Trees near. Tie to Iron Rod shown in C.S. File 39/88.

82  
Section Corner to Sections 20 - 21 - 28 - 29.  
Found - Iron Pipe with Brass Cap set by Richardson, 1947, Pipe was  
bent over & cap mashed into ground. REN. #41  
12" W.Oak S.31 $\frac{1}{2}$ °E. 32.8 ft., shows 2 good axe scars. Didn't cut open.  
28" W.Oak N.37 $\frac{1}{2}$ °E. 49.5 ft. (Orig. BT.) shows faint traces of  
scribing still visible on badly rotted old face.  
Other 3 BT's. mkd. in 1947 have all been bulldozed out, but stump  
holes & pieces of Oak Roots remain.  
Straighten & Reset Cap in its Orig. position. Drive Steel Fence  
Post alongside.  
New BT's: 11" W.Oak N.18°W. 42.9 ft. Mkd: T26S R4W S20 CS BT.  
7" W.Oak N.55°E. 46.4 ft. Mkd: T26S R4W S21 CS BT.  
20" D.Fir S.10°W. 70.5 ft. Mkd: T26S R4W S29 CS BT.  
Corner lies 25 ft. south of an E. W. Fence Line.

James W. Byron, Deputy  
Done For L. D. Blakeley  
Milo Godfrey & C. Putnam, Chairmen  
Feb. 9, 1961  
C.S. File No. 52/68  
Map File M 11 - 80

James W. Byron  
Clete Putnam  
June 30, 1961  
C. S. File  
No. 49/125

Milo E. Godfrey, Deputy  
Vernon Tracy & Mike Stone  
Sept. 11, 1962  
C.S. File No. 49/125

RE-RENEWED, SEE CORNER NO. #110