

**Douglas County Surveyor's Record of
Government Corners Renewed**

T. 26 S . T.S. R. 4 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21981

(Continued)

B.A. Shaner L.S.#430
For: J. Barnes
July 27, 1981
C.S. 58/229

bears S.85-1/2°E., 96.4-ft.
14" Alder BT, I barkscribed "T26S R4W NWC DLC 50 BT" bears
N.40°W., 75.2-ft.

120

Set - At the NW corner of D.L.C. #50, T26S, R4W, W.M., I set
a 2" I.P. with a 2-1/2" Brass Cap marked: "T26S R4W WM
N.W.C. D.L.C. NO. 50 RLS 430 1981".
Note - The courses for the above accessories go from this set B.C.
Note - This corner restoration is part of a road right of way survey
which probably will be completed at a later date.

7/27/81

Interior "L" corner, DLC #43

121

Found - 1971 County brass cap, properly mkd. lying alongside
gravel road with pipe badly bent. Ren. #104
14" fir, Ren. #8, now 30" stump with scribed "T" visible
in opened blaze.

Set - I set a 1" x 30" iron pipe with brass cap attached marked:
Douglas Co. Surveyor T268 Int. L R 4 W 1983
D.L.C. 43

Brass cap protrudes 12" above ground along west edge of one
lane gravel road. I place fence post & witness sign one foot
west of corner.

Bearings and distances used to set cap are:

From 30" fir stump, S. 48 1/2° W., 48.0 ft.
From 38" Oak, S.1°W., 185.1 ft.

New BT - 24" W. oak scribed "Int L DLC 43 CS BT" in double blaze bears
N.18°W., 179.8 ft.

Sketch in C.S. file.

5/12/83

Township corner for Sec. 36; Sec. 31, T.26-3; Sec. 1, T27-4 and
Sec. 6, T.27-3

122

Found - A 2 1/2" County brass cap on a 2" I.P., protrudes 4" above
ground, properly marked. Ren. #36
10" now a 32" dia. W. oak with a previously opened now rotted
face and a single well healed blaze per Ren. #84 bears S.76°W.,
175.7 ft. 1917 resurvey.
36" now a 48" dia. 3 ft. high D. fir stump with bark scribing
"S BT" bears S.6°E., 543.8 ft. Ren. #36
30" now a 30" 2 ft. high W. oak stump with a possible blaze, bears
N.15 1/2°W., 233.1 ft. (Rec. 231.5 ft. to face) Ren. 36
12" now a 22" D. fir with a well healed double blaze bears
S.26 1/2°E., 443.8 ft. (Rec. S.28°E., 444.6 ft.) Ren. #84

No original BTs found and the SW BT gone from 1947.

New BT - 6" dia. W. oak double blazed and scribed "T26S R3W S31 CS BT"
bears N.53 3/4°E., 293.1 ft.

Corner lies 6" north of an E-W fence line and approx. 200 ft. east of
Buckhorn Road in a pasture.

1/9/85

Section corner for secs. 18 and 19; and Secs. 13 & 24 of T.26-5

123

Found - A 1958 DCSO brass cap/I.P. protruding 12" above ground. Ren. #60
(Orig. stone not found)
10" now 26" W. Oak with a fully healed double blaze bears
S.42°53'W., 296.0 ft. (agrees with record)
13" now 22" dia. B. oak with a fully healed double blaze bears
N.11°52'E., 373.3 ft. (agrees with record).
New BTs - 13" W. oak double blazed & scribed "T26S R4W S19 CS BT" bears
S.72 1/2°E., 317.3 ft.
22" Pear, not scribed, (stands alone in open field) bears
N.17°W., 263.4 ft.

Corner lies in open field approx. 150 ft. north of North Bank Road.

Gregory Quibell
Deputy, Doug. Co.
Surveyors Office
John Powell
May 12, 1983
C.S. 62/7

RE-RENEWED, SEE NO. #124

By: Kris O'Shea
M#100-41A

Randall Smith
Stephen Flause
Douglas County
Surveyors Office
January 9, 1985
C.S. 62/25

Douglas Co. Surveyors
Office
Randall W. Smith
Stephen J. Flause
Deputies
C.S. 62/31
Feb. 5, 1986