

Douglas County Surveyor's Record of
Government Corners Renewed

26 T. S. 5 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

1/4 corner to secs. 14 and 23. 39
Corner reset from original B.T. - a 28 inch (now), S.79°W., 389.4 feet. Tree
alive and in good condition and scribed 1/4 S. We can not find the original
Northwest BT.
Set an 1 inch x 36 inch iron pipe with brass cap mkd. County Surveyor's
Office 1/4 cor. Sec. 14 T 26 R 5

Blaze and scribe:
15 inch W. O., S.84°12'W., 383.5 feet mkd. 1/4 S 23 CS BT.
7 inch B. O., N.30°W., 180.2 feet mkd. 1/4 S 14 CS BT.

Southeast corner of the Ardin A. Tyrell DLC 39. 40
Found 1 inch iron pipe at corner; A 36 inch B. O., (recorded 24 inch)
N.51°E., 52.2 feet (we find bearing to be N.58°E., 52.2 feet), chopped
out with some scribing visible. 36 inch B. O. (recorded 24 inch) S.70°W.,
107.6 feet (we find bearing to be S.77°W., 107.6 feet), original blaze
not chopped out and tree dead with center rotted. REV. # B
Blazed and scribed:
18 inch W. O., S.50°W., 6.0 feet mkd. N. E. Cl 41 CS BT.
10 inch W. O., N.41°W., 28.4 feet mkd. S. E. Cl 39 CS BT.

Reference Point to the S. E. Corner D.L.C. #45. *(SW Cor DLC #43)* 41
Set 1 1/2" x 32" Iron Pipe bears N.88°51'W. of S.E. Cor. D.L.C. #45,
which is also the N.E. Corner D.L.C. #44. 101
Set in the S. P. Ry. Right-of-Way, 36.3 ft. East of Centerline of
Main Line Track on E. W. Centerline of Section 7.

Renew Meander Corner to Sections 26 & 25. Lt. Bank N. Umpqua River. 42
Found - 3/4" I. P. at Corner, checks for bearing & distance to Orig.
BT., now 10" W. O. S.28°W. 33 ft. on old weathered face
found scribed T & parts of other scribe marks. I open
blaze at base, center rotted but find raised BT on
chip cut out.
S.E. BT. gone.
Scribed 10" W. O. S.5°E. 51.5 ft. M.C. S25 CS BT. 112
10" W. O. S.32 1/2°W. 45.5 ft. M.C. S26 CS BT.
Set Brass Cap at Corner Mkd: MC. S26/S25 T26S R5W County Surveyor's
Office, 1956.

Meander Corner to Sec. 24, T26S R5W, & Sec. 19, T26S R4W. 43
Found - Orig. 8", now 18" W. Oak S.63°E. 157.0 ft. I open near
base & find good scribing "BT".
Corner falls on River Bar. I set Brass Cap 165.0 ft.
South of M.C. I find no evidence of BT's. at this
point for 1/4 Corner 24/19. I do find 1" I.P. bears
S.29°W. 17.4 ft. This pipe may have been set for
1/4 Corner.
North - South Fence is 81.0 ft. West from Witness Corner.
Set Brass Cap for Wit. Cor. Mkd: Wit. Cor. 165 ft. North to
MC T26S County Surveyor's Office, 1958
R5W 24 | 19 R4W
New BT's: 7" W. Oak N.64°E. 16.4 ft. scribed WC MC S19 CS BT.
7" W. Oak S.35°W. 53.3 ft. scribed WC MC S24 CS BT.

Meander Corner to Sections 23 & 26 Right Bank. 44
Found - Orig. 36", now 48" Pine S.72 1/2°E. 29.0 ft., previously
opened, shows good scribing "BT".
No trace of Orig. N.E. BT.
Also find Woodford's Stake at Corner, See C.S. File No. 41/144
Note - M.C. is below high water line. I Set Witness Corner
70.0 ft. East of M.C.
Set Brass Cap at Witness Corner Mkd: Wit. Cor. 70.0 ft. West to
M.C. S23 T26S R5W County Surveyor's Office, 1958.
New BT's: S26
17" W. Oak bears S.64 1/2°E. 56.0 ft. scribed WC MC S26 CS BT.
8" W. Oak bears N.20°E. 37.6 ft. scribed WC MC S23 CS BT.

James W. Byron, Deputy County Surveyor
August - September, 1954.
C. S. File No. 46/74.

Wm Elmer
For Wilbur Lumber
June 12, 1948
40/105 103

James W. Byron
For Kahlhagen
Jan. 9, 1956
C. S. File No. 47/60

James W. Byron
Milo Godfrey
S. A. Bilow
Dec. 9, 1958
C. S. File No. 49/125

James W. Byron
Milo Godfrey
S. A. Bilow
Dec. 23, 1958
C.S. File No. 49/128

RENEWED, SEE CORNER NO #153

RENEWED, SEE CORNER NO. 112