

Douglas County Surveyor's Record of
Government Corners Renewed

T 26 T. S. 5 W. R. W. W. M.

ROCKE-CHAPMAN CO., EUGENE, ORE. 21881

67

G. Robert Lecklider
For Bernard Grubbe
September 1961
Map File M 21 - 29

$\frac{1}{4}$ Corner to Sec. 2, T26-5W. & Sec. 35, T25-5W.
Found - Oak Stump S:73 $\frac{1}{2}$ $^{\circ}$ W. 120 lks. B.T. destroyed by logging.
Renewed from notes I had from previous occasion.
Set - Steering Wheel Shaft.
24" P. Pine N. 07 $^{\circ}$ W. 40.7 ft.
14" Fir S. 65 $^{\circ}$ W. 37.4 ft.

68

Center $\frac{1}{4}$ Corner of Section 11.
Set - 1 $\frac{1}{2}$ " Iron Bar in Mound of Stone.
24" W. Oak S.84 $^{\circ}$ E. 69.7 ft.
10" W. Oak N.46 $^{\circ}$ W. 69.7 ft.

James W. Byron
Dale McFarland
March 23,
1962
C.S. File
No. 49/125

$\frac{1}{4}$ Corner to Sec. 32, T26-5W. & Sec. 5, T27-5W. 69
Found - Both Orig. BT's. Orig. 6", now 12" W. Oak N.55 $^{\circ}$ W. 27.7 ft.,
previously opened, shows good scribing "4".
24", now 30" B.Oak Snag S.7 $^{\circ}$ E., not S.3 $^{\circ}$ E. 92.4 ft, not 96.4 ft.,
shows good scribing

Fence Corner Thus: 

Set Brass Cap at Cor. Mkd: $\frac{1}{4}$ $\frac{S32}{S5}$ T26S R5W County Surveyor's
T27S Office, 1962
New BT's: Rescribe Orig., now 12" W.Oak N.55 $^{\circ}$ W. 27.7 ft. "CS BT".
7" W.Oak S.19 $^{\circ}$ W. 21.4 ft. scribed $\frac{1}{4}$ S 5 CS BT.

James W. Byron
Dale McFarland
& J. Powell
April 27, 1962
C.S. File No.
49/125

$\frac{1}{4}$ Corner to Sections 31, T26-5W. & Sec. 6, T27-5W. 70
Found - Orig. 9", now 24" W.Oak S.29 $^{\circ}$ E. 108.9 ft., shows good
reverse scribing on old face "S".
Orig. N.W. Bearing Tree not found.
Note - Corner falls in center of small stream, se5 Wit. Cor. 10 ft. West.
Set - Brass Cap & Mkd: Wit. Cor. 10.0 ft. East to $\frac{1}{4}$ $\frac{S31}{S6}$ T26S R5W
County Surveyor's Office, 1962 T27S
New BT's: 7" W.Oak bears N.38 $^{\circ}$ E. 25.4 ft. scribed W.C. $\frac{1}{4}$ S31 CS BT.
5" W.Oak bears S.61 $^{\circ}$ W. 5.5 ft. scribed W.C. $\frac{1}{4}$ S 6 CS BT.

Milo E. Godfrey,
Deputy
V. Tracy & M. Stone
April 9, 1963
C.S. File
No. 49/125

Sec. Cor. to Secs. 31 - 32, T26-5W. & Sec.s 5 - 6, T27-5W. 71
Found - Black Oak, (not White Oak) N.31 $\frac{1}{2}$ $^{\circ}$ W. 97.0 ft., now 18".
Tree almost dead, badly rotted inside, cut open & fd. good
reverse scribing, face above completely rotted away.
Badly burned Bl. Oak Stump S.60 $\frac{1}{2}$ $^{\circ}$ E. 68.0 ft. Center & North &
West sides of stump completely burned away.
No trace of N.E. Or S.W. Trees.
Set - Brass Cap at Cor. Mkd: County Surveyor's $\frac{S31}{S6}$ | $\frac{S32}{S5}$ T26S
Office, 1963 T27S
New BT's: 9" Bl. Oak N.31 $^{\circ}$ W. 11.7 ft. Mkd: T26S R5W S31 CS BT.
10" W.Oak N.22 $^{\circ}$ E. 19.8 ft. Mkd: T26S R5W S32 CS BT.
16" Bl.Oak S.31 $^{\circ}$ W. 22.3 ft. Mkd: T27S R5W S6 BS BT.
6" W.Oak S.79 $\frac{1}{2}$ $^{\circ}$ E. 66.5 ft. Mkd: T27S R5W S5 CS BT.
Corner lies approximately 45 ft. west of top of spur sloping South.

Milo E. Godfrey
& Crew
For Bob Franks
C.S. 52/54
M 26 - 67

Intersection of Sec. Line & E. Line DLC No. 39. 72
Set - Brass Cap at intersection of section line between Sections 14 & 23,
T.26S R5W and East Line D.L.C. #39 Mkd:
County Surveyor's Office, 1963

	Sec.	LINE	Line
		D.L.C.	

New BT's: 11" W.Oak N. 27 $^{\circ}$ E. 51.1 ft. Mkd: Int. CS BT.
6" W. Oak S. 81 $^{\circ}$ W. 54.4 ft. Mkd: Int., CS BT.
Sept. 27, 1963

N. E. Richard-
son
C.S. File No
39/54

$\frac{1}{4}$ Section Corner to Sections 20 and 29. 73
Found - Old Bearing Trees: Remarked Fir in Bark N.83 $^{\circ}$ E. 18.3 ft. 79
Set - 1 $\frac{1}{2}$ " x 30 $\frac{1}{2}$ " I. Pipe
New BT: 10" Fir S.42 $\frac{1}{2}$ $^{\circ}$ W. 23.4 feet.

October 29, 1946