

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 26 S. T. S. R. 5 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

107

$\frac{1}{4}$  Corner to Sections 5 and 8.  
Found - Charred Oak Snag S.57°E. 17.2 ft., cut open & find good scbng.  
Stump Hole N.17°E. 130.7 ft. Top of Oak tree lying downhill  
from stump hole. Trunk of tree completely burned away.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T26S R5W  $\frac{1}{4}$   $\frac{S 5}{S 8}$   
Office, 1964  
New BT's: 24" D.Fir N.1 $\frac{1}{2}$ °E. 60.7 ft. Mkd:  $\frac{1}{4}$  S5 CS BT.  
9" D.Fir S.55°W. 78.2 ft. Mkd:  $\frac{1}{4}$  S8 CS BT.  
Note - Fence corner, fences W. & N. bears N. 68° W., 12.0 ft.

108

$\frac{1}{4}$  Corner to Sections 3 and 10.  
Found - 22" W.Oak N.33 $\frac{1}{2}$ °E. 27.7 ft. (to face). Previously opened,  
fragments of unmistakable scribing visible on old face.  
32" W.Oak S.37 $\frac{1}{2}$ °W. 74.6 ft. (to face), shows good scar.  
Did not open.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T26S R5W  $\frac{1}{4}$   $\frac{S 3}{S 10}$   
Office, 1964  
New BT's: 12" W.Oak S. 8° E. 18.2 ft. Mkd:  $\frac{1}{4}$  S10 CS BT.  
14" D.Fir N. 9° E. 50.4 ft. Mkd:  $\frac{1}{4}$  S 3 CS BT.  
Note - Corner lies approx. 50 ft. south of small creek (winter).

109

Section Corner to Sections 3 - 4 - 9 - 10.  
Found - Stump Hole & Oak Log. S.34 $\frac{1}{2}$ °E. 72.6 ft. Opened & found  
reverse scribing "S" & "BT".  
12" W.Oak S. 2° W. 109.6 ft., opened & found good scribing,  
Tree fell after opening.  
20" Bl.Oak N.14 $\frac{1}{2}$ °W. 244.9 ft., shows scar, Did not open.  
Stump hole & rotted remnants of Oak Tree N.69 $\frac{1}{2}$ °E. 227.7 ft.  
Found overgrowth of old scar, badly rotted, no scrbng.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T26S R5W  $\frac{S 4}{S 9}$  |  $\frac{S 3}{S 10}$   
Office, 1964  
New BT's: 8" W.Oak S.72°E. 21.4 ft. Mkd: T26S R5W S10 CS BT.  
9" W.Oak N.29°E. 90.6 ft. Mkd: T26S R5W S3 CS BT.  
22" W.Oak N.65°W. 135.0 ft. Mkd: T26S R5W S4 CS BT.  
16" W.Oak S.18°W. 37.0 ft. Mkd: T26S R5W S9 CSBT.

110

$\frac{1}{4}$  Corner common to Sections 5 and 4.  
Found - 72" Fir Stump S.69°W. 23.8 ft., opened & found reverse  
scribing, old face at approx. 44" diam., ring count  
shows correct age. No trace of S. E. BT.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1964  
T26S R5W  $\frac{1}{4}$  S 5/S 4  
New BT's: 10" D.Fir N.58°W. 26.0 ft. Mkd:  $\frac{1}{4}$  S 5 CS BT.  
12" D.Fir S.10°E. 57.8 ft. Mkd:  $\frac{1}{4}$  S 4 CS BT.  
Note - 3-Way fence corner (fences approx. E.-W. & N.) bears S.55°E. 20.ft.

$\frac{1}{4}$  Corner common to Sections 26 and 35.  
Found -  $\frac{1}{2}$ " I.Pipe at Corner, set by Frear, 1947. See Ren. No. 19.  
15" W.Oak N.54°E. 17.0 ft., lower scar opened prev., scrbng. vis.  
White Oak Stump S.31°E. 37.9 ft., scar visible.  
New BT: 9" White Oak S.11°E. 33.5 ft. Mkd:  $\frac{1}{4}$  S35 CS BT.  
Note - Corner is approximately 50 ft. east of centerline of Sunshine  
Ranch Road.

112

Meander Corner Sections 26 and 25 (Left Bank)  
Found - Brass Cap set in 1956 - Also  $\frac{3}{4}$ " Pipe. See Ren. No. 42.  
10" W.Oak S.32 $\frac{1}{2}$ °W. 45.5 ft., alive & in good condition.  
10" W.Oak S.5°E. 51.5 ft. Top broken out, may not last long.  
10" W.Oak S.28°W. 33 ft., is in very poor condition.  
New BT: 20" D.Fir S.44°W. 41.7 ft. Mkd: "M. C. S26 CS BT".  
No trees available to East of Line.

Milo E. Godfrey, Deputy County Surveyor  
Wm. Stoffel - Mike Stone - Mike Darby  
March 1964  
C. S. File No. 49/125

RE-NEWED CORNER #154