

Douglas County Surveyor's Record of
Government Corners Renewed

T. 26 S. T. S. R. 5 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

113

$\frac{1}{4}$ Corner common to Sec. 19, R5W and Sec. 24, R6W.
Found - 22" White Oak S.24 $\frac{1}{2}$ °E. 159.1 ft. Cut open & found good
scribing "S". Other Tree not found.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1964
T26S R6W $\frac{1}{4}$ S 24/8 19 R5W
New BT's: 15" W.Oak S.13 $\frac{1}{2}$ °E. 97.5 ft. Mkd: $\frac{1}{4}$ S19 CS BT.
8" White Oak S.4 $\frac{1}{2}$ °E. 91.0 ft. Mkd: $\frac{1}{4}$ S19 CS BT.
No trees near west of line.

Section Corner to Secs. 35 and 36, T26-5W. & Secs. 2 & 1, T27-5W. 114
Found - $\frac{3}{4}$ " I.Rod at approx. corner location. All 3 Orig. BT's. found,
bear. & dist. according to gov't. notes, as follows:
20" B.Oak, now 52", S.83 $\frac{1}{2}$ °W. 109 lks., opened prev., center rotted.
12" Bl.Oak, now 34", N.62°W. 74 lks., shows good scar.
10" B.Oak, now 26", N.7 $\frac{1}{2}$ °W. 157 lks., shows very good scar. #145
Bearings fit very closely, but distances vary from 1.5 ft. to
8 ft. from record distances. Since it is impossible to find any one
point which will fit distances given, I decide to accept rod found as corner.
Set - Brass Cap alongside I.Rod & Mkd: County Surveyor's T26S S35 | S36
Office, 1964 T27S S 2 | S 1 R5W
New BT's: 12" B.Oak N.11°E. 10.3 ft. Mkd: T26S R5W S36 CS BT.
10" B.Oak S.84°E. 21.6 ft. Mkd: T27S R5W S1 CSBT.
9" B.Oak S.56°W. 24.3 ft. Mkd: T27S R5W S2 CS BT.
Old BT. 26" B.Oak N.8°W. 102.1 ft., still in good condition, not rescribed.
Note - Fence Corner, fences N. and E. bears South 19.5 feet.

$\frac{1}{4}$ Corner to Secs. 35, T26-5W. & Sec. 2, T27-5W. 115
Found - Stump of White Oak S.81°W. 321.4 ft. (now 24") Opened & found
good scribing "BT".
48" B.Oak N.48°W. 87.1 ft., faint scar visible. Did not open.
Set - Brass Cap at Cor. Mkd: County Surveyor's $\frac{1}{4}$ R5W T26S S 35 R5W
Office, 1964 T27S S 2
New BT's: Note - Bearings not true for this corner, read with compass
set for variation of 19°30'E.
9" W.Oak S.20°W. 58.0 ft. Mkd: $\frac{1}{4}$ S2 CS BT.
12" W.Oak N.79°W. 85.6 ft. Mkd: $\frac{1}{4}$ S35 CS BT.

S. E. Corner D. L. C. No. 41. 116
Found - 1" Pipe in Fence Corner.
This is a renewal of Corner set by Woodford, 1953, see
notes in C. S. File #41/144.
It is not the same location as S.E. Cor. DLC 41 as set 144
by Stewart, 1922, See Ren. No. 7.
New BT's: 8" White Oak N.57°E. 5.4 ft. Mkd: SE DLC 41 CS BT.
10" W.Oak N.25°W. 69.9 ft. Mkd: SE DLC 41 CS BT.

Meander Corner, left bank, Sections 23 and 26. 117
Found - $\frac{1}{2}$ " Iron Pipe set in Concrete. See Ren. No. 57.
Orig. Bl.Oak, now 24", S.9°E. 26.4 ft. Tree dead & down,
shows good scar, Did not open.
12" Orig.W.Oak, now 31", N.16 $\frac{1}{2}$ °W. 38.2 ft., Still alive & standing.
12" White Oak N.18°E. 30.3 ft., still alive & standing, scribing
still visible. (1958 BT.)
New BT: 17" White Oak S.40°E. 31.5 ft. Mkd: WMC S26 CS BT.

$\frac{1}{4}$ Corner to Sections 34 and 35. 118
Found - Old rotted Oak Stump N.7°W. 246.8 ft., opened & found good scribing.
Rotted Oak Stump N.6°E. 236.9 ft., No marks found.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1964
T26S R5W $\frac{1}{4}$ S34/S35
New BT's: 14" W.Oak N.12°W. 168.0 ft. Mkd: $\frac{1}{4}$ S34 CS BT.
8" W.Oak N.28°E. 171.0 ft. Mkd: $\frac{1}{4}$ S35 CS BT.
Note - Corner lies in open, grassy, nearly level pasture land, approx.
240 feet south of small winter creek.

Milo E. Godfrey, Deputy Co. Surveyor
Wm. Stoffel - Mike Stone - Mike Darby
March and April 1964
C. S. File 49/125