

Douglas County Surveyor's Record of  
Government Corners Renewed

26 T. S. 6 R. W. W. M.

Dec. 10, 1937  
F.C. Frear  
Wit.  
Milton Miller  
N.E. Richardson  
Nov. 13, 1940  
N.E. Richardson  
H.I. Epstein Jr.

N.E. COR. HENRY EVANS D.L.C. NO. 43  
I reset as per old Y. Oak B.T. out down N.  $1^{\circ}$ E., 75.2 ft.  
Marks plain. Drove 1" x 36" I. Pipe from which  
A Maple 36" dia. bears N.  $70\frac{1}{2}^{\circ}$ W., 63.5 ft.  
A Maple 36" dia. bears S.  $82\frac{3}{4}^{\circ}$ W., 76.8 ft.

MEANDER CORNER BETWEEN SEC. 33 and 34  
Set the corner from one old B.T. namely a Y. Oak N.  $47\frac{1}{2}^{\circ}$ E.,  
149 lks. For this corner set an Oak Post 4 x 4 x 48" Marked  
M. C. C.S. 33 and 34 from which  
Triple White Oak 14" dia. marked M.C. C.S. B.T. bears  
N.  $43\frac{1}{2}^{\circ}$ E., 29.0 ft.

$\frac{1}{4}$  SECTION CORNER BETWEEN SECTIONS 7 and 18.  
After a diligent search no traces of this corner were found  
although several line blazes were readily located.  
This corner was relocated by proportional measurements  
between the section corners next east and west. A 2 x 36"  
Iron Pipe was driven for the corner from which  
A B. Oak 14" dia. bears N.  $23^{\circ}$ E., 72.0 ft. marked  
S. 7 T. 26S. R. 6 W. B.T.  
A Cedar 12" dia. bears S.  $66^{\circ}$ W., 54.0 ft. marked  
S. 18 T. 26S. R. 6 W. B.T.

SECTION CORNER ON THE TOWNSHIP LINE BETWEEN SECTIONS 7 AND  
18 OF T. 26 S. R. 6 W. AND SECTIONS 13 AND 12 OF T. 26S. R. 7W.  
I found at this corner a rotten stake at a fence corner and  
an original B.T. in good condition (which I did not chop  
out) now a 16" Black Oak N.  $78\frac{1}{2}^{\circ}$ E., 61 lks. also a Black Oak  
down and rotting but with scribe marks in the stump still  
legible S.  $79^{\circ}$ W., 132 lks.  
From this evidence I set a 4" Oak Post of proper length  
from which  
A 16" Black Oak bears N.  $78^{\circ}30'$ E., 39.4 ft. old B.T.  
A 24" Black Oak bears N.  $23^{\circ}18'$ W., 210. ft. marked  
S. 31 T. 26S. R. 7 W. B.T.  
A 14" Black Oak bears S.  $80^{\circ}30'$ E., 59.0 ft. marked  
S. 18 T. 26S. R. 6 W.  
A 8" Fir bears S.  $40^{\circ}50'$ W., 52.0 ft. marked S. 24  
T. 26S. R. 6 W.

$\frac{1}{4}$  SECTION CORNER BETWEEN 17 and 18 T. 26 S. R. 6 W.  
Found one old B.T. standing and containing scribe marks  
also a stump hole where the other B.T. had been. From this  
evidence I set a sun barrel for the corner from which  
A Black Oak 28" dia. bears S.  $82^{\circ}55'$ E., 42 ft. marked  
S. 17 T. 26S. R. 6 W. B.T.  
A Black Oak 36" dia. bears N.  $69^{\circ}23'$ W., 56 ft. marked  
S. 18 T. 26S. R. 6 W. B.T.  
A 24" B. Oak bearing N  $59\frac{1}{2}^{\circ}$  E 57.4 ft. (New B. T. set Dec. 28, 1946) N. E. Richardson

CORNER COMMON TO SECTIONS 8, 9, 16 and 17  
Found mound of rock with old stake in center. Four  
bearing trees found checked except in two instances. One  
distance 86 lks. instead of 36 lks. other bearing N.  $62^{\circ}$ E.  
instead of S.  $72^{\circ}$ E. Trees had been chopped out and were  
badly rotted. Replaced trees as follows  
A 4" Fir N.  $5^{\circ}46'$ E., 21.9 ft. marked S. 9 T. 26S. R. 6 W. B.T.  
A 8" Black Oak S.  $70^{\circ}15'$ E., 21.4 ft. marked S. 16  
T. 26S. R. 6 W. B.T.  
A 20" Fir S.  $56^{\circ}30'$ W., 49.5 ft. marked S. 17 T. 26S. R. 6 W.  
B.T.  
A 24" Fir N.  $58^{\circ}00'$ W., 75.0 ft. marked S. 8 T. 26S. R. 6 W.  
B.T.

$\frac{1}{4}$  SECTION CORNER BETWEEN SECTIONS 8 and 17  
No trace of original corner found after a diligent search.  
Set new corner midway between the two section corners. This  
corner is a sun barrel driven in the ground from which  
A 8" Fir bears N.  $28^{\circ}$ W., 55.5 ft.  
A 6" Black Oak bears S.  $17^{\circ}6'$ E., 48 ft.

28

29

30

31

32

33

34

C.S. File 37/105

Ben. B. Irvine  
July 1942

RENEWED CORNER NO. 55:93-  
RENEWED CORNER NO. 104  
RENEWED CORNER NO. 131  
RENEWED CORNER NO. 152  
RENEWED CORNER NO. 130  
RENEWED CORNER NO. 133  
RENEWED CORNER NO. 132