

Douglas County Surveyor's Record of  
Government Corners Renewed

26 T. S. 6 R. W. W. M.

35

SECTION CORNER COMMON TO SECTIONS 7, 8, 17, and 18.

No trace of the original corner could be found after a diligent search. Mr. George Winnefred stated that he found one B.T. several years ago but had looked for it later and failed to find it. The area including this corner has been slashed during last winter.

I relocated this corner by proportional measurements from the section corners next east and west from this corner and from the quarter-section corners next North and South of this corner. For the corner I drove an Iron Pipe 2" x 36" in the ground from which

A 18" Fir bears S.41°30'W., 275.4 ft. marked S.18 T.26S  
R.6W. B.T.

A 30" Fir bears S.14°15'E., 211.0 ft. marked S.17 T.26S.  
R.6W. B.T.

and as there were no trees in sight in the north quadrant and as there was a possibility of the above trees being killed when the slash was burned I set an additional tree as follows:

A 15" White Oak S.47°45'E., 611 ft. marked S. 17  
T.26S.R.6W. B.T.

This tree is on the bank of the creek running through the draw.

SW COR. THOMAS SMITH DLC #44. Sec. 25

Reset from on OBT with scribe marks 24" Oak N15°W 15.8 ft.

and B. Oak stump N 5° E 132.0 ft.

Remark OBT 24" B. Oak N 15° W 15.7 ft.

W. Oak N 59½° E 30.9 ft.

Marked SW - DLC #44 CS BT

Set 2"x54" cast pipe, driven 8" underground on river bank, Approximately HW mark.

¼ SEC. COR. 25-36

Set from split rock with X on top, trees gone, *REN #1*  
stumps check for bearing and distant.

7" Oak bears N 25° E 73.4 ft.

8" W. Oak N 8¼° E 102.8 ft.

¼ COR. 3-4

Found 2 O.B.T.'s. in good shape *REN #24*

Set ¾" x 36" iron rod for corner, from which O. B. T.'s.

Oak N 54° W 59.0 ft.

Oak N 22° E (66.0 ft.) approx. 66 lks.

¼ COR. 2-3

Found Y. Oak B.T. N 82° W, rotted but blaze discernible with faint scribed marks. *Sec. O.K. 6-8-64*

Set Auto axle for cor. from which

24" Fir bears N 4° W 10.3 ft., mkd. ¼ S 3 C.S.B.T.

15" Fir bears S 14° E 20.6 ft. mkd. ¼ S 2 C.S.B.T.

¼ COR. 3-10

Found O. B. T. stump badly rotted, faint scribe mark visible on blaze on root, S 70½° E 31 lks.

Set a 1" iron pipe from which

34" Fir bears N 9° E 4.5 ft. mkd. ¼ S 3 C.S.B.T.

No other suitable trees available.

¼ COR. 34-3 ( Sec. 34 T 25 - 6)

Found 36" Fir line tree called for in notes, measured called distance, location fits Laurel tree for direction and distance. Laurel blazed but blaze rotted out.

Set ¾" iron rod from which

12" Fir bears S 88° E 17.9 ft. mkd. ¼ S 3 C.S.B.T.

No suitable tree available in Sec. 34.

JUNE '63 - M.E.G.  
SEARCHED FOR - NOT FOUND  
SEE C. L. 49/23

N. B. Richardson  
Dep. Co. Surv.  
Milo Godfrey  
L. Kershner  
Witnesses  
6/46

Richardson  
Godfrey  
Kershner  
3-10-46

Witnesses

Bob Matthews  
E. A. Jennie

A. R. Evans - Surveyor

C.S. File 37/105

No Ref. Found No Ref. Found

November 1949  
C.S. File 43/167, M 16 - 25

36

37

38

39

40

41

129

112

51

117

119