

Douglas County Surveyor's Record of
Government Corners Renewed

26 T. S. 6 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

81

$\frac{1}{4}$ Corner to Sec. 12, T26-6W. & Sec. 7 T26-5W.
Position identified from one O.B.T., scribe marks nearly
rotted off.
Drove 2" x 36" Iron Pipe and Mkd. the following trees:
14" Fir bears S.42°W. 84 lks. Scribed $\frac{1}{4}$ S12 CS BT.
10" Fir bears N.31 $\frac{1}{2}$ °E. 36 lks. scribed $\frac{1}{4}$ S7 CS BT.

Ben B.
Irving, DCS
March 18,
1929
C.S. 10/3
Page 291
C.S. File 22/40

82

$\frac{1}{4}$ Corner Sec. 30, T26-6W. & Sec. 25, T26-7W.
Set $\frac{1}{2}$ " x 36" Iron Pipe 8" above ground for corner from
Stump of B.T. in Section 30.
Original B.T. good in Section 25, cut B.T. out on stump
and marked new B.T.:
18" Fir bears N.87°E. 17.3 feet.
Old Bearing Tree in Section 25 good.

H. L.
Eppstein
April
12,
1939

TO Witness Corner-

Sec. Cor. to Secs. 12 & 13, T26-6W. & Secs. 7 & 18, T26-5W.
Note - This corner is on new 99 Hwy. pavement. It was
originally a three way fence corner, but has been
used for many years as section corner. Was used
& referenced out by State Hwy. Dept. before grade
was built.

See C. S. File No 49/152 for field notes and sketch of
the way this corner was referenced & what was found.

Set Brass Cap at Wit. Corner for Sec. Cor. Mkd. Brass Cap
Wit. Cor. 120 ft. West to

S12	S7
R6W	S13

 T26S County

Surveyor's Office, 1960

No Trees Near.

James W. Eyrton, Deputy
Milo Godfrey
Clete Putnam
May 5, 1959
C.S. File 49/152

84

$\frac{1}{4}$ Section Corner to Sec. 12, T26-6W. & Sec. 7, T26-5W.
Found - 2" I. Pipe at Corner and Both BT's. as renewed by
B. B. I.: 14", now 16" R. Fir S.42°W. 55.4 ft., shows
good scar. I do not open. REN #81
10", now 12" Stump Fir shows good scribing N.31 $\frac{1}{2}$ °E,
record 23.8 ft. I find to be 47.0 ft.
New BT: 5" R. Fir bears N.32°E. 29.0 ft. scribed $\frac{1}{4}$ S 7 CS BT.

Sec. Cor. to Secs. 32-33, T26-6W. & Secs. 5 - 4, T27-6W.

Found - Orig. 18", now 50" Maple N. 9°W. 46.2 ft., center
burned out, now shell only, no scribing.

All other BT's. gone.

2" x 8" x 18" Stone 6" under surface & under N-S

Fence. Stone set on end.

Set - Brass Cap at Corner and alongside corner stone Mkd:

County Surveyor's

S32	S33
S 5	S 4

 T26S R6W

Office, 1961

New BT's: 36" Maple bears N.14 $\frac{1}{2}$ °W. 51.1 ft. scribed S32 T26S R6W CS BT.

10" Myrtle bears N.51°W. 113.7 ft. scribed S32 T26S R6W CS BT.

No other trees near.

James W. Eyrton, Deputy County Surveyor
Milo Godfrey
Clete Putnam
February 1961

85

Sec. Cor. to Secs. 34 - 35, T26-6W. & Secs. 3 - 2, T27-6W.

Found - All Orig. BT's. Orig. 6", now 18" W.O. S.57 $\frac{1}{2}$ °W. 44.2 ft.,
center rotted.

Orig. 6", now 24" B.O. N.86°W. 28.4 ft., shows scar.

Orig. 10", now 34" B.O. N.10°E. 79.2 ft. We open & find

good scribing "W".

Orig. 8", now 24" B.O. S.73°E. 89.8 ft., shows scar.

Set - Brass Cap at Corner Mkd: County Surveyor's

S34	S35
S 3	S 2

 T26S

Office, 1961

New BT's: 24" B.O. N.86°W. 28.4 ft. (O.B.T.) scribed S34 T26S R6W CS BT.

12" W.O. N.20°E. 84.0 ft. scribed S35 T26S R6W CS BT.

9" B.O. S.15°E. 53.0 ft. scribed S 2 T27S R6W CS BT.

9" W.O. S.29°W. 14.7 ft. scribed S 3 T27S R6W CS BT.

C. S. File No. 49/79

86