

Douglas County Surveyor's Record of
Government Corners Renewed

T 26 T. S. R 6 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 91881

192

CONT - - -

Doug. Co. Surveyor
R. Smith - S. Flauser
Jan. 5, 1990
C.S. 64/5

New Accessories (cont.)

5/8" iron rod with alum. cap (CRRW 10+00.00 PT on south side of Cleveland Loop Dr.) bears N.19½°E., 197.40 ft.

5/8" iron rod with alum. cap (CRRW 10+46.76 PC on south side of Cleveland Lp Dr.) bears N.32 3/4°E., 202.36 ft.

Corner lies 1½ ft. north of the intersection of a North-South and East running fence line.

1/5/90

Section Corner for Sections 5 and 6 and
Section Corner for Sections 31 and 32 T. 25-6

193

Found - A 2½" dia. 1979 DCSO brass cap on a 1¼" O.D. I.P. protrudes 6" out of ground, now bent approx. 12" north of plumb.
Ren. #179

5/8" dia. iron rd, protrudes 9" out of ground, now bent approx. 15" north of plumb. (source unknown)

9"x9"x17" stone no marks visible found approx. 2.0 ft. north of DCSO BC/IP's plumb position (possibly from Ren. #79)

Above 5/8" iron rod found along north side of DCSO BC/IP.

(Bearings and distances taken to plumb position of DCSO BC/IP:

10" now 14" B. Oak with a fully healed double blaze bears N.8½°E., 59.9 ft. (Rec. N.7°E., 61.3 ft. slope dist.) from Ren. No. 79)

6" now 14" madrone with fully healed blazes bears N.36°W., 38.8 ft. (agrees w/rec. in Ren. No. 79) From Ren. #79

12" now 14" madrone with partially healed double blaze scribing visible "T26S R6W" bears S.31°E., 50.4 ft. Ren. #179

11" now 14" oak with fully healed double blaze bears S.34½°W., 158.5 ft. (Rec. S.33°W., 158.5 ft.) Ren. No. 179.

Set - Position of bent DCSO BC/IP is referenced. DCSO BC/IP is straightened and returned to referenced position. BC/IP now protrudes 3" above ground. 5/8" I.R. is straightened and set along North side of DCSO BC/IP. 5/8" I.R. now protrudes 1" above ground. Stone is placed along East side of DCSO BC/IP. BC/IP measures 36". 5/8" Iron rod measures 50" long.

Corner lies on a NW-SE running ridge on a bench approx. 50 ft. North of a dirt road.

1/31/90

194

Section Corner for Secs. 32 and 33; and Secs. 5 & 4 of T.27-6

Found - A 3" x 8" x 24" stone set on end, top approx. 6" below ground. (Rec. 2" x 8" x 18" in Ren. #85). Top 9" is broken off and fractured into 3 pieces. (Probably broken when field was plowed) No marks found on stone. Stone set in Ren. #18 of T27-6
A 2½" dia. DCSO brass cap on a 1¼" O.D. x 36" long split end iron pipe is found laying on top of ground approx. 4 ft. south of found stone. Top of BC/IP shows evidence of being hit by a plow. Ren. #85

(Brg. & dist. taken from top center of stone)

A bent metal fence post is found along east edge of stone. (Source unknown.)

10" now 20" dia. myrtle with healed scars, we open in 3 places, no blazes or scribing found, bears N.54¼°W., 113.7 (Rec. N.51°W., 113.7 ft.) Possible northwest BT from Ren. #85.

No other original or Renewal BTs found.

Set - A 5/8" x 30" long iron rod is set 2½ ft. below ground at referenced position of found stone. Stone is reset on end on top of 5/8" I.R. at referenced out position. DCSO BC/IP is reset 0.2 ft. west of stone, along west edge of stone. The marks "RESET 1990" are added to brass cap. Stone is set 4" below ground, DCSO BC/IP protrudes 2" above ground.

New BTs (Brg. & Dist. taken from top center of stone)

12" Cottonwood double blazed and scribed "T27S R6W S4 CS BT" bears S.7½°E., 276.1 ft.

28" Myrtle double blazed and scribed "T27S R6W S5 CS BT" bears S.84½°W., 301.8 ft

18" Cottonwood double blazed and scribed "T26S R6W S32 CS BT" bears N.20°W., 134.0 ft.

2/21/90

Douglas County
Surveyors Office
Randall Smith
Stephen Flauser
Jan. 31, 1990
C.S. 64/5

Douglas County
Surveyors Office
Randall Smith
Stephen Flauser
Feb. 21, 1990
C.S. 64/5