

Douglas County Surveyor's Record of
Government Corners Renewed

26 T. S. 7 R. W. W. M.

Ben B. Irving - Surveyor
A. R. Evans - Witness
R. L. Matthews "

3/28/50
C.S. 49-38

Sec. COR. 11-12-13-14

Sec. cor. identified from O. B. T. *SEE ALSO REN. 1*
24" B. O. bears S 20° W 25 lks., old blazes rotted out.
19" B. O. bears S 20° E 71 lks. down, B.T. legible **53**
B. O. bears N 50° E, down and rotten
B. O. bears N 70° W 26 lks, small part of stump left.
Intersection fences South and West, old fence corner post down.
Set $\frac{1}{4}$ " x 36" iron rod for corner from which
10" Cedar bears S 81° E 81.2 ft., with a brass disc marked C.S.
7" Cedar bears N 67 $\frac{1}{2}$ ° E 84.7 ft.
10" Fir bears N 74° W 74.9 ft.
30" Fir bears S 31 $\frac{1}{2}$ ° W 16.2 ft with a brass disc mkd.
County Surveyors Office, XI, XII, XIII, XIV.

21

~~1/4 COR. 2-11~~

~~Set post by bearing tree
3 rocks 8 x 14 x 8~~

~~SEARCHED FOR - NOT FOUND
MARCH 1966 C.S. 54/23 Tracy-LH~~

~~22~~

~~SEC. COR. 2-3-10-11~~

~~Set rock 22 x 10 x 8 by bearing tree~~

~~IN RESEARCH (VOL. 1 P 70-71)
8/19/92 JP T. 28-5
SEE COR. REPORT
"LOOKED FOR, NOT FD"
IN C.S. 64/5~~

~~23~~

~~1/4 COR. 3-10~~

~~Set rock 18 x 12 x 6 and rock 14 x 12 x 6 by BT.~~

~~24~~

1/4 SEC. COR. BET. SECS. 25 & 26

Found old witness tree stump S 6° W 67 lks. (See affidavit Dr. 44, file 7)
At corner point set $\frac{1}{2}$ " x 36" iron pipe
12 in. W. Fir bears N 32 $\frac{3}{4}$ ° E 73.5 ft.

25

SEE CORNER NO. 33

H. Crowder
Transitman
Co. Engineer's Office Jan. 8, 1886
May 22, 1951
C.S. 47/47

June 2, 1938
V. 15, E. 11

Section corner between 35 & 36, T26S, R7W., and 1 & 2, T27S, R7W.
Renewed corner to sections from the 18" Black Oak S. 37° W., 65 lks.
in Section 2. Other trees gone. Set $\frac{1}{2}$ " Iron Pipe for corner.
Marked New B. T.
White Fir 12" dia. bears S. 40° W., 81 ft.
No trees in other sections near.
Set 1" pipe N. 50° W., 21.8 ft. in section 35.
Set 1" pipe N. 58° E., 26.8 ft. in section 36.
Set 1" pipe S. 51° E., 29.0 ft. in section 1.

26

SEE CORNER NO. 74

Edwin S. Woodford
Wit: Marr
Linehart
August, 1946
C. S. File 42/119

Section corner to secs. 3 and 4, T 26 S., R 7 W., and secs. 33 and 34,
T 25 S., R 7 W.
Found 1 old B. T.:
24 inch Oak, S. 75° E., 43 lks. - (tree now 36 inches). Found reverse of
scribe marks in cut out slab.
Set a 1 inch x 30 inch steel shaft set for corner.
Marked new tree:
15 inch Fir, S. 30 $\frac{1}{2}$ ° E., 7.7 feet.

27

SEE CORNER NO. 75

James W. Byron, Deputy Co.
Surveyor
May 13, 1957.
C. S. File No. 47/191.

Section corner to secs. 7, 8, 17 & 18.
Found original N.E. BT which shows good but faint scribe marks. Same for
orig. N.W. BT - Check for bearings. The N.W. BT measures 27.5 (record
40.3 feet) (steep slope to BT). Also found base of rotted stump of orig. BT,
S. 80° E., 64.7 feet & found old stump hole for S.W. BT. Orig. N.E. & N.W.
BTs no 40 inch Fir.
Set an iron pipe with brass cap at corner mkd. Sec. corner $\frac{7}{8}$ T26S R7W,
18/17
County Surveyors Office, 1957.
Blazed and scribed:
5 inch Hemlock, S. 72° E., 34.6 feet mkd. S 17, CS BT.
6 inch W. Fir, N. 68° W., 29.3 feet mkd. S 7, T26S R7W CS BT.
8 inch Fir, S. 84° W., 36.5 feet mkd. S 18, T26S, R7W CS BT.
Rebark & scribed orig. N.E. BT, S 8 T26S R7W CS BT. (N. 85° E., 15.2 feet).

28

RENEWED, SEE CORNER NO. #110