

Douglas County Surveyor's Record of  
Government Corners Renewed

26 T. S. 7 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

51

$\frac{1}{4}$  Sec. Corner to Sec. 32, T26-7W. & Sec. 5, T27 - 7W.  
Found - Orig. 30", now 36" R.Fir Stump S.58°E. 8.6 ft. We  
open & find good scribing "BT".

No trace of N. W. BT. found.

Set - Brass Cap at Corner Mkd: County Surveyor's  $\frac{1}{4}$  S32 T26S  
Office, 1961 S 5 T27S

New BT: 12" R.Fir bears N.66°W. 134.0 ft. scribed  $\frac{1}{4}$  S32 CS BT.  
No trees near to South.

James W. Byron, Deputy  
Milo Godfrey  
Clete Putnam  
February 1961 R7W  
C.S. File No. 49/79

52

Sec. Cor. to Secs. 31-32, T26-7W. & Secs. 5-6, T27-7W.  
Found - Orig. 18", now 42" Fir Stump S.75°W. 42.9 ft., shows good  
scribing "BT".

Orig. 24", now 48" Fir Stump, checks bearing & distance for  
N.W. BT.

Orig. S. E. BT. would be in existing Roadway.

Orig. 10", now 28" Fir checks bearing & distance for N.E. BT.

Set - Brass Cap at Corner Mkd: County Surveyor's S31 | S32 T26S  
Office, 1961 S 6 | S 5 T27S

Note -  $\frac{3}{4}$ " Pipe bears S.43°W. 2.5 ft.

New BT's: 21" R.Fir bears N.43 $\frac{1}{2}$ °E. 41.5 ft. scribed S32 T26S R7W CS BT.

24" R.Fir bears S. 9°E. 65.3 ft. scribed S 5 T27S R7W CS BT.

53

Section Corner to Sections 11 - 12 - 13 - 14.

Found -  $\frac{3}{4}$ " Iron Rod at Corner. *REN. 21*

34" Fir S.31 $\frac{1}{2}$ °W. 16.2 ft. Blaze healed over, tree alive.

16" I. Cedar S.81°E. 81.2 ft., scribing visible in partially  
covered scar. Tree alive & in good condition.

12" I. Cedar N.61 $\frac{1}{2}$ °E. 84.7 ft., scribing visible in partly  
covered scar. Tree alive & in good condition.

Fir Stump N.74°W. 74.9 ft. No scar on stump

Set - Brass Cap alongside I. Rod At Cor. Mkd: Co. Surveyor's T26S S11 | S12  
Office, 1962 R7W S14 | S13

New BT's: 8" Madrone N.28°W. 12.0 ft. Mkd: T26S R7W S11 CS BT.

New Fence Corner, fences West & North bears East 11.0 feet.

54

Section Corner to Sections 9 - 10 - 15 - 16.

Found -  $\frac{3}{4}$ " I. Pipe set by Stewart in 1922. *REN. 12*

34" Fir Stump N.71°E. 91.8 ft., shows good scar.

28" Fir Stump North 21.7 ft. Bark scribing visible "BT".

42" Fir S.20°E. 27.9 ft. (to face) bark scribing visible,  
Tree alive & in good condition.

26" Fir S.88°W. 24.0 ft. (to center) Bark scribing visible.

Blaze & Rescribe this Tree "T26S R7W S16 CS BT".

DID NOT SET BRASS CAP.

New BT's: 24" D.Fir N.60°E. 47.0 ft. Mkd: T26S R7W S10 CS BT.

6" W.Fir N.45°W. 7.1 ft. Mkd: S9 CS BT.

Corner lies on rocky bench at foot of steep north slope.

SEE COV'T  
NOTES  
Vol. 33, P. 13664

Milo E. Godfrey, Deputy  
Vern Tracy and Mike Stone  
Dec. 1962 and Jan. 1963  
C. S. File No. 49/129

55

$\frac{1}{4}$  Corner to Sec. 31, T26-7W. & Sec. 36, T26-8W.

Found - 32" D.Fir Snag showing good scar & overgrowth where it had  
previously been opened. Hathorne in 1855 called for a  
10" Hemlock. We chopped Fir open & found good scribe &  
reverse scribe of partial " $\frac{1}{4}$ " at about the point this tree  
would have been 10". Also, a ring count showed it to be 95  
to 105 years, accurate count impossible. This Fir BT. faces  
the proper direction as called for in Orig. notes.

$\frac{1}{2}$ " Alum. Pipe at Corner. Set Brass Cap alongside.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963  
T26S R8W  $\frac{1}{4}$  S36/S31 R7W

New BT: 26" D.Fir bears N.32°E. 32.6 ft. Mkd:  $\frac{1}{4}$  S31 CS BT.  
No other trees available.

April 1, 1963

#94