

**Douglas County Surveyor's Record of  
Government Corners Renewed**

T. 26 S. T. S. R. 7 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

72

$\frac{1}{4}$  Corner to Sections 2 and 1.  
Found - Orig. 16", now 36" S. 70° W. 74.6 ft. Chop open & find "4S"  
scribe & reverse. Ring count 100+ years.  
Stump hole at approximate location of S. E. BT.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1966  
T26S R7W  $\frac{1}{4}$  S 2 / S 1.  
New BT's: 18" D. Fir N. 61° E. 6.7 ft. Mkd:  $\frac{1}{4}$  S1 CS BT.  
16" B.Oak N. 23° W. 7.1 ft. Mkd:  $\frac{1}{4}$  S2 CS BT.  
Note - Corner lies 10 ft. East of old road not used for number of years.

73

$\frac{1}{4}$  Corner to Sections 12 and 13.  
Found - Orig. 8", now 15" B.Oak S. 31° E. 25.7 ft., down & dead,  
Open & find "4 S BT", reverse scribe & reverse axe notch.  
Orig. N. W. BT. apparently taken out by slide.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1966  
T26S  $\frac{1}{4}$ 

S	12
S	13

 R7W  
New BT's: 24" D. Fir N. 17° W. 40.6 ft. Mkd:  $\frac{1}{4}$  S12 CS BT.  
10" D. Fir S. 21° W. 53.5 ft. Mkd:  $\frac{1}{4}$  S13 CS BT.  
Note - This corner lies on east slope approximately 200 ft. west  
of small creek, course S. E.

74

Wit. Cor. Sec. Cor. to Secs. 35 & 36, T26-7W. & Secs. 2 & 1, T27-7W.  
Found - Iron Pipes as used, See Ren. #26,  
12", now 24" D. Fir S. 40° W. 81.0 ft., recorded as W. Fir,  
we chop out "BT".  
1" I. P. N. 58° E. 26.8 ft. - 1" I.P. S. 51° E. 29.0 ft. **#88**  
Do Not find I.P. set for corner nor I. P. Refernced N. W.  
Corner falls in Road.  
Set - Wit. Cor. 23.0 ft. East of true corner.  
Brass Cap Mkd: County Surveyor's Office, 1966  
Wit. Cor. 

T26S	S 35	S 36
R7W	S 2	S 1

  
New BT's: 8" Cedar N. 42° W. 56.0 ft. Mkd: W. C. T26S R7W S35 CS BT.  
9" Cedar S. 65° W. 48.2 ft. Mkd: W. C. T27S R7W S2 CS BT.  
No trees close to East - Use old reference I.P.'s., as follows:  
1" I. Pipe N. 1° W. 13.8 ft.  
1" I. Pipe S. 2° W. 18.6 ft.  
Witness Corner lies on East edge of road, course N. & S. in old fence.

Vernon "Ray" Tracy  
Mike Stone & Jack Heritage  
March and April 1966  
C. S. File No. 54/23

75

Sec. Cor. to Secs. 3 & 4, T26-7W. & Secs. 33 & 34, T25-7W.  
Found - 1" x30" Steel Shaft set by Woodford, See Ren. #27.  
15", now 24" D. Fir S. 30 $\frac{1}{2}$ ° W. 7.7 ft. (not S. 30° W. **#120**)  
24", now 38" Orig. B. Oak S. 75° E. 24.8 ft.  
Set - Brass Cap alongside Shaft Mkd: County Surveyor's Office, 1966  

T26S	R7W	S 33	S 34
T26S	R7W	S 4	S 3

  
New BT's: 16" D. Fir N. 36° E. 71.4 ft. Mkd: T25SR7W S34 CS BT.  
18" B. Oak N. 18° W. 31.0 ft. Mkd: S 33 CS BT.  
Note - Corner is N. 30° E. 9 ft. from a N - S - W Fence Corner  
on a moderate north slope about 80 ft. south of a creek.

Michael S. Stone  
Jack Heritage  
April 13, 1966  
C. S. File No. 54/10

**RE-RENEWED, SEE CORNER NO. #120**

76

Section Corner to Sections 5 - 6 - 7 - 8.  
Found - Orig. 16", now 25" Fir S. 85° E. 11.9 ft. (face). Open &  
find "S8" scribe.  
Orig. 24", now 36" Fir Stump S. 80° W. 9.2 ft. (face. No scribe fd.  
Orig. N. E. BT. is shattered stump out of place.  
N. W. BT is snag showing faint scar.  
18" D. Fir S. 65° E. 35.4 ft. Mkd: T26 R7S8 BT RE2741 (unrecorded)  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1966  

T26S	S 6	S 5
T26S	S 7	S 8

 R7W  
New BT's: 11" Chinquapin N. 64° W. 54.7 ft. Mkd: T26S R7W S6 CS BT.  
5" D. Fir N. 14° E. 34.2 ft. Mkd: S 5 CS BT.  
4" D. Fir S. 27° W. 11.6 ft. Mkd: S 7 CS BT.  
Note - This corner lies in very brushy, old, logged-off unit.

Vernon "Ray" Tracy  
Mike Stone & Jack Heritage  
May 31, 1966 - C. S. 54/23

FD. OK 12/63  
E. G. GARDNER  
M 90-51