

Douglas County Surveyor's Record of
Government Corners Renewed

Twp. 26 S. T. S. Rge. 8 W. R. W. W. M.

NOTE-CHAPMAN CO., EUGENE, ORE. 97196

1

Surveyor:
A. Boyer
May 1952
C.S.#1128

SECTION 20 N 1/4 CORNER:

6 x 6 Sq. Fir Post 3' above ground, scribed S20, S17 1/4
15" Chinquapin N. 40 degrees West, 48.0 Ft.
15" Red Fir S. 63 degrees West, 8.3 Ft.
22" Red Fir N. 53 degrees 30' East, 4.0 Ft.

2

Section corner to sections 22, 23, 26 and 27.

Found:

48 inch Fir snag, S.61°W., 155 lks. dist., old scribe marks good-
This tree supposedly was destroyed by fire prior to 1898
retracement.

Rotten Fir snag S.5 1/2°E., 170 lks. - no scribe marks - too rotten.
Stump hole, N.35°W., 135 lks. dist.

House sets on position of N. E. tree - 14 inch, N.62°E., 260 lks.
dist. - John Henry states that at time he built house, he
destroyed tree.

At corner point set steel car jack with 1 inch shaft exposed 6 inches
above ground,
from which:

O. B. T. - 48 inch Fir snag bears S.61°W., 155 lks. dist.

New B. Ts:

15 inch D. Fir bears N.41°30'E., 11.20 feet dist. scribed T 26 S.,
R 8 W., S 23 B. T. R E 3561.

17 inch D. Fir, bears S.61°00'E., 15.70 feet dist., scribed T 26 S.,
R 8 W., S 26 BT. R. E. 3561.

17 inch D. Fir bears S.64°15'W., 29.80 feet dist., scribed T 26 S.,
R 8 W., S 27 BT. R. E. 3561.

16 inch D. Fir bears N.40°15'W., 14.80 feet dist., scribed T 26 S.
R 8 W., S 22 BT. R. E. 3561.

FO. OK
Michael McDowell
Weyerhaeuser
1185
1199-18

3

Richard Grant
D. Powell - W. Oilar
J. Chapman
Martin Bros. Box
Jan. 3, 1958
C.S. File No. 42/328

Section Corner to Sections 13 & 24, T26S R8W, Secs. 18 & 19 T26S R7W.

Set 1" x 30" Iron Pipe with Brass Cap marked 13|18
T26S R8W 24|19 T26S R7W

from testimony of Jack Chapman, Wayland Oilar & R.C. Grant, who
had viewed original location of corner and witness trees prior
to corner being destroyed by a small slide on the Hubbard Creek
Road.

No new trees available as area was burned & logged.

4

Section Corner to Secs. 27, 28, 33 and 34.

At the Corner Point, Set an Iron Pipe, 3 ft. long 2" diam, #69
28" in the ground, mkd. RS404; from which the orig. BT's:

30" Fir Snag bears N.42°E. 57 lks., partial scribe marks.

36" Fir Snag bears S.63°E. 60 lks., partial scribe marks.

40" Fir Snag bears S.14°E. 134 lks., marks burned out.

16" Fir Snag bears N.31°W. 58 lks., marks burned out.

New BT's: 14" Fir bears N.12°E. 44 lks. mkd. T26S R8W S27 RS404 BT.

16" Fir bears S.69 1/2°E. 47 lks. mkd. T26S R8W S34 RS404 BT.

12" Fir bears S.66 1/2°W. 9 1/2 lks. mkd. T26S R8W S33 RS404 BT.

18" Fir bears N.10 1/2°W. 63 lks. mkd. T26S R8W S28 RS404 BT.

RE-REMOVED, SEE CORNER NO. #69

Marvin C. Ramsey
Work done for J. H. Baxter & Co.
August 28, 1959
C. S. File No. 51/41

1/2 Section Corner to Sections 27 and 28.

Set an Iron Pipe 3 ft. long, 1 1/2" diam, 28" in the ground mkd.
RS404, from which the orig. BT's:

Fir Snag 38" bears N.64°E. 47 lks. mkd. BT.

40" Fir Snag bears N.37°W. 50 lks. with scar, mrks burned out.

New BT's: 18" Fir bears N.49°E. 6 1/2 lks. mkd. 1/2 S27 RS404 BT.

20" Fir bears S.13 1/2°W. 18 lks. mkd. 1/2 S28 RS404 BT.

FO. OK
8/185 Michael
McDowell
Weyerhaeuser
1199-18

6

Section Corner to Sections 27, 28, 21 and 22.

determined from the only extant bearing tree that can
be identified, the other bearing trees are badly burned:

Set an Iron Pipe 3' long, 2" diam, 28" in the ground, mkd. RS404
from which the only extant original BT.:

32" Fir Snag bears N.43°E. 36 lks., with partial scribe mks.

FO. OK
8/185
Michael
McDowell
Weyerhaeuser
1199-18

(continued over)