

Douglas County Surveyor's Record of
Government Corners Renewed

26 T. S. 8 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97190

(continued)

FD. OK
8185 Michael
McDowell:
Weyerhaeuser
M 99-18

New BT's: 8" Chinquapin bears N.8 3/4°E. 31 lks. mkd.
T26S R8W S22 RS404 BT.
16" Fir bears S.55 1/2°E. 46 lks. mkd. T26S R8W S27 RS404 BT.
22" Fir bears S.15°W. 70 lks. mkd. T26S R8W S28 RS 404 BT.
9" Chinp. " N.61 3/4°W. 43 lks. mkd. T26S R8W S21 RS404 BT.

C. S.
File
No.
51/41

South 1/4 Corner of Section 30, N. 1/4 Cor. 31.
Found - Lower scribed blaze on Stump of Wit. Tree in Sec. 30.
Rotted Stump of Tree in Section 31, both Orig. Trees and
from them, located corner driving a 1" x 30" Steel Shaft here.
Marked two Wit. Trees: 18" Fir, N.44°W. 25.0 ft. scribed 1/4 S30, 1581 B.T.
8" Fir S.31°W. 16.3 ft. scribed 1/4 S31, 1581 B.T.
(Measurements to center Trees)

Sec. Cor. Secs. 30 & 31, T26S R8W & Secs. 25 & 36, T26S R9W.
Ran a Line West, on a 20° decl. from S. 1/4 cor. Sec. 30, a dist of
2640 ft. Then from the found 1/4 Sec. Cor. between Secs.31,
T26/R8W and Sec. 36 T26/R9W ran 2640 ft. N., on 20° decl.
to a point. Then searched for the sec. cor. for S. 30, 31,
25 and 36 and found a Fir Snag in 36 on the bark of which
was distinct signs of the blazes for the wit. tree, but the
inside of the bark marking was rotten wood where the scribe
would have been. Also found the snag of the wit. tree in
Sec. 31 which showed signs of having been axed out for
the markings. Fire destroyed most of the trees here. When
the corner was set from these two tree, the bearings &
distances matching, the corner fell S.45°E. 18 ft. from a
point measured N. 2640 ft. from the 1/2 cor. bet. 31 & 36,
using a 20° decl., and 2.9 ft. N. of a point which is W. 2659'
from the S. 1/4 Cor. of 30, using 20° decl;
Drove a 4" x 4" Fir Post for the corner & blazed & scribed an:
18" Fir N.77°E. 4.0 ft. Mkd. S30 T26S R8W 1581 B.T.
12" Fir S.30°E. 20 ft. mkd. S31 T26S R8W 1581 B.T.
24" Fir S.37°W. 26.6 ft. mkd. S36 T26S R9W 1581 B.T.
24" Fir N.64°W. 7.9 ft. mkd. S25 T26S R9W 1581 B.T.
(all measurements to the center of trees.)

Arthur Boyer
Witnesses: Harvey Epstein, Donald Wood
Glenn Wood
October 8, 1959
C. S. File No. 51/50

This corner is on the East slope of a N. & S. ridge, 50 ft. South
of top of ridge, about 100 ft. West of small creek. A
vertical rock bluff is about 100 fto to 150 ft. East
running E. & W. with sec. line.

Section Corner to Secs. 27, 28, 33 and 34. See cor. = 4
Monumented with an Iron Pipe 2" in diam., 8" above ground,
mkd. RS404, from which:
D. Fir 14", bears N.12°E., 44 lks. dist., mkd. T26S R8W
S27 RS404 BT.
D. Fir 16", bears S.69 1/2°E. 47 lks. mkd. T26S R8W S34 RS404 BT.
D. Fir 12", bears S.66 1/2°W. 9 1/2 lks. dist., mkd. T26S R8W S33
RS404 BT.
B. Fir 18", bears N.10 1/2°W. 63 lks. mkd. T26S R8W S28 RS404 BT.
The geographis position of this sec. cor. is lat. 43°16'33"N. &
long. 123°38'22"W., The observed mag. decl. is 20°33'E.

Marvin C. Ramsey
For J. H. Baxter & Co.
June 1960
C. S. File No. 51/105

1/4 Section Corner of Sections 28 and 33, det. from O.B.T's:
D. Fir 60", bears N. 8°E. 185 lks. with mks. obltd. by fire.
D. Fir Snag 48" bears S. 8°E. 149 lks. mkd. 1/4 S BT.
Set an Iron Pipe 3 ft. long 1 1/2" diam. 28" in the ground,
mkd. RS404, from which:
D. Fir 26" bears N.58 1/2°E. 16 lks. mkd. 1/4 S28 RS404 BT.
D. Fir 16" bears S.58 1/2°W. 43 lks. mkd. 1/4 S33 RS404 BT.

51/41