

Douglas County Surveyor's Record of  
Government Corners Renewed

26 T. S. 8 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21951

18

Section Corner to Sections 23, 24, 25 and 26.

Determined from the only two extant original BT's.:

Dead Fir, dead snag 38" bears N.14°W., 31 lks.

D. with partial scribe marks:

Cedar 20 ins. bears S.73°W., 108 lks., healed.

Set an iron pipe 3' long 2" in diam., 28" in the ground mkd.

RS 404, from which new BT's:

14" D. Fir bears N.68°E. 14 lks. mkd. T26S R8W S24 RS404 BT.

12" D. Fir bears S.40°E. 27 lks. mkd. T26S R8W S25 RS404 BT.

10" D. Fir bears N.49°W. 26 lks. mkd. T26S R8W S23 RS404 BT.

19

~~1/4 Section corner to Sections 26 and 27. - See CORNER # 23~~

~~determined from the original bearing trees:~~

~~D. Fir, dead snag 50" bears N.60°E. 210 lks. with partial scribe mks. in the top blaze, the bottom blaze has been remarked BT.~~

~~D. Fir 50" bears N.50°W. 295 lks., down & decayed.~~

~~Set an Iron Pipe 3' long 1 1/2" diam., 28" in the ground, Mkd.~~

~~RS404, from which new BT's:~~

~~16" D. Fir bears S.76 1/2°E., 11 lks. mkd. 1/4 S26 RS404 BT~~

~~24" D. Fir bears N.42 1/2°W. 64 lks. mkd. 1/4 S27 RS404 BT.~~

DESTROYED  
CORRECTIVE SURVEY - MAY 1961  
CO. SURVEYOR'S  
BRASS  
CAP SET

20

Center of Section 26.

Intersection with the North & South center line.

Set an iron pipe 3' long 1 1/2" diam., 28" in the ground, Mkd.

RS404, from which:

18" D. Fir bears N.47°E. 62 lks. mkd. C 1/4 S26 RS404 BT.

22" D. Fir bears S.47°E. 25 lks. mkd. C 1/4 S26 RS404 BT.

14" Hemlock " S.24°W. 48 lks. mkd. C 1/4 S26 RS404 BT.

34" D. Fir bears N.60°W. 10 lks. mkd. C 1/4 S26 RS404 BT.

21

1/4 Section Corner of Sections 25 and 26.

determined from the only extant original bearing tree:

14" D. Fir Snag 6 ft. tall bears N.20°W. 34 lks. mkd. BT.

Set an Iron Pipe 3' long 1 1/2" in diam., 28" in the ground, mkd.

RS404, from which new bearing trees:

10" Cedar bears S. 8°E. 58 lks. dist., mkd. 1/4 S25 RS404 BT.

14" Hemlock " N. 6°W. 63 lks. dist., mkd. 1/4 S26 RS404 BT.

FO. OK  
1/18/11  
B. HACT  
M 87-55

22

1/4 Section corner of Sections 26 and 35.

which is monumented with a yew wood post with partial scribe marks in a mound of stone. The original BT's have been destroyed by fire.

Set in place of the yew wood post an iron pipe 3' long, 1 1/2" diam.

28" in the ground, mkd. RS404 from which new BT's:

20" D. Fir bears S.58°W. 13 lks. mkd. 1/4 S35 RS404 BT.

22" D. Fir bears N. 1°W. 64 lks. mkd. 1/4 S26 RS404 BT.

Fd. 3/90  
C.S. 63/127

23

1/4 Section Corner to Sections 26 and 27.

Found - Orig. 48", now 60" Fir Snag N.2 1/2°E. 144.5 ft., shows good scribing on old face. "1/4 S".

Now 60" Fir that checks close for Orig. N.W. BT., recorded by Hayden 1896.

Set - Brass Cap at Corner Mkd: 1/4 S26/S27 T26S R8W County Surveyor's Office, 1961

New BT's: 14" R. Fir bears S.71°E. 6.8 ft. scribed 1/4 S26 CS BT.

10" R. Fir bears N.44 1/2°W. 14.0 ft. scribed 1/4 S27 CS BT.

NOTE - See explanation in file for reason for setting corner in different position than the one set by Ramsey, 1960, Corner No. 19.

Marvin C. Ramsey  
For J. H. Baxter & Co., Roseburg, Oregon  
Wit: J. D. Kirklin & James Goodin  
July 6 - 29, 1960  
C. S. File No. 52/116

James W. Byron, Deputy  
Milo Godfrey  
Clete Putnam  
April 20, 1961  
C. S. File No. 52/79

Fd. OK  
8/95 By M. McDowell  
Weyerhaeuser Co.  
M. 59-18