

Douglas County Surveyor's Record of
Government Corners Renewed

T 26 T. S. R 8 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

63

1/4 Corner for Sections 33 and 34.

Set - Brass cap mkd. T26S, R8W, WM 1/4 S33, S34 1974 from which:
16" Douglas fir, I scribed "1/4S BT", bears N.56 W., 11.6 ft.
16" Douglas fir, I scribed "1/4S BT", bears N.28 E., 4.7 ft.

No original evidence found.

6/24/74

*Fd. 7/90
C.S. 63/127*

64

1/4 Corner for Sec. 33 and Section 4, T27-8.

Set - Brass cap mkd. T26S, R8W, WM 1/4 S33; T27S, R8W, WM 1/4 S4 1974
from which a:
24" Douglas fir, I scribed "1/4S BT" bears N.13 W., 22.0 ft.
24" Douglas fir, I scribed "1/4S BT", bears S.35 W., 26.9 ft.

No original evidence found.

6/24/74

65

Section corner for Secs. 33 and 34 and Secs. 3 and 4, T27-8.

Set - PK nail on the face of a 15 ft. high rock cliff from which a:
Brass cap, I mkd. Witness corner, South 3 ft. to T26S, R8W
S33, S34; T27S, R8W S4 S3 1974, bears North, 3.0 ft.
14" Cedar, I scribed "T26S, R8W S34 BT", bears N.13 E., 17.9 ft.
30" Douglas fir, I scribed "T26S R8W S33 BT", bears N.50 W.,
108.0 ft.
18" Douglas fir, I scribed "T27S R8W S3 BT", bears S.8 E., 26.0 ft.
16" Douglas fir, I scribed "T27S, R8W S4 BT", bears S.18 W., 33.2 ft.

No original evidence found. Panther Creek lies 20 ft. North. Area has
been badly burned and corner area may have been badly eroded by Panther
Creek.

6/24/74

66

1/4 Corner for Sec. 34 and Section 3, T27-8.

Set - Brass cap mkd. T26S, R8W, WM 1/4 S34, T27S, R8W WM 1/4 S3 1974.
from which a:
26" Douglas fir, I scribed "1/4S BT", bears N.27 E., 5.7 ft.
22" Douglas fir, I scribed "1/4S BT", bears S.8 1/2 E., 16.0 ft.

No original evidence found.

6/24/74

67

Section corner for Secs. 34, 35 and 3 and 2, T27-8.

Found - 1 1/2" I.P. & Set brass cap alongside mkd. T26S R8W WM S34, S35
T27S R8W WM S3, S2 1974 from which a:
60" orig douglas fir BT stump with partial face, bears S.25 E.,
42.2 ft.
6" Yew, possible BT down and rotting, bears S.10 W., 29.0 ft.
36" D. Fir stump scribes vis., bears S.81 E., 36.5 ft.
8" D. Fir BT, no scribes on face, I scribed "T26S R8W S35 BT",
bears N.58 E., 18.6 ft.
10" D. Fir BT faced but no scribes vis., I scribed "T26S R8W
S34 BT", bears N.68 W., 13.1 ft.
8" Madrone BT bark scribes vis., bears S.87 W., 17.6 ft.
8" Hemlock BT, faced but no scribes, I scribed "T27S, R8W S2
BT", bears S.77 E., 10.7 ft.
Badly burned post with scribes vis. wired to pipe. Last 4
trees have "Weyco" tags and "W" nails in root collars.

6/24/74

68

1/4 Corner for Secs. 27 and 34.

Found - 1970 County Surveyors brass cap from which:
74" Orig. D. Fir BT snag, scribing vis. bears S.24° W., 30.4 ft. Ren. #44
15" D. Fir BT scribing vis. bears S.7° E., 20.3 ft. (record
7.3 ft.)
15" D. Fir BT scribing vis. bears N.67° E., 21.4 ft.

81

RE-RENEWED SEE CORNER NO.

Shaner Engineering
for
Hub Lumber
RM 2 - 63
6/24/74