

Douglas County Surveyor's Record of  
Government Corners Renewed

T 26 T. S. R. 8 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21681

69

Shaner Engineering  
for  
Hub Lumber  
June 24, 1974

Section corner for Secs. 28, 27 33 and 34.  
Found - 2" iron pipe with brass washer attached mkd. "RS 404 Ren # 4  
from which A:  
36" orig. D. Fir BT now rotted snag, bears N.42° E., 37.6 ft.  
36" orig. D. Fir BT now rotted snag, bears S.63° E., 39.6 ft.  
40" orig. D. Fir BT now rotted snag, bears S.14° W., 88.4 ft.  
42" orig. D. Fir BT, now rotted snag, bears N.31° W., 38.3 ft.  
20" D. Fir BT, face grown over, bears N.8° W., 42.1 ft.  
16" D. Fir BT, face grown over, bears N.12° E., 29.0 ft.  
18" D. Fir BT, face grown over, bears S.72° E., 31.4 ft.  
14" D. Fir BT opened and found scribes, bears S. 62 W., 6.4 ft.

R. C. Adamek,  
Dellwood Dist. Eng.  
for Weyerhaeuser Co.  
Sept. 23.1974  
M 54 - 75  
C S. 58/23

1/4 Cor. for Sec. 7 and Sec. 12 of T26-9. 70  
No trace of orig. bearing trees was found. The correct position was  
determined by single proportion and fell in Cedar Creek so a:  
1" I.P. witness corner was established N.28°36.5'W., 18.11 ft. of the  
true position.  
The witness corner was referenced as follows:  
Large boulder bears N.73°51.5'E., 11.4 ft.  
24" Alder, bears S.78°31.5'W., 38.3 ft.

Robert C. Adamek  
For: Weyerhaeuser Co.  
Aug. 18, 1975  
M 57-74 C.S. 58/63

1/4 Corner for Secs. 23 and 26. 71  
Corner restored by single proportion method and now falls in small creek.  
Found - 32" D. Fir, reference point scribed by #404 (Ramsey). No bearing  
or distance available. Ren. #17  
Set - 3/4" I.P. in a pile of rocks from which:  
32" D. Fir, bears S.04°W., 53.0 ft., scribed by #404  
48" D. Fir, bears N.31°E., 10.0 ft., not scribed

Robert C. Adamek  
For: Weyerhaeuser Company  
Elk Wallow Survey  
July 13, 1977  
M 66 - 12 CS 58/139

W. 1/4 Corner for Sec. 31. 72  
Set by single proportion: A 2" brass cap monument  
From which:  
A 18" Hemlock bears N.81°W., 12.8 ft. scribed 1/4 Cor RP  
A 13" Hemlock bears S.85 1/2°E., 19.1 ft. scribed 1/4 Cor RP.

SW Corner Sec. 31 (Township corner) 73  
Set - By double proportion a 2" brass cap monument from which:  
A 12" D. Fir bears N.76°W., 27.9 ft. scribed TWP Cor RP.  
42" D. Fir bears S.78°E., 50.1 ft. scribed TWP Cor RP.  
19" D. Fir snag bears N.21°E., 15.8 ft. scribed TWP Cor RP.  
13" Chinquapin bears N.89 1/2°W., 27.2 ft. scribed TWP Cor RP.

S 1/4 Cor Sec. 31 74  
Set - by single proportion a 2" brass cap monument  
From which:  
A 26" D. Fir bears N.49°E., 17.6 ft. scribed 1/4 Cor RP.  
A 27" D. Fir bears S.11 1/2°E., 47.6 ft. scribed 1/4 Cor RP.

R. B. Kimberling  
Doug. Co. Surveyors  
Office  
P.L. Earle  
S.J. Flause

1/4 Corner for Secs. 13 and 14. 75  
Found - A 1" x 30" I.P. laying 6" underground in loose turf, 2.0 ft. from  
corner location marked "County Surveyor Office" T26S 1/4 S14 S13  
R8W 1968 BLM 1971. Ren. #31  
Orig. BT, a 18" now 27" Hemlock is uprooted with visible scribing  
"1/4 S13 CS". Orig. position bears approx. N.63°E., 18.5 ft.  
A 10" now 11" rotted Hemlock stump, with blazed and scribed "BT"  
section laying alongside, bears N.23°W., 15.2 ft.  
A 44" D. Fir bears N.86°W., 24.9 ft. with a well healed blaze.  
Set - I reset brass cap 4" above ground and stamp "Reset 1978".  
New BT's-A 46" D. Fir bears N.82°E., 12.5 ft. I double blaze and scribe  
"1/4 S13 CS BT".  
A boat spike in center of a 34" Fir stump bears S.k8 1/2°W., 18.9 ft.  
marked "BO 1".  
A boat spike in center of a 48" Fir stump bears S.76 1/2°E., 30.0 ft.  
marked "BO 2".

Corner is at the North edge of a new clearcut unit and 120 ft. east of  
Road #26-8-13.1. See BLM Resurvey Pg 21042

5/2/78

1-79