

Douglas County Surveyor's Record of
Government Corners Renewed

27 T. S. 1 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Burton W. Helt
Wit: C. Halversen
June 10, 1960
C. S. File No. 51/100

East $\frac{1}{4}$ Corner of Section 24. 1
as determined by old BT's.:
Found - O.B.T. 32" Fir S.40°W. 26.4 ft. scribes & tree in good condtn.
The 30" Fir N.59°W. 14.5 ft. was removed in road construction.
22" Fir S.61°E. 19.8 ft., now stump with face where scribes
were purposely destroyed.
Line Tree 13.2 feet North.
Old Stone Mkd. $\frac{1}{4}$ but the brass cap & pipe are missing.
Set $\frac{1}{2}$ " x 36" I. R. with 1" sq. nut at top for corner and set new
BT., which is:
46" D. Fir bears S.72°W. 29.8 ft. to face of tree, Mkd.:
 $\frac{1}{4}$ S24 BT. on bark.
This corner is approx. 80 ft. south of the Cleburn Sale Road and
50 ft. S. of W. $\frac{1}{4}$ cor. Sec. 19, T27S R1E.

RE-RENEWED CORNER NO. 41

Burton W. Holt
Wit: Jim Coon
December 3, 1960
C. S. File No. 51/100

Closing Corner between Sections 6 & 7. 2
as determined by Original BT.:
Found 12" D. Fir S.12°E. 29.7 ft. in good condition with
scribing visible.
The 7" Maple N.52°E. 26.4 ft. was removed in road construction.
Found - 8" x 10" x 12" Stone at Corner.

Set 1" x 36" Iron Pipe with Brass Cap at Corner Marked:

T27S
R | S 6 | R
2 | S 7 | 1
W | | W

RE-RENEWED CORNER NO. 13

LS418
1960
Rescribed OBT above old scribes marked: C. C. S 7 BT.
Set new BT. which is: 18" D. Fir N.84°E. 100.2 ft. to face
of tree, marked: C.C. S 6 T27S RLW BT.
USFS Road passes bet. N. E. BT. and Corner.

Thomas E. Shrum, Jr.
Wit: Bud Shrum
February 6, 1961
C. S. File No. 51/175

Section Corner 17 - 18 - 19 - 20. 3
Found - 12" Hemlock N.72°W. 24.4 ft. - Dead
14" Hemlock S.41°W. 60.7 ft. - Dead
Set - 46" Cedar N.45°E. 210.1 ft.
28" Cedar S.89°E. 154.8 ft.

RE-RENEWED CORNER NO. 64

Section Corner 19 - 20 - 29 - 30. 4
Found - Stone marked as called for in G. L. O. Notes
All trees have been destroyed.
Set - 16" Doug. Fir S.82°W. 84.3 ft.
33" Cedar S.21°E. 110.5 ft.
8" Hemlock N.43°E. 100.1 ft.

RE-RENEWED CORNER NO. 66

$\frac{1}{4}$ Section Corner 17 - 20. 5
Found - 14" Doug. Fir N.62°E. 26.4 ft. - Rotten
14" Doug. Fir S. 6°W. 39.6 ft. - Down
Set - $\frac{3}{4}$ " X 36" Iron Rod
12" Doug. Fir S.26 $\frac{1}{2}$ °W. 38.7 ft.

RE-RENEWED CORNER NO. 85

$\frac{1}{4}$ Section Corner 19 - 20. 6
Found - Stone marked as called for in G. L. O. Notes.
36" Doug. Fir - N.32°W. - 15.2 ft. (S.32°W. in Orig. Notes)
36" Doug. Fir - S.48°E. - 17.8 ft. (N.48°E. in Orig. Notes)
Set - 7" Hemlock - S.41°W. - 55.7 ft.

RE-RENEWED CORNER NO. 65