

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 27 S. T. S. R. 1 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

119

Section Corner to Sections 32, and 33, T. 27 S. R. 1 W.  
Found - No trace of Hemlock cor. post. But found one good BT and one down BT.  
10" D.Fir, now 14" windfall, N.56°E. 16.5 ft., shows open rotted face, no scribing.  
18" D.Fir, now 29", N.42°W. 28.4 ft., opened and found scribing of "3" and other marks.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1970 T 27 S R 1 W S 32 | S 33 S 5  
New BT's: 36" D.Fir N.18°W. 27.4 ft., scribed "T27S RLW S32 CS BT".  
18" D.Fir N.20½°E. 41.5 ft., scribed "T27S RLW S33 CS BT".  
Note: See corner of 32, 33, lies 10.4 ft. West of the C.Cor. of 4, 5, on the Township Line of T27S, and T28S. 1/9/70

120

Closing Corner to Sections 4 and 5, T28-1W.  
Found - 12X8X8 corner stone in place and marked 4 notches East & 2 on West plus two good BT's.  
14" D.Fir, now 26", S.15°E. 25.7 ft., shows good axe face.  
12" D.Fir, now 20", S.45°W. 44.9 ft., opened and found scribing of "BT".  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1970 T27S RLW S 33 T28S CC S 5 S 4  
No new BT's needed. This C.Cor. of 4, 5 lies 10.4 ft. East of the sec. cor. of 32,33 on Township Lines of T27S and T28S. 1/9/70

121

¼ Cor. sections 23 and 26.  
Found- No trace of a 15x10x5 cor. stone.  
30" Douglas Fir now 48" N.43°E. 24.4 ft. Shows a good axe face.  
14" Cedar now 30" S.40°W. 22.4 ft. Opened and found scribing of (4,2)  
Set - Brass cap at the ¼ cor. mkd: County Surveyor's Office 1970 T27S RLW ¼ S23 S26  
Rescribed BT- 30" Cedar S.40°W. 22.4 ft. Scribed ¼ S26 CS BT.  
Note - This ¼ cor. lies 100 ft. E. approx., of a Cr. on a steep N. slope. Jan. 13, 1970

122

Section Corner to Sections 5 and 6 only, T27-1W.  
From Iron Rod set as reference pins, see notes in file & Ren.#90.  
This corner lies in center of Road. Reset Brass Cap.  
Reset corner to proper location, See sketch on field notes in file.  
New BT's: 30" Cedar N. 3° W. 34.3 ft. scribed "T26S RLW S31 CS BT".  
12" Hemlock N.31°W. 49.6 ft. scribed "T26S RLW S31 CS BT". 11/13/70

123

Sec. Corner to Sections 31 and 32 only, T26-1W.  
Set from rod which was set as reference pins, See Ren. #91 and notes in C.S.File. This corner lies 25 ft. N. of new road.  
Also, 116.4 ft. E. of Sec.Cor. Secs. 5 & 6 only, T27-1W.  
Reset Brass Cap in proper location, from Bearing Trees:  
36" Cedar N.34°E. 7.9 ft. scribed "T26S RLW S31 CS BT".  
15" Hemlock N.19°W. 21.8 ft. scribed T26S RLW S31 CS BT". 11/13/70

124

¼ Corner Section 18 only, T. 27 S. R 2 W. # 22  
Found - Unrecorded U. S. Plywood Alum. Cap Mkd. ¼ S 18 only 1962 & O.B.T, as follows:  
Orig. 7" now 9" Hemlock . 18°E., 11.2 ft. lying face down--we roll over & fd. ¼ S 18 BT Scribe under 40 + years of overgrowth - (Old field notes call for Fir) No trace other O.B.T. Cor. stone called for is broken & small piece is Mkd. ¼" We mark new B.T.s.  
54" D.Fir stump N.69°E., 29.5ft. Mkd. ¼ S 18 CS BT.  
50" D.Fir stump S.22°E., 37.0 ft. Mkd. ¼ S 18 CS BT.  
This cor. lies on N. slope in old clear cut area. 6/20/69

John M. Powell  
Frank Jones & W. Penley  
C. S. File No. 54/94

V. R. Tracy  
J. Heritage  
V. Perron  
6/12/69  
C.S. No. 54/40

MARCH 71

JAN 1972

DUP

of BEN.