

Douglas County Surveyor's Record of
Government Corners Renewed

T. 27 S. T. S. R. 2 W. R. W. W. M.

FOKE-CHAPMAN CO., EUGENE, ORE. 97401

224

1/4 Section Corner common to Sec. 2, & Sec. 35 of T. 26-2.

Fnd - 1967 C.S. BCIP. Ren. #64.

BTs- 40" fir snag, 20ft. tall bears N.4°W., 29.7-ft. Orig. BT.
5" fir, down & decaying, bears N.63°W., 9.2-ft.
scribing visible on open face. 1967 BT.
12" fir bears S.11°W., 3.1-ft. w/closed face. 1967 BT.

New BT- 6" fir bears N.38°W., 40.8-ft., scribed 1/4 S35 BT. 3,4/84

Ronald Geisler,
PLS #1988
For Champion Intern.
Mar. - Apr., 1984
M 90 - 55

225

1/4 Corner for Section 8 only. (north)

Found - 1971 BLM brass cap/iron pipe.
4" double-trunked maple bears S.33°E., 11.6 ft. (rec. 11.2 ft.)
No scribing found - rescribed: X BT

New BT - 6" maple bears S.16°E., 38.3 ft. scribed 1/4 S8 BT.

Ronald Geisler
L.S. 1988
For: Champion
International
Aug.-Oct. 1984
M 90 - 60

226

Closing Corner for Section 8 and 9

Found - 1971 BLM brass cap/iron pipe.
Found a badly bent 1968 County brass cap which bears N.0°15'W.,
1.4 ft. Ren. #119
Decaying maple stump bears S.03°W., 52.8 ft. Down maple nearby,
shows visible scribing. (1971)
25" fir bears S.27°E., 34.8 ft. (Rec. 34.3 ft.) Closed face. (1971)

New BT - 6" cedar bears S.04°W., 96.4 ft. scribed T27S R2W S8 CC BT.

Aug-Oct 1984

1/4 Corner for Sections 1 and 12.

Found - 1957 County brass disk on a I.P. protruding 10" above ground. #6
Orig. BT, 18" now a 17" dia. W. fir with an opened blaze, scribing
visible "S" bears N.42 1/2°W., 4.5 ft. (Rec. N.39°W., Ren. #156)
14" Fir now down and rotted, no scribing visible. Root hole bears
N.30 1/2°E., 17.4 ft. Ren. #6

SW BT per Ren. #6 not found.

A 16" W. fir with a double well healed blaze bears N.70 1/2°W.,
6.3 ft. (Rec. per Ren. #156, N.78°W.) Ren. #60

A 12" maple with a partially healed double blaze, scribing
visible "1/4 S12 BT" and an alum. washer in bottom blaze marked
"LS 1005" bears S.49°E., 16.4 ft. (Rec. S.45°E., 17.0 ft.) #156

New BT - A 6" W. fir double blazed and scribed "1/4 S12 CS BT" bears
S.27°W., 54.3 ft.

Corner is approx. 200 ft. south of Littler River Road.

12/11/84

Center 1/4 Corner for Section 13

Corner was established by R. Ware LS 1005 in 1977. Ren. #162, It was
monumented with an iron pipe with brass cap. In 1982, the I.P./B.C. was
referenced out and the monument removed by Jim Landrum, Deputy Co. Surveyor,
due to new road construction. Ren. #221. I am unable to locate Ware's
iron pipe removed in 1982.

Found - A 12" hemlock (1/2 dead) bears N.73°E., (Rec. N.69°E.) 35.2 ft.
with scribe marks "C 1/4 S13 BT" visible on partially healed
double blaze. Ren. #162

A 25" hemlock bears S.32°W., 28.7 ft. with scribe marks "C 1/4
S13 BT" visible on partially healed double blaze. Ren. #162.
(Both BTs have a 1 1/2" diam. alum. washer, stamped "LS 1005"
nailed to lower blazes.)

A 60d nail in base of 68" D. fir snag (on east side of snag)
bears N.68 3/4°W., 32.9 ft. to center of nail head. Ren. #221

A 60d nail in top of 48" D. fir stump (6" from NE edge) bears
S.74 1/2°E., 27.6 ft. to center of nail head. Ren. #221

Set - At point of intersection of all record distances and of the
bearings as noted, I dig a hole 34" deep in gravel road (USFS
Road #2700-030), in bottom of hole, I place a 2 1/2" dia. tin
United States Tobacco Co. lid. I then set a 2 1/4" outside
dia. I.P. 25" long with flared base in the hole with brass cap
marked "T27S R2W C 1/4 S13 LS 1181 1984". Brass cap is now 9"
below road surface in right wheel track with a 7" x 10" alum.
sign immediately on top of it.

Maurice Farr
LS #1181
Leonard Herzstein
Randy Lopez
U.S.F.S.
Dec. 12, 1984
C.S. 62/15

228