

Douglas County Surveyor's Record of
Government Corners Renewed

T. 27 S. T. S. R. 2 W. R.W.W.M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

Section Corner: Sections 10, 11 14, 15

31

Found - Original Stone and 9" D.Fir S.40°E. 35.0 ft.
15" D.Fir, S.28°W. (Orig.S.21°W.) 33.0 ft.
Set - 2 1/2" Aluminum Cap (See Map File M 37 - 18)
9" D.Fir N.19°W. 34.1 ft. Mkd: S10 BT.
6" Madrone N.26°E. 24.6 ft. Mkd: S11 BT.
Orig. 6" Madrone for Sec. 11 is gone
Orig. 10" Live Oak N.59°W. for S10 is not legible.

1/4 Section Corner: Sections 14 and 15.

32

Found - 10" Yew, N. 20° E. 38.3 feet.
Set - 2 1/2" Aluminum Cap
7" Yew, N. 48 1/2° W. 40.7 feet. Mkd: 1/4 S15 BT.
Original Maple is gone.

1/4 Section Corner: Sections 13 and 14.

33

Found - 14" Cedar, N.22 1/2° E., 19.3 feet.
18" Cedar Stump, N.72°W. 15.5 ft.
Set - 2 1/2" Aluminum Cap.

1/4 Section Corner: Sections 26 and 35.

34

Found - 3/4" Iron Rod - This rod was set by me in 1956 from
the Orig. BT's. subsequent logging destroyed all
Orig. BT's. I now set a 2 1/2" Alum. cap in place of
the iron rod & reference two new BT's:
Set - 2 1/2" Aluminum Cap
15" Yew, S. 45° W. 5.8 feet; Mkd: 1/4 S35 BT.
13" Yew, N. 75 1/2° E. 47.4 feet. Mkd: 1/4 S26 BT.
10/15/68 - FOUND O.K. V.R.T.

Section Corner: Sections 27, 28, 33, 34.

35

Found - 1 1/2" Iron Pipe
30" Cedar Stump, S: 21° E., 25.7 ft. Rescribed: S34 BT.
34" D.Fir Stump S.21 1/2°W. 11.9 ft., rescribed S33 BT.
30" Cedar Stump, N. 11 1/2°W., 7.9 ft., Rescribed S28 BT.
36" Hemlock Stump, N.57 1/2°E. 42.2 ft.
Set - 2 1/2" Aluminum Cap.
35" Cedar Stump N.17 1/2°E. 50.5 ft. Mkd: S27 BT.

Section Corner: Sections 25, 26, 35 36.

36

Found: 26" D. Fir Stump S:49°W. 5.6 ft. Scribe good
condition (Orig. 24" Doug. Fir)
36" D. Fir Stump N.55°W. 20.0 ft.
Rescribe: S26 BT (Orig, 30" Doug. Fir)
18" Yew, S. 65 1/2° E. 26.7 ft. Rescribe: S36 BT.
Set: 2 1/2" Aluminum Cap
22" D. Fir Stump, N. 15 1/2° E., 12.1 ft. Mkd: S25 BT.
(Orig. Hemlock for S25 is gone.)

Same as above
T.E. Shrum
C.S.File
51/254

Dec.
1962

1/4 Section Corner: Section 14 and 23.

37

Found - 20" D.Fir, S. 34° E., 17.8 feet.
20" D.Fir, N. 20° W., 4.6 feet.
(Original BT's. in good condition)
Set - 2 1/2" Aluminum Cap.

1/4 Section Corner: Sections 26 and 27.

38

Found - 1 1/2" Iron Pipe (set in 1954)
18" Hemlock, N. 57° W., 8.0 feet (down & rotten)
Set - 2 1/2" Aluminum Cap
(No trees within limits to scribe)

SEARCHED FOR, NOT FOUND Nov 1968 V.R.T

Thomas E. Shrum, Jr.
For U. S. Plywood Corp.
November 1962
C. S. File No. 51/254

Thomas E. Shrum, Jr.
For U. S. Plywood Inc.
April 17, 1963
C. S. File No. 51/254