

Douglas County Surveyor's Record of
Government Corners Renewed

T. 27 S. T. S. R. 2 W. R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE. 21881

39

$\frac{1}{4}$ Section Corner : Sections 11 and 12.
Found - Original Stone, $\frac{1}{4}$ on W. face.
10" Doug. Fir, S. 72° E., 34.3 feet, dead & burned, but scribe visible.
Chinquapin, (Orig. BT gone)
Set - 2 $\frac{1}{2}$ " Aluminum Cap
8" Hemlock S. 30° W., 26.3 feet, Mkd: $\frac{1}{4}$ S11 BT.
Nothing alive within limits to scribe in Section 12.

RE-RENEWED - SEE CORNER NO. 101

40

South $\frac{1}{4}$ Section Corner, Section 12, (only)
Found - Original Stone - $\frac{1}{4}$ N. face.
48" Doug. Fir, S. 79° W., 38.4 feet. (Orig., good condition)
37" Doug. Fir Snag, N. 54° W., 22.3 feet., (original)
Aluminum reference tag S. 76° E., 7.9 feet, 1952.
Set - 2 $\frac{1}{2}$ " Aluminum Cap
10" Sugar Pine, N. 17° E., 26.2 feet, Mkd: $\frac{1}{4}$ S12 BT.

FOUND - Nov. 1968

41

Cor. to Sections 7 & 18, T27-1W. (E. Line T.27S R2W)
Found - 36" Sugar Pine S. 22° E. 30.4 ft., opened & found good scribing.
No trace of any other Bearing Trees.
Did not find Rock at Corner.

Set - Brass Cap at Cor. Mkd: County Surveyor's T27S R2W S 7 RLW
Office, 1963 S18

New BT's: 18" D. Fir N. 11° E. 35.5 ft. Mkd: T27S RLW S7 CS BT.
16" Red Cedar S. 67° E. 29.4 ft. Mkd: T27S RLW S18 CS BT.

Note - This corner is approx. 10 chains south of cor. Secs. 12 & 13, T27-2W.

FOUND O.K. Nov. 1968 V.R.T.

42

Closing Corner to Secs. 12 and 13, T27-2W. (W. Line T27-1W)
Found - Rock 15" x 8" x 6" with 2 notches on one side & 4 notches on
opposite side lying loose on top of ground near corner.
11" Red Cedar S. 30° W. 20.5 ft., has been previously opnd, good scrbing.
Stump of 50" Fir N. 40° W. 23.1 ft., scar visible.

Set - Brass Cap at Cor. Mkd: County Surveyor's T27S R2W S12 RLW
Office, 1963 S13

Deposit Corner Stone alongside.

New BT's: 15" Red Cedar N. 14° W. 66.3 ft., Mkd: T27S R2W S12 CS BT.
12" D. Fir S. 60° W. 9.6 ft. Mkd: T27S R2W S13 CS BT.

Note - Corner lies approx. 200 ft. N. of rocked logging road running NW. & SE.

43

Closing Corner to Sections 6 and 7, T27-1W. (E. Line T27-2W.)
Found - Brass Cap set in 1960. Also Orig. Rock alongside (See Ren.#2, T27-1W.)
18" D. Fir N. 84° E. 100.2 ft. (to face) bark scribing visible. This
tree is across road from corner. Tree alive & in good condition.
10" Fir S. 12° E. 29.7 ft. bark scribing visible. This tree is still
alive but in poor condition.

New BT: 20" D. Fir S. 30° E. 40.8 ft. Mkd: T27S RLW CC S7 CS BT.

RE-RENEWED - SEE CORNER NO. #247

44

Corner to Sections 18 and 19 only, T27-1W. (E. Line T27S R2W)
Found - 24" Hemlock Snag S. 26° E. 8.6 ft., face badly burned, no scbng. visible
Uprooted Fir Snag N. 21° E. 17.8 ft., cut open & fd. good scribing "S".
Could not tell exactly where tree had stood.

Portion of large Cedar Stump with root system still in ground,
N. 63° W. 23.8 ft., no markings.

Did not find Orig. S. W. BT.

Set - $\frac{3}{4}$ " Iron Rod, Corner position falls under log approx. 40" diam.

Rescribe - Hemlock Snag S. 26° E. 8.6 ft. T27S RLW S19 CS BT.

New BT: 40" D. Fir Stump N. 34° E. 60.0 ft. Mkd: T27S RLW S18 CS BT.

No live trees available. Corner is in clean cut logged area.

Jan. 2, 1964

44A

South $\frac{1}{4}$ Corner to Section 11 only.

Set - 2 $\frac{1}{2}$ " diam. Aluminum Cap

Bearing Tree: Yew 8" diam. N01 $\frac{1}{2}$ W. 28.5 ft.

RE-RENEWED - SEE CORNER NO. 130

February, 1964

Thomas E. Shrum, Jr.
For U. S. Plywood, Inc.
April 17, 1963
C. S. File No. 51/254

Milo E. Godfrey, Deputy County Surveyor
Wm. Stoffel and Mike Stone
December 1963
C. S. File No. 49/28

Thomas E.
Shrum, Jr.
For: U. S.
Plywood
M 29 - 26