

Douglas County Surveyor's Record of
Government Corners Renewed

T. 27 S. T. S. R. 2 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

(continued)

Set - Brass Cap at Cor. Mkd: County Surveyor's T 27 S
(Reset stone alongside) Office, 1968 R2W $\frac{1}{4}$ S 36 | S 31 RLW
This corner falls 50 ft. N. of small creek, course NW in dense
thicket of vinemapple. No smaller trees near to scribe for BT's.

80

North $\frac{1}{4}$ Corner to Section 1 only, T28-2W.

Found - 1923 GLO Brass Cap under log and bent over.

Orig. 48", now 50" Fir, alive, S.26°E. 139.9 ft., blazed, no scribe visible.

Orig. 84", now 85" Fir, dead, S.43°W. 49.5 ft., open & find " $\frac{1}{4}$ " BT" scribe.

Reset Brass Cap at Cor. Point & remove portion of Log.

New BT's: 80" D.Fir S.23°W. 43.0 ft. mkd: " $\frac{1}{4}$ " S1 CS BT".

15" R.Fir S.62°E. 116.6 ft. mkd: " $\frac{1}{4}$ " S1 CS BT".

This corner lies on northerly slope in dense vine maple thicket.

81

Cl. Corner for Sec. 1, T28-2W. and Sec. 6, T28-1W.

Found - Do not find corner stone called for at closing corner.

Orig. 18", now 36" Fir, alive, S.71°E. 49.5 ft., shows good scar.

Orig. 12", now 24" Fir, alive, S.79°W. 41.6 ft., shows good scar.

We open & find scribe marks.

Set - Brass Cap at Cor. Mkd: County Surveyor/s T27S
Office, 1968 T28S R2W S 1 | S 6 RLW

New BT's: 20" D.Fir S.10°W. 7.9 ft. mkd: "T28S R2W S1 CC CS BT.

14" D.Fir S.42°E. 14.2 ft. mkd: "T28S RLW S6 CC CS BT.

This corner lies on steep S.W. slope about 413 ft. W. of Stand. Cor. of

T27S R's. 1 & 2 W.

C. C. to Sections 1 and 2, T28-2W.

Found - 1923 GLO Brass Cap, properly marked and in place.

Orig. 9", now 30" Fir, alive, S.5°W. 75.2 ft., shows good scar.

Orig. 6", now 24" Fir, alive, S.68°E. 147.2 ft., shows good scar.

New BT's: 14" D.Fir S.73°W. 12.3 ft. mkd: "T28S R2W S2 CC CS BT.

15" D.Fir S.34°E. 5.0 ft. mkd: "T28S R2W S1 CC CS BT.

This corner lies on steep easterly slope in 2nd growth fir.

83

$\frac{1}{4}$ Corner to Sections 21 and 22.

Found - Unrecorded $\frac{3}{4}$ " Iron Rod at assumed corner point & old

squared post with fragmentary scribe, badly decayed,

12", now 14" D.Fir, S.71°E. 4.0 ft. (Rec. S89E 33.7) previously

opened, shows "BT" scribe. We open above & find "2" scribe

& reverse under 51+ years overgrowth.

24", now 28" D.Fir, N.71°W. 4.6 ft. (Rec. N89W 34.3) large boulder

lays against good axe scar making it impossible to chop open.

No evidence of any other BT's. at record bearing & distance.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 27 S R 2 W
Office, 1968 $\frac{1}{4}$ S 21 | S 22

New BT's: 20" D.Fir N.84°E. 6.3 ft. mkd: " $\frac{1}{4}$ " S22 CS BT".

13" D.Fir N.45°W. 6.6 ft. mkd: " $\frac{1}{4}$ " S21 CS BT".

The call on ridge to south of $\frac{3}{4}$ chains would fit this corner location

very good. This corner lies on steep westerly slope.

84

$\frac{1}{4}$ Corner to Sections 29 and 32.

Found - 2 $\frac{1}{2}$ " Alumn. Cap, firmly set & properly mkd., Ren. #25.

12", now 16" Cedar, down, N.50°E. 11.2 ft., old scribe visible
& new scribe visible.

6", now 10" Cedar, alive, S.36°W. 19.2 ft., scribe visible on
nearly healed blaze.

Set - 6 ft. Steel Fence Post alongside Aluminum Cap.

New BT: 8" Hemlock S.20°E. 31.0 ft. mkd: " $\frac{1}{4}$ " S32 CS BT".

No other trees near north of corner in section 29.

This corner lies on moderate northerly slope in clear cut unit.

Vernon "Ray" Tracy
J. Heritage & V. Perron
October, 1968
C. S. File No. 54/40

RENEWED CORNER NO. #203 82
RENEWED CORNER NO. #206