

Douglas County Surveyor's Record of
Government Corners Renewed

T 27 T. S. R 3 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97501

138

cont - - -

(1/4 Cor. 2 and 11, cont.)
Found - 15" Fir, now a 15" dia. 6 ft. tall fir stump with a well healed single blaze, no scribing visible, bears N.19°E., 163.0 ft. (per rec). (1958 Dependent Resurvey)
18" Cedar now a 24" dia. 2 ft. tall cedar stump with a well healed single blaze bears S.44 1/2°E., 132.7 ft. (1958 Resurvey)
New BTs from as yet unrecorded BLM survey done in 1984:
6" D.B.H. D. fir with the scribing 1/4 S11 BT visible in a partially healed single blaze, bears S.65 1/2°E., 25.4 ft.
An 11" D.B.H. cedar with the scribing 1/4 S2 BT visible in a partially healed single blaze bears N.31 1/2°W., 33.8 ft.
Monument lies near top of cut bank on north side of Little River Rd. approx. 0.2 miles southeast of Little River Store. (Cavitt Creek area.)

S. J. Flause
R. W. Smith
Doug. Co. Surveyors
Office - 12/7/84
C.S. 62/21

1/4 Corner for Section 12; and Sec. 7 of T.27-2
Found - 1968 County brass disk on a I.P. protruding 8" above a 2 1/2 ft. dia. mound of stone, properly marked. Ren. #107
No visible evidence found of 1/2" I.R. noted in Ren. #62 or #107. No evidence found of 3/4" I.R. set in 1947. (per C.S. 40/56).
Found - 14" now a 28" dia. 3 ft. high rotted and burnt stump. No scribing found, bears N.36°W., 7.8 ft. to center. (Rec. N.15°W., 5.3 ft. Original BT.
10" now a 16" D. fir with a well healed single blaze bears S.55 1/2°W., 25.7 ft. which agrees with 1979 BLM resurvey. (Rec. S.57°W., 26.5 ft. per Ren. #62 and #107)
6" now a 14" D. fir with a well healed single blaze bears S.13°E., 20.8 ft. which agrees with 1979 BLM resurvey. (Rec. S.11°E., 21.0 ft. per Ren. #62 and #107)
New BTs - 8" D. fir double blaze and scribed "1/4 S7 CS BT" bears S.51°E., 25.6 ft.
13" D. fir double blaze and scribed "1/4 S12 CS BT" bears N.25 1/2°W., 38.6 ft.
Corner lies approx 50 ft. south of the left bank of Little River.

139

Larry E. Monrean
L.S. #1830
Randall Smith
Stephen Flause
Doug. Co. Surveyors
Office
Dec. 13, 1984
C.S. 62/21

12/13/84

140

Township corner for sec. 6; Sec. 1, T.27-4; Sec. 36, T26-4; Sec. 31, T.26-3
Found - A 2 1/2" County brass disk on a 2" I.P., protrudes 4" above ground, properly mkd. Ren. #17A & 56
10" now 32" dia. W. oak with a previously opened now rotted face and a single well healed blaze per Ren. #92 bears S.76°W., 175.7 ft. 1917 resurvey
36" now a 48" dia. 3 ft. high D. fir stump with bark scribing "S BT" bears S.6°E., 543.8 ft. Ren. #17A & 56
30" now a 30", 2 ft high W. oak stump with a possible blaze, bears N.15 1/2° W., 233.1 ft. (Rec. 231.5 ft. to face.) Ren. #56
12" now a 22" D. fir with a well healed double blaze bears S.26 1/2°E., 443.8 ft. (Rec. S.28°E., 444.6 ft.) Ren. #92
No original BTs found and the SW BT gone from 1947.
New BT - 6" dia. W. oak double blazed and scribed "T26S R3W S31 CS BT" bears N.53 3/4°E., 293.1 ft.
Corner lies 6" north of a E-W fence line and approx. 200 ft. east of Buckhorn Road in a pasture.

Randall Smith
Stephen Flause
Douglas County Surveyors
Office
January 9, 1985
C.S. 62/25

1/9/85

141

1/4 Section Corner for Secs. 11 and 14. REN #1
Found - A B.L.M. disk on a 2" diam. I.P., protruding 7 ins. above ground, mkd. "U.S. DEPT. OF THE INTERIOR T27S R3W 1/4 S11 S14 1984 BUR. OF LAND MANAGEMENT" (1984 BLM Unofficial Resurvey). With a 3/4" inside diam. I.P. along west edge of disk, protruding 9 ins. above ground per Ren. #1, and a 5/8" I.R. protruding 5 ins. above ground, source unknown.
Orig BT's- 16" now a 40" diam. R. Cedar with a chopped into partially healed upper blaze, scribe visible "S", lower blaze is partially healed with scribing visible. Bears S.43°W., 31.7 ft. (Rec. S.25°W., 31.7 ft.)
18" now a 46" diam. R. Cedar with a chopped into upper blaze, no scribe visible, lower blaze is partially healed with scribing visible "CS BT" bears N.61°W., 10.9 ft. (Rec. N.45°W, 9.2 ft. dist. is a face measurement).

Douglas Co. Surveyor's
Office
Randall W. Smith, &
Stephen J. Flause
July 9, 1985
C.S. 62/28

FD OK
6/2006
D. Edwards
M150-67
Change Report
C.S. 63/34
2/4/86

continue on next page...