

Douglas County Surveyor's Record of
Government Corners Renewed

27 T. S. 3 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 91881

Ronald G. Geisler, Champion International
June, 1985 thru August, 1985
M 90 - 71

149

Township Corner for Sec. 36 (T27-3); Sec. 31 (T27-2); Sec. 6 (T28-2); and
Sec. 1 (T28-3). Renewal #131 (27-3)
Found - A 1962 County Surveyor brass cap on an iron post, and the following
accessories;
BT's - 27" Fir stump, bears N.40°E., 46.9 ft. (Rec. N.43°E., 46.2 ft.)
Scribing partly visible. (Original)
44" Fir stump, bears N.52°W., 29.9 ft. (Rec. N.55°W., 30.4 ft.)
No scribing visible. (Original)
Badly decayed stump, bears S.25°W., 27.7 ft. (Orig.)
11" broken-top Fir, bears N.10°W., 19.7 ft. Closed face. (1962)
22" Cedar, bears S.27°W., 71.6 ft. (Rec. 72.0 ft.) Closed face
(1962)
16" Madrone snag, 17 ft. tall, bears S.06°E., 17.0 ft.
(Rec. S.03°E) Scribing visible. (1962)
9" down and uprooted fir bears N.87°E., 50.0 ft. No scribing
found. (1962)
10" Fir, bears N.27°E., 35.1 ft. (Rec. 35.3 ft.) Closed face.
(1980)
Set - 5" Fir, bears S.79°E., 5.9 ft. dist. Scribed: X BT.

Larry E. Monrean,
Deputy, Doug. Co.
Surveyors Office
R.W. Smith; S.J.
Flause, Crew.
Mr. Stan Hendy, Land
Owner
Sept. 11, 1985
C.S. 62/29

150

Section corner for Secs. 6 and 7; and 1 & 12 of T.27-4
Note: Original 1855 post not found. Ren. #26 of T.27-4, 1889 does not
indicate setting monument. 1917 resurvey, 16x10x4 sandstone not
found. 1958 resurvey monument, a 2 1/2" x 28" I.P. set at corner
was not found. Mr. Stan Hendy, (property owner) produced a 3 1/4"
dia. bronze disk marked in 1958. Disk was found lying loose on
the ground surface near the area we determine to be the corner
location. No original or Ren. #26 (T27-4) BTs were found. (No
BTs scribed per orig. notes.)
Found - 1917 BT, a 28" dia. Fir now a badly decayed fir stump with no
scribing found on old blaze bears N.19°W., 40.8 ft. (Rec. 40.3)
Size and center of stump indeterminable.
11" now 21" dia. Fir (1958) with well healed single blaze bears
S.50°E., 90.1 ft. level to center (Rec. 93.7) BT is alive and
in good condition.
11" now 13" W. oak with well healed blaze bears S.28 1/2°E.,
68.7 ft. Ren. #94
9" now 7" decayed fir stump 24" high with scribing "R S6 CS BT"
visible in partially healed double blaze bears N.44 1/2°E.,
162.3 ft. (Rec. N.45 1/2°E., 163.2 ft.)
No other BTs were found.
Set - At the point referenced by bearings and distances, we set a
1" x 30" galv. iron pipe with brass cap attached. Cap is marked
"Douglas County Surveyor T27S R4W S1 S12 R3W S6 S7 1985".
Monument protrudes 9 inches from ground.
New BT - 15" W. oak double blazed and scribed "T27S R4W S6 CS BT" bears
N.47°E., 171.0 ft.

Ron Giesler
For:Champion Internat-
ional Corp. February 1987
M 103 - 61

9/11/85

151

Center 1/4 Section 2.
Set : 2 1/2" Aluminum cap on a 2 1/2" x 30" flared aluminium
pipe.
BT's : A 6" fir bears N11°E, 59.9'.
8" fir bears S88°E, 66.5'.
Both trees are scribed "C 1/4 S2 BT".

Douglas Co. Surveyors
Randall Smith
Stephen Flause
Sep. 16, 1987
C.S. 62/45

152

Section Corner for Sections 21,22,27 and 28
Found - A Douglas County Surveyor 1 1/2" outside dia. iron pipe thats 36" long
with a 2 1/2" brass cap, bent and out of the ground. Per ren. #48
1958 BLM brass cap with iron pipe not found.
- A 20" now 36" dia. douglas fir with evidence of bark blaze and
axe marks no scribing found, bears N 10°W, 24.4 ft. (agrees
with record). Original BT.
15" laurel now 34" dia. madrone which was previously opened,
we opened further, no blaze or scribing found. Bears
S 54°E, 75.9 ft. (BT noted as a depression in Ren#48. S 54°E
74.6 ft. per 1957 BLM resurvey S54°E, 75.9 ft. per 1979 BLM
resurvey; original 74.6 ft. is a possible face measurement.)
No other original BT's found.
Bts Fd. per Ren. #48:
A 10" now 14" dia. Cedar with a fully healed double blaze bears
S 15°E, 48.8 ft. (S 15°E, 59.2 ft. per ren. #48, S 15°E,