

Douglas County Surveyor's Record of
Government Corners Renewed

27 T. S. 3 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97195

RE-RENEWED **RECORDED NO. #157** **40**
 $\frac{1}{4}$ Section Corner to Sections 10 & 15.
 Found - original Bearing Tree 12 inch now 28 inch Cedar snag, S.20°W.,
 13.9 feet face open, good scribing, "BT". Checks age by ring count.
 N. W. bearing tree gone. 10 T 27S.
 Set Brass Cap at corner marked County Surveyor's Office, 1957. $\frac{1}{4}$ S 15 R 3W.
 New Bearing Trees: 14 inch Cedar S.12°E, 44.8 feet scribed
 $\frac{1}{4}$ S. 15, CS BT.
 12 inch Cedar 52.0 feet, N.60°E., scribed $\frac{1}{4}$ S 10 CS BT.

James W. Byron
 M. Godfrey
 S. Blilow
 Sept. 18, 1957
 C. S. File No. 49/14

Section Corner to Sections 10, 11, 14, & 15. **FDAC D. Edwards 6/2006** **41**
MISO-67
 Found - Scribed stake at Corner & 4 Rocks. Also found all four bearing
 trees as recorded by B.B. Irving, 1945. All alive, show scribing
 and are in good condition. **REN. #6**
 Set Brass Cap at corner marked: S 10 | 11 T 27S, R 3W. County Surveyor's
 15 | 14 Office, 1957.

J. Byron
 M. Godfrey
 S. Blilow
 Sept. 18, 1957
 C. S. File #49/14

FIELD NOTES BE **ERRONEOUSLY MARKED** **42**
 $\frac{1}{4}$ Section Corner to Sections 35 & 36. **Should stump (9/13/57)**
 Found - Both of Boyer's renewed BTs. The 36 inch Black Oak ~~stump~~
 S. 57° W., 42.0 feet, shows rotted face, no scribing found.
 The 18 inch now 22 inch White Oak S.73°30'E, 108.0 feet has
 rotted face with faint scribe, marks "BT". Also find what I
 believe to be the original S.55°E, 93.1 feet BT. Checks bearing
 & distance and shows old face, rotted, no scribing found.
 Boyers BTs check bearings & distances. I can not find Boyers $\frac{1}{2}$ inch iron pipe.
 Set Brass Cap at corner marked S 35 | 36 T. 27S, R. 3W., County Surveyor's
 Office, 1957.
 I blaze & scribe 36 inch Black Oak stump S.57°W., 42.0 feet $\frac{1}{4}$ S. 35 CS BT.
 10 inch forked cedar S26 $\frac{1}{2}$ °E. 61.4 ft. scribed $\frac{1}{4}$ S 36 CS BT.
 11 inch Fir S.87°E, 96.7 feet scribed $\frac{1}{4}$ S. 36 CS BT.
 Brass cap is near fence corner, (See sketch in file.)

James W. Byron
 M. Godfrey
 S. Blilow
 Sept. 19, 1957
 C. S. File No. 49/5

43
 $\frac{1}{4}$ Section Corner to Sections 21/22.
 Found - Original 6" now 16" R. Fir BT. S.62°W., 40.9 ft, recently
 opened. I find good scribing "S".
 I can find no evidence of Original N.E. BT.
 Set Brass Cap at corner marked $\frac{1}{4}$ S21/S22 T27S R3W County Surveyor's
 Office, 1957.
 New BTs.: 24" R. Fir S.86°W., 31.3 ft. scribed $\frac{1}{4}$ S21 CS BT.
 20" R. Fir S.82°E., 33.7 ft. scribed $\frac{1}{4}$ S22 CS BT.
 Oct. 11, 1957

44
 $\frac{1}{4}$ Section Corner to Sections 18 & 17.
 Found - Original 24" now 30" R. Fir N.55°E., 29.7 ft. Shows old
 bark scribing "4S".
 The original 36" Cedar is down scribing would be under.
 Checks bearing distance. Seems to be about 3 ft.
 greater distance than record.
 Set Brass Cap at corner marked $\frac{1}{4}$ S18/S17 T27S R3W County Surveyor's
 Office, 1957.
 New BTs: 10" R. Fir bears N.32 $\frac{1}{2}$ °W., 10.3 ft. scribed $\frac{1}{4}$ S18 CS BT.
 Cedar bears N.81°E., 22.0 ft. scribed $\frac{1}{4}$ S17 CS BT.
 Oct. 14, 1957

James W. Byron, Deputy County Surveyor
 M. Godfrey
 S. Blilow
 Oct. 11-14-15, 1957
 C. S. File No. 49/14

45
 $\frac{1}{4}$ Section Corner to Section 21 and 28.
 Found - The original 20" now 36" R. Fir BT. Good bark scribing " $\frac{1}{4}$ S BT".
 The original N. E. BT. not found.
 Set Brass Cap at corner marked $\frac{1}{4}$ S 21 T27S R3W County Surveyor's
 S 28 Office, 1957
 New BTs.: 7" Cedar bears N.7°W., 18.2 ft. scribed $\frac{1}{4}$ S21 CS BT.
 16" R. Fir bears S.9°W., 27.7 ft. scribed $\frac{1}{4}$ S28 CS BT.
 Oct. 15, 1957