

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 27 S. T. S. R. 4 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97101

Milo E. Godfrey, Deputy County Surveyor  
Wm. Stoffel & Mike Stone  
January 1964  
C. S. File No. 53/33

Township Corner R5W  $\frac{S}{S} \frac{36}{1} | \frac{S}{S} \frac{31}{6}$  R4W (See Ren. No. 58) 114

Found - Corner Tree - 24" Doug. Fir in Fence Corner. Fences E. N. & N.W.  
1 1/8" Steel Axle N.55°E. 3 ft. from Corner Tree.  
30" Fir Stump N.87 1/2°W. 22.1 ft., opened & fd. good scribing "36".  
28" Fir Stump S.62°W. 21.8 ft., shows good scar.  
26" Fir Stump S.30°E. 31.0 ft., shows good scar.  
No trace of N. E. Bearing Tree.  
New BT's: 11" D.Fir N.83°E. 28.8 ft. Mkd: T26S R4W S31 CS BT.  
9" D.Fir N.16°W. 41.3 ft. Mkd: T26S R5W S36 CS BT.  
4" Madrone S.36°E. 51.4 ft. Mkd: S 6 CS BT.  
No trees available S. W. of Corner.

S. W. Cor. DLC No. 40 & S. SE Cor. DLC No. 39. 115  
Found- 36" W.Oak N.35°W. 44.2 ft., uprooted & down. Cut open & fd. good scribing "B".  
34" White Oak S.65°W. 39.6 ft. (to old face) shows faint scar. Did not open.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T27S R4W DLC 39/DLC 40  
Office, 1964.  
Set Steel Fence Post alongside.  
New BT: Rescribe - 34" White Oak S.65°W. 40.6 ft. (to center) Mkd: SW DLC 40CSBT  
No other trees near. A private power line pole bears N.36°E. 70.5 ft.  
Corner is in Barnyard.

S.W. Corner D. L. C. No. 39. 116  
Found - 1 1/2" Iron Pipe - No record of this pipe being set.  
30" White Oak Stump S.50°W. 56.1 ft., center of stump completely  
burned away, faint scar visible on bark.  
Note - This corner is 427 ft. W. of Cor. DLC 39/DLC40, see corner above.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1964  
T27S R4W S.W. Cor. DLC 39  
New BT's: 14" D.Fir S.62°W. 41.1 ft. Mkd: S W DLC 39 CS BT.  
22" W.Oak S.45°W. 38.7 ft. Mkd: S W DLC 39 CS BT.  
A 6" Well Casing in Concrete Slab bears N. 79° E. 42.7 feet.  
Corner is approximately 30 feet East of Buckhorn Creek.

N.W. Cor. DLC #40 & Int. "L" Cor. DLC #39. 117  
Found - 1 1/2" Iron Pipe in E. & W. Fence Line (See Ren. No. 11)  
16" Bl.Oak S.55°E. 56.0 ft., scribing visible in open blaze "L 40".  
No trace of Original BT. - No trace of N.W. Renewal BT.  
New BT's: 12" D.Fir S.35°W. 27.7 ft. Mkd: D.L.C. 39 CS BT.  
9" D.Fir S.28 1/2°E. 20.0 ft. Mkd: N.W. D.L.C. 40 CS BT.

N. W. Corner D. L. C. No. 43. 118  
Found - 34" Bl.Oak N.79°W. 33.0 ft. This tree has been opened years ago, face  
badly rotted, no scribing found, but portions of overgrowth on  
flat face found. *See Vol 2, Pg. 265 FORMER RENEWAL.*  
Badly Rotted Oak Stump S.59 3/4°W. 39.6 ft., showed axe marks on surface,  
no scribing found.  
Large Stump Hole S.57°E. 54.8 ft. (This fits Original BT.)  
Remains of old N. & S. Fence meets present E. & W. Fence Line 4 ft.  
South of Corner.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1964  
T27S R4W /DLC 43  
New BT's: 7" D.Fir S.11°W. 8.5 ft. Mkd: "NW DLC 43 CS BT".  
5" D.Fir N.61°E. 63.0 ft. Mkd: "NW DLC 43 CS BT".  
Note - For former renewal See Volume 2, Page 265.

1/4 Corner to Sections 3 and 10. 119  
Found - 42" Bl.Oak N.66 1/2°W. 9.9 ft., opened & fd. good scribing "S".  
24" W.Oak S.13 3/4°E. 44.2 ft., shows faint scar, blaze & rescribe this  
tree "1/4 S10 CS BT" (Dist. is to old face. See Ren. No. 14.)  
Set - Brass Cap at Cor. Mkd: County Surveyor's T27S R4W 1/4 S 3  
Office, 1964 S 10  
New BT: 5" White Oak N.80°W. 60.7 ft. Mkd: 1/4 S3 CS BT.  
Note - Faint evidence of old Fence Corner at 1/4 Corner.