

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 27 S. T. S. R. 4 W. R. W. W. M.

HOKE-CHAPMAN CO., EUGENE, ORE. 21881

N. E. Corner D. L. C. No. 43. 120  
Found - 19" Bl. Oak S.35°W. 12.5 ft., cut open & fd. good reverse  
scribing "BT".

Stump Hole of N. W. Bearing Tree.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1964

T27S R4W NE. DLC 43/

New BT's: 13" D. Fir S.15°W. 57.8 ft. Mkd: NE DLC 43 CS BT.

12" Bl. Oak N.67°W. 31.2 ft. Mkd: NE. DKC 43 CS BT.

Note - Corner lies 1.5 ft. North of an E. & W. Fence Line.

-----  
 $\frac{1}{4}$  Corner to Sections 2 and 11. 121

Found - 39" White Oak, N.3°E. 27.7 ft. This tree has been opened  
many years ago & center portion burned away.

(See affidavit of Mr. Lorris Singleton on Field Notes)

No trace of S. E. Bearing Tree.

Set - Brass Cap at Cor. Mkd: County Surveyor's T27S R4W  $\frac{1}{4}$  S 2  
Office, 1964 S 11

New BT's: 20" W. Oak N.39°E. 102.0 ft. Mkd:  $\frac{1}{4}$  S2 CS BT.

17" W. Oak N.51°W. 21.5 ft. Mkd:  $\frac{1}{4}$  S 2 CS BT.

No suitable trees available south of line.

Note - A 3-Way fence Corner - (Fences E. W. & N. bears N.51°W. 3.7 ft.)

-----  
 $\frac{1}{4}$  Corner to Sec. 6, T27-4W. & Sec. 1, T27-5W. 122

Found - 42" White Oak S.53°E. 92.4 ft., cut open & fd. good scbng.

Stump Hole & Small pieces of Oak N.2 $\frac{1}{2}$ °W. 92.4 feet.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1964

T27S R5W  $\frac{1}{4}$  S 1/S 6 R4W

New BT's: 8" W. Oak N.81°W. 22.5 ft. Mkd:  $\frac{1}{4}$  S1 CS BT.

9" W. Oak S.75°E. 28.6 ft. Mkd:  $\frac{1}{4}$  S6 CS BT.

-----  
Sec. Cor. to Secs. 5 & 6, T27-4W. & Secs. 31 & 32, T26-4W. 123

Found - 21" W. Oak N.70°E. 217.8 ft., opnd. & fd. rev. scribing "BT"  
on badly rotted pieces of overgrowth of old face.

No trace of any other Bearing Trees.

Set - Brass Cap at Cor. Mkd: County Surveyor's R4W T26S S 31 | S 32  
Office, 1964 T27S S 6 | S 5

New BT's: 6" D. Fir S.67°E. 15.3 ft. Mkd: T27S R4W S5 CS BT.

12" Inc. Cedar S.17°E. 88.8 ft. Mkd: T27S R4W S5 CS BT.

No suitable trees available in any other quadrant.

Note - Corner lies in E. edge of power line road, directly under  
power wires. Gate Post E. end steel gate in E. & W. Fence  
Line (scribed "BO") bears N.22°E. 16.0 feet.

-----  
 $\frac{1}{4}$  Section Corner to Sec. 2, T27-4W. & Sec. 35, T26-4W. 124

Found - 18" Bl. Oak N.25°E. 44.9 ft. This tree opened many years ago.

Good Scribing "BT" visible on badly decayed old face.

Tree still alive but top is broken out.

No trace found of S. W. Bearing Tree.

Set - 21" Black Oak N.19°W. 43.5 ft. Mkd:  $\frac{1}{4}$  S35 CS BT.

27" Doug. Fir S.25°W. 177.1 ft. Mkd:  $\frac{1}{4}$  S 2 CS BT.

Note - 3-Way Fence Corner (Fences N, S, and E.) bears East 2.0 ft.

-----  
N. W. Corner D. L. C. No. 51. 125

Found - 22" White Oak S.50°W. 50.8 ft., fragmentary scribing visible  
on decayed face in open blaze. This tree is recorded

as a renewal of the S. W. Cor. of DLC #51, instead of the

N.W. Corner. See Ren. No. 12 I believe this recording

to be in error. In Eppstein's notes in C. S. File 17/26, copy of  
Orig. Field Notes call N. W. Corner, S. W. Corner, (written over as  
N.W. Cor.) On prior job by Eppstein, 1919, recorded in F.B. 47, Pg. 44,  
he mentions a stake at the S.W. corner but says he can find no trace  
of Orig. BT's. (2 firs). Present investigation shows no trace of any  
Oaks near the location of the S. W. Corner, but plenty of evidence  
of old Firs, some over 100 years old. Also, the fence corner used as  
the N.W. Cor. of DLC # t1, falls less than 10 ft. from cor. set from  
this tree. No trace of Original BT's. found (See next page)

Milo E. Godfrey, Deputy County Surveyor  
 Wm. Stoffel and Mike Stone  
 January 1964  
 C. S. File No. 53/33

FD. 11/90 M 111-24

FO OK 8/87  
 D. BENTZ  
 M 101-26