

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 27 S. T. S. R. 4 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97101

(continued) N.W. Cor. DLC #51.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1964  
T27S R4W N.W. Cor. DLC 51  
New BT's: 12" Doug. Fir N.74°E. 65.2 ft. Mkd: N W DLC 51 CS BT.  
11" Madrone N.7°W. 28.5 ft. Mkd: NW DLC 51 CS BT.  
Fence Corner (Fences South & East) bears S.40°E. 8.0 feet.

N. E. Corner D. L. C. No. 52. 126  
Found - 1/2" Iron Pipe set in 1918, See Ren. #1.  
Rotted & burned remnants of Fir Stump N.60 1/2°W. 13.9 ft. (Ren. BT.)  
Stump Hole only S.60°W. 46.2 ft. (Orig. BT. 10" W.Oak S.60°W. 70 lks.)  
New BT's: 12" I. Cedar S.38°W. 82.4 ft. Mkd: N.E. DLC 52 CS BT.  
12" White Oak N.46°E. 70.8 ft. Mkd: N.E. DLC 52 CS BT.  
Note - Location of pipe found, checks tie for section corner shown in  
notes of Frear's survey, recorded in Vol. 3, Page 45.

1/4 Corner to Sections 35 and 36. 127  
Found - Dogwood, badly rotted, N.85°W. 5.3 ft. Opened & found fragments  
of reverse scribing on overgrowth of old face.  
Portion of stump & roots (badly rotted) of Cedar S.81°E. 4.0 ft.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1964  
T27S R4W 1/4 S35/S36.  
New BT's: 25" Hemlock S.74°W. 28.4 ft. Mkd: 1/4 S35 CS BT.  
53" Doug. Fir N.56°E. 24.0 ft. Mkd: 1/4 S36 CS BT.  
Note - Corner lies on very steep north slope approx. 1 chain south  
of small stream running west.

Sec. Cor. to Secs. 32 & 33, T27-4W. & Secs. 4 & 5, T28-4W. 128  
Found - Brass Cap set in 1959. Also 1/2" I. Pipe, See Ren. #43.  
3 BT's. mkd. in 1959 still in good condition:  
12" E. Cedar S.53 1/2°W. 99.9 ft.  
34" D. Fir N.79°W. 37.0 ft.  
8" D. Fir S.56 1/2°E. 75.4 ft. - N. E. Tree is now broken off.  
New BT's: 8" D. Fir N.58°E. 100.4 ft. Mkd: T27S R4W S33 CS BT.

Standard Corner of Sections 34 & 35, T27-4W. 129  
Note - This corner lies East 39.7 ft. of closing corner to  
Sections 3 and 2, T28S R4W.  
Found - 1958 Cadastral Brass Cap, pushed over & buried 13' below surface.  
Stump of Orig. N.W. BT. still in location.  
12" Cedar, now stump & covered by logs, N. 59° E. 73.3 ft.,  
scribe visible.  
13", now 14" Cedar, alive, N. 29 3/4° W. 39.1 ft., scribe visible.  
Reset - Brass Cap in proper position.  
New BT's: 6" Cedar N. 36 1/2° E. 136.8 ft. mkd. T27S R4W S35 CS BT.

Section Corner to Sections 14 - 15 - 22 - 23. 130  
Found - 1959 County Surveyor's Brass Cap, firmly set & mkd. T24S R7W.  
We change Twps. & Range to "T27S R4W". See Ren. # 54.  
All BT's. alive & in good condition.  
The N. E. Bearing Tree will be removed, leaving:  
39" B. Oak S. 89° E. 135.4 ft., shows scribe on unhealed blaze.  
New BT: 30" B. Oak N. 7° W. 252.6 ft. mkd. T27S R4W S15 CS BT.  
No other suitable trees within 400 ft. of corner.  
Note - This corner lies on hillside sloping west, approx. 75' E. of road.  
Aug. 23, 1967

Milo E. Godfrey, Deputy Co. Surv.  
Wm. Stoffel - M. Stone - M. Darby  
April - May 1964  
C. S. File No. 53/33

Vernon "Ray" Tracy  
Jack Heritage & E. West  
August, 1967  
C. S. File No. 53/33

SEE REN # 140  
140