

Douglas County Surveyor's Record of  
Government Corners Renewed

T 27      T.S.      R 4      R.W.W.M.

ROSE-CHAPMAN CO., EUGENE, ORE. 21881

141

1/4 Corner for Secs. 14, & 23. Ren.#53  
 Found - 1975 B.L.M., B.C. (properly mkd.) protruding 5" above ground.  
 1959 County Surveyor cap on 1-1/4" I.P. (properly mkd.) protruding 5" above ground.  
 BTs - Byron's C.S. cap fnd per B.L.M. Rec., N10°10'W., 19.1-ft. from the B.L.M. monument.  
 Byron's 4" fir (now 13" fir w/well healed dbl.blaze) fnd per Byron's Rec., N.1°30'E., 40.6-ft. - also bears N.3°W., 59.5-ft. from the B.L.M. monument.  
 Byron's 12" B.Oak (now 17" w/well healed dbl.blaze) fnd per Byron's Rec., S.83°W., 26.0-ft. - also bears N.61°W., 33.0-ft. from the B.L.M. mon. --NOTE-- This tree's scribing is for the wrong section.--  
 10" oak w/nearly healed blaze bears N.74°W., 30.6-ft. (B.L.M. Rec., 30.4-ft.)  
 8" oak w/ partially healed blaze bears S.47-1/2°W., 31.5-ft. (B.L.M. Rec., S.42°W., 31.0-ft.)  
 No evidence of original corner or accessories found.  
 Comments- Byron clearly states on survey M 14-42 that he single proportioned in the Sec. cor. for Secs. 15, 14, 22, & 23. B.L.M. properly proportioned S.1/4 Sec.14, & W.1/4 Sec.23. in 1975.  
 Set - We cut off Byron's 1-1/4" I.P. & place a yellow plastic cap inside pipe which is stamped: "DOUG.CO.SUVEYOR" (sic) 2/84

142

1/4 Corner for Secs. 22, & 23. Ren.# 55  
 Found - 1975 B.L.M., B.C. (properly mkd.) on a 2-1/2" I.P., protruding 5" above ground.  
 1959 County Surveyor cap on a 1-1/4" I.P. (properly mkd.) protruding 10" above ground.  
 BTs - Byron's C.S. cap is N.3-1/2°W., 18.9-ft. from the B.L.M. mon. (B.L.M. Rec. is N.1°30'E., 19.1-ft.)  
 Byron's 5" fir (now 12" w/well healed dbl.blaze) bears S.73°E., 52.5-ft. from Byron's cap (B.L.M. Rec., 52.1-ft.), & N.85-1/2°E., 49.3-ft. from the B.L.M. monument.  
 Byron's 12" fir (now 16" w/well healed dbl.blaze-and with the face oriented S.50°E.) Fnd.per B.L.M. Rec. from Byron's cap, N.46°W., 23.8-ft. - also bears N.26°W., 39.6-ft. from the B.L.M. corner.  
 B.L.M.'s 9" fir (now 10" w/well healed blaze) fnd per B.L.M. Rec. from B.L.M. corner, S.20°E., 15.2-ft.  
 B.L.M.'s 8" fir w/well healed blaze bears N.70°W., 20.2-ft. from the B.L.M. corner - (B.L.M. Rec., 19.8-ft.).  
 Evidence of thorough search by B.L.M.  
 NOTE - Byron incorrectly proportioned this corner in 1959 per survey M 14-42. B.L.M. correctly proportioned this corner in 1975.  
 Set - We cut cap off Byron's 1-1/4" I.P. & place a yellow plastic cap inside pipe which is stamped: "DOUG.CO.SUVEYOR" (sic) 2/84

143

1/4 Corner for Secs. 15, & 16. Ren.#105.  
 Fnd - Properly marked Co. Surveyors Office B.C. Ren.#39.  
 BTs - Orig. 10", now 20" rotted B.Oak snag 8-ft. high, no blaze visible, bears N.25°E., 13.0-ft. (Rec. 11.9-ft. is to face).  
 23" fir, now dead, w/partially healed dble.blaze w/ scribing visible "1/4 S15 CS BT", bears S.76°E., 13.0-ft. per Ren.#39.  
 20" fir, now 20" stump, 3-ft. high, no blaze visible, bears S.76°W., 18.0-ft. per Ren.#39.  
 19" B.Oak, now 22" snag 7-ft. high w/ scribing visible: "1/4 S15 CS BT", bears N.44°E., 38.5-ft. per Ren.#105.  
 25" B.Oak, now a depression in ground, bears N.23°W., 65.2-ft. per Ren.#105.  
 No evidence of Orig. 16" oak was found.  
 New BTs- 6" madrone, bark scribed: "1/4 S15 CSBT" bears S.69°E., 48.0-ft.  
 4" madrone, bark scribed: "1/4 S16 CSBT" bears S.72-1/2°W., 35.9-ft.  
 Note: See file for sketch and comments. 2/84

L. E. Monrean, Deputy Douglas County Surveyor  
 Douglas County Surveyors Office  
 Janet Lundeen, Randy Smith  
 Feb. 10, 1984  
 C.S. 62/16

Randy Smith, Deputy  
 Doug. Co. Surveyors  
 Office  
 Stephen Flause  
 February 28, 1984  
 C.S. 62/16