

Douglas County Surveyor's Record of
Government Corners Renewed

27

T. S.

5

R. W. W. M.

25

CORNER SOUTH SIDE OF SECTION 31

Set from original bearing trees by driving $\frac{3}{4}$ " x 36" round Iron Bolt for corner. Marked new bearing trees as follows

- Forked Fir 14" dia. bears N.56°E., 18.6 ft.
- White Oak 16" dia. bears N.52°W., 20.5 ft.

26

CORNER NORTHSIDE SECTION 6 T.28S.R.5W.

Set Corner from one original B.T. by driving $\frac{3}{4}$ " x 36" round Iron Bolt in ground. Marked new bearing trees as follows

- Fir 14" dia. bears S.22°15'E., 120.3 ft.
- White Oak 8" dia. bears S.46°45'W., 17.3 ft.

27

CORNER TO SECTIONS 31 and 32. ON S. BDKY OF TWP.

Found one original bearing tree other gone. Set corner from one B.T. by driving $\frac{3}{4}$ " x 36" round Iron Bolt for corner from which

- Fir 24" dia. bears N9°E., 11.4 ft. New B.T. 89-A
- Fir 30" dia. bears N.70°45'W., 65.3 ft. Old B.T.

28

CORNER BETWEEN 31 and 32.

Found one original bearing tree almost gone from which the corner was set. A stake from which new bearing trees are as follows

- Pine 24" dia. bears S36°45'W., 18.0 ft.
- Fir 12" dia. bears S.54°E., 22.0 ft.

29

CORNER BETWEEN SECTIONS 30, 29, 31, and 32.

Found $\frac{3}{4}$ " Iron Pipe at corner and two original bearing trees with scribe marks visible. Marked four new bearing trees

- White Oak 16" dia. bears S.76°45'W., 77.2 ft.
- White Oak 12" dia. bears N.40°30'W., 57.3 ft.
- White Oak 24" dia. bears S.5°30'E., 71.5 ft.
- White Oak 16" dia. bears N.17°00'E., 98.9 ft.

30

CORNER BETWEEN 30 and 31.

Found Iron Pipe by old corner post. One original bearing tree other gone.

31

CORNER BETWEEN 19 and 24. (R.6: R.5)

As this corner was lost I set it in by proportional measurement by setting $\frac{1}{2}$ " x 30" Iron Pipe 6" under ground in alley of block 57 City of Roseburg from which the intersection of alley with Mosher Street center line bears S.27°E. 170.92 ft. No tree near.

32

MEANDER CORNER BETWEEN SECTION 19 and 24 R.5 and 6 W.

An Iron Pipe set for corner. Old B.T.s not cut out as they are in owner yard, Washington Hughes.

33

MEANDER CORNER BETWEEN SECTIONS 18 and 13. R.5 and 6 W.

All indication of corner gone. Corner, $\frac{5}{8}$ " x $42\frac{1}{2}$ " Iron Rod set by proportional measurement, 4.8 ft. south of the South rail S.P.R.R. A channel Iron $1\frac{1}{2}$ " x 16" x 14" in ground under right of way fence. A bridge bears N.16°30'W., 62 feet about 455 feet from B.C. R.R. curve left north of cut on R.R.

- A White Oak 14" dia. bears S.60°30'W., 117.4 ft. marked M.P. C.S. B.T.

34

COR. BETWEEN SECS. 14 & 15

Set $\frac{1}{2}$ " Steel Bar with hook on upper end. mkd,
B. O., 30" diam. bears N 84° 30' E 318.4 ft.
W. O., 19" diam. bears S 66° W 75.7 ft.

1934, 1937, 1938
On S.E.R.A. Project
Glende Grocker
J. H. Wolford
Arthur Boyer
B. A. Lane

1934
J. H. Wolford
B. A. Lane
P. D. Wolford
Ben B. Irvine
1934
N. E. Richardson
B. A. Lane

1935
Frank Cain
B. A. Lane
N. E. Richardson

H. L. Eppstein
Dec. 1921

Fd. O.K. by H. Pilske June 22 M 90-22

Fd. Book 8/90 M112-12

Vol. 4 Page 50 to 58 inc.

Vol. 4 P. 51

CS File 4/23

RENEWED, SEE CORNER NO. 86

RENEWED, SEE CORNER NO. 89-A

RENEWED, SEE CORNER NO. 112

RENEWED, SEE CORNER NO. 138

RENEWED, SEE CORNER NO. 78

RENEWED, SEE CORNER NO. 70

RENEWED, SEE CORNER NO. 115

RENEWED, SEE CORNER NO. 80