

Douglas County Surveyor's Record of
Government Corners Renewed

27 T. S. 5 R. W. W. M.

James W. Byron
M. Godfrey
J. Fee
June 14, 1957
C. S. File No. 47/200

RENEWED, SEE CORNER NO. #155 67
 $\frac{1}{4}$ Section Corner to Section 19 and 30.
 Found - Original S.E. BT. (Now 30 inch W. Oak). I open & find good scribing "BT".
 Also find parts of rotted oak stump that checks for bearing & distance
 to N. E. BT.
 Set Brass Cap at corner marked, County Surveyor's Office, 1957 $\frac{1}{4}$ S $\frac{19}{30}$ T27S, R5W
 Note: Corner is 5.5 ft. South of East West Fence Line.
 Blaze & Scribe: 12 inch W. Oak S.55°W 47.4 feet $\frac{1}{4}$ S 30 CS BT.
 10 inch W. Oak N.28 $\frac{1}{2}$ °E 29.1 feet $\frac{1}{4}$ S 19 CS BT.

Section Corner to Section 19, 30, 24, & 25. SEE ALSO REN #20 R 6W R5W 68
 Set Brass Cap in corner marked County Surveyor's Office, 1957 $\frac{24}{25}$ | $\frac{19}{30}$ T 27S
 Set flush with ground surface.
 18 inch High brick wall bears S.34°27'50"E. 1.4 feet and S.55°30'10"W. 0.21.

$\frac{1}{4}$ CORNER - SEC. 6, T.21, R5 & SEC. 7, T.21/R.6W. 69
 Found Machine Gun Barrel at Corner. REN. #39
 Also Found White Oak 20" diam. S.83°W. 77.7 ft. showing good scars.
 Did not chop open.
 No trace of S. E. Tree marked by Irving in 1934 could be found. FD OK
Nov. 1980
B. SHAWNEE
R. M. 3-38
 Blaze & Scribe: 6" Madrone N.60°E. 29.7 ft. Scribe Madrone $\frac{1}{4}$ S6 CS BT"
 Did not set new Corner; Barrel in good condition.

$\frac{1}{4}$ Section Corner to Sections 13 & 18. 70
 Found - Brass Cap at Corner as set, 1953, (See C.S. File 45/150) REN. #57
 Both BT's. have been bulldozed out.
 I measure record distance South from Section Corner $\frac{12}{13}$ | $\frac{7}{18}$ Checks O.K.
 I Set PK Nail 1' above ground in Power Pole N.2°W. 228.5 ft. (West Pole)
 I Set PK Nail in top of Fence Corner Post N.12°E. 248.0ft.
 Var. 20 $\frac{1}{2}$ °

$\frac{1}{4}$ Section Corner to Sections 23 & 24. 71
 Found - Brass Cap. - SEE REN. NO. 62 AND NO. 4.
 Ben B. Irving BT., now 16" B.O., shows good scar, recorded
 S.78°27'W. I find should be N.81°W. 95.0 ft.
 B.B.I. BT., now 12" B.O. shows good scar, record S.21 $\frac{1}{2}$ °E., I find
 should be S.25°E. 13.0 ft. #735

Section Corner to Secs. 25 & 36, T27S R5W, & Secs. 30 & 31, T27S R4W. 72
 Found - Orig. 11", now 20" B.O., I open & find good scribing "S36"
 S.37 $\frac{1}{2}$ °W. 29.7 ft.
 Orig. 10", now 24" B.O. N.59°W. 52.1 ft., dist. should be
 58.7 ft., shows scar, I do not open.
 Stump Holes that check Original N.E. & S.E. BT's.
 Set Brass Cap at Corner Mkd: County Surveyor's Office, 1959

| | | | |
|-----|-----|-----|-----|
| | S25 | S30 | |
| R5W | S36 | S31 | R4W |

 T27S
 New BT's:
 11" W. Oak bears N. 0 $\frac{1}{2}$ °W. 56.0 ft. scribed S25 T27S R5W CS BT.
 6" W. Oak bears N.75°W. 33.4 ft. scribed S25 CS BT.
 Rescribe Orig., now 20" B.Oak S.37 $\frac{1}{2}$ °W. 29.7 ft. S36 T27S R5W CS BT
 No Trees near to S.E. & N.E.
 FD OK. 4-22-80

$\frac{1}{4}$ Section Corner to Section 25, T27S R5W, & Sec. 30, T27S, R4W. 73
 Found - Orig. 12", now 24" B.O. S.20°W. 82.5 ft., I open & find good
 scribing "S".
 No trace of Original S.E. BT. found.
 Set Brass Cap at Corner Mkd: County Surveyor's Office, 1959
 $\frac{1}{4}$ S25/S30 T27S

| | |
|-----|-----|
| R5W | R4W |
|-----|-----|

 New BT's: 14" R.Fir bears N.21°E. 19.5 ft. scribed $\frac{1}{4}$ S30 CS BT.
 11" R.Fir bears S.72°W. 24.7 ft. scribed $\frac{1}{4}$ S25 CS BT.
 Note - N.S. Fence 4 ft. West.

James W. Byron
M. Godfrey
S. Bilow
Jan. 16, 1958
C.S. File 49/62

James Byron, Deputy
M. Godfrey
S. Bilow
April 7, 1958
C.S. File 49/74

James Byron, Deputy
Milo Godfrey
S. A. Bilow
Jan. 23, 1959
C. S. File No. 49/130

H. Collison, Jr.