

Douglas County Surveyor's Record of
Government Corners Renewed

27 T. S. 5 R. W. W. M.

HOKE-CHAPMAN CO., EUGENE, ORE. 21881

1/4 Section Corner to Section 31, T27S R5W, & Sec. 36, T27S R6W.
Found - Both BT's. as recorded by Boyer: **REN #22** **74**

Orig. 20", now 40" Oak Snag, lower section previously opened, shows good scribing "BT".

I open each of Boyer's BT's. & find good scribing.

The NW. BT. checks bearing & distance.

The SW. BT. should be S.56°E. 30.4 ft.

Note - A East-West Fence is 2 ft. South of Corner.

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1959

1/4 S36/S31R5W T27S
R6W

New BT's: 7" W. Oak bears S.69°W. 27.8 ft. scribed 1/4 S36 CS BT.

12" W. Oak bears S.7 1/2°E. 13.0 ft. scribed 1/4 S31 CS BT.

James W. Byron
Milo Godfrey
S. A. Blilow
April 13, 1959
C.S. File 49/145

FD. O.K. by:
H. PIESKE
JUNE, 1982
see M 90-22
Fd 8/90
M112-12

Section Corner to Sections 30 & 31, T27S R5W, & Secs. 25 & 36 T27S R6W.
Found - 3/4" Bolt at Corner & 2 BT's. set by Crocker: **REN #21** **75**

6" B. Oak, now 10", S. 2°E. 41.5 ft., showing good scar, did not open.

18" W. Oak, now 24", N. 1°W. 146.0 ft., showing good scar, did not open.

Clump of Laurels bears N.87°E. 158.5 ft., did not find one Mkd. for BT.

Mkd. new trees as follows: 9" W. Oak N.84°E. 42.0 ft., blaze & scribe "T27S R5W S30 CS BT."

(7/71-3/4" Bolt Missing -
Set 5/8" I. Rod, See
Map M 42 - 50 (Garrett)

10" B. Oak S.41 1/2°W. 95.4 ft., blaze & scribe "T27S R6W S36 CS BT."

SEE CORNER NO. #157

James W. Byron, Deputy
Milo Godfrey
S. A. Blilow
June 23, 1959
C.S. File No. 49/145

Section Corner to Sections 20, 21, 28 & 29. **76**

Found - Orig. 12", now 26" W. Oak N.84°E. 6.6 ft., I open & find good scribing "21".

Orig. 15", now 30" W. Oak N.13°W. 44.9 ft., shows good scar, I open center, rotted, no scribing found.

Stump Holes that check for S. E. & S. W. BT's.

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1959

S 20	S21	T27S R5W
S29	S28	

New BT's: 7" W. Oak bears N.24°W. 20.2 ft. scribed S20 T27S R5W CS BT.

24" B. Oak bears S.37°W. 14.8 ft. scribed S29 T27S R5W CS BT.

6" W. Oak bears S.41°E. 14.9 ft. scribed S28 CS BT.

8" W. Oak bears N.28°E. 27.6 ft. scribed S21 T27S R5W CS BT.

FD. O.K. 4-22-80 FD. 5/21/81 R. THOMPSON M 24-58

James W. Byron, Deputy
Milo Godfrey
C. Putnam
July 2, 1959
C. S. File No. 49/62

Section Corner to Sections 15, 16, 21 & 22. **77**

Found - Orig. 20", now W. Oak, shows good scar, center rotted, S. 6 1/2°W. 279.8 ft.

Orig. 14", now 22" Oak Stump, center rotted, shows good reverse scribing "S 2" N.88 1/2°E. 623.7 ft.

No evidence of Orig. S.E. BT.

Note - Corner is in Field. I set Witness Corner 8' east of Section Corner.

Set Brass Cap in N. S. Fence Line ~~about~~ 8.0 ft. East of Sec. Cor., Mark Wit. Cor. 8' West to Sec. Cor.

S16	S15	T27S R5W	County Surveyor's
S21	S22		Office, 1959

New BT's: 9" W. Oak bears S.85 1/2°E. 317.7 ft. W.C. S22 T27S R5W CS BT.

18" W. Oak bears S. 3° W 205.8 ft. scribed S21 W.C. T27S R6W CS BT,

No other BT's. near.

FD OK 3/91/77 G. LANGRITZ, Co. SURV. OFFICE C.S. #59/31

July 20, 1959
C.S. File 49/62

1/4 Section Corner to Sections 30 and 31. **78**

Found - 3/4" Iron Pipe at Corner. - **REN. No. 30** **#173**

Orig. 12", now 30" W. Oak N.6 1/2°E. 299.6 ft., shows old face, now rotted. No scribing found, checks bearing and distance.

No trace of Orig. S. E. BT. found.

Also found now 15" W. O. bears N.6°W. 68.7'. Shows good scribing "S36 CS BT". Scribed about 30 years ago. Probably scribed 1934.

RE-RENEWED

Nov. 10, 1959
C.S. File 49/62

O.K. by:
H. PIESKE
JUNE 1982
see M 90-22