

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 27 S. T. S. R. 5 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Byron & Godfrey, Deputies  
Nov. & December 1963  
C. S. File No. 53/38

90

N. E. Corner D. Barnes D.L.C. No. 49.  
Found -  $\frac{1}{2}$ " I.P. (bent over) set by Boyer in 1938, See Ren. No. 12.  
(Straightened Pipe).  
Stump of 15" Bl. Oak S.84°E. 11.3 ft., opened & fd. scrbing, "BT".  
Stump of 8" W.Oak S.27°W. 30.0 ft., shows good scar. Did not open.  
No trace of Original Bearing Tree.  
New BT's: 9" W. Oak S.22°E. 58.0 ft. Mkd: N.E. DLC 49 CS BT.  
9" W.Oak N.49°E. 101.0 ft. Mkd: N.E. DLC 49 CS BT.  
Renewed 11/21/63 - Godfrey.

91

$\frac{1}{4}$  Corner to Sections 28 and 33.  
Found - Both Orig. BT's. Orig. 12", now 20" B.Oak S.33°E., not S.23°E.  
9.2 ft., shows good scribe marks.  
Orig. 12", now 24" B.Oak N.13°E.9.2 ft., shows good scars.  
(Each BT has rotted center).  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963  $\frac{1}{4}$  S28 T27S R5W  
Note - Corner at N. - S. Fence. S33  
New BT's: 14" R.Fir bears S.68°W. 39.5 ft. scribed  $\frac{1}{4}$  S33 CS BT.  
12" B.Oak bears N.75°W. 41.5 ft. scribed  $\frac{1}{4}$  S28 CS BT.  
Ren. 12/9/63 - Byron

FD. 5/21/84 R. Thompson M96-58

FD. O.K. 4.22.80

92

Township Corner T26S  
R5W  $\frac{S36}{S1}$  |  $\frac{S31}{S6}$  R4W  
T27S

Found - Corner Tree - D.Fir, now 24", in Fence Corner, Fences E.N. & N.W.  
 $\frac{1}{2}$  1/8" Steel Axle N.55°E. 3 ft. from Corner Tree. (See Ren. #83)  
30" Fir Stump N.87 $\frac{1}{2}$ °W. 22.1 ft., opened & fd. good scribing "36".  
28" Fir Stump S.62°W. 21.8 ft., shows good scar.  
26" Fir Stump S.30°E. 31.0 ft., shows good scar.  
No trace of N.E. Bearing Tree.  
New BT's: 11" D.Fir N.83°E. 28.8 ft. Mkd: T26S R4W S31 CS BT.  
9" D.Fir N.16°W. 41.3 ft. Mkd: T26S R5W S36 CS BT.  
4" Madrone S.36°E. 51.4 ft. Mkd: S6 CS BT.  
No trees available S.W. of Corner.

93

$\frac{1}{4}$  Corner to Sec. 1, T27-5W. & Sec. 6, T27-4W.  
Found - 42" W.Oak S.53°E. 92.4 ft., cut open & fd. good scribing "BT".  
Stump Hole & Small pieces of Oak N.2 $\frac{1}{2}$ °W. 92.4 ft.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1964  
T27S R5W  $\frac{1}{4}$  S1/S6 R4W.  
New BT's: 8" W.Oak N.81°W. 22.5 ft. Mkd:  $\frac{1}{4}$  S1 CS BT.  
9" W.Oak S.75°E. 28.6 ft. Mkd:  $\frac{1}{4}$  S6 CS BT.

94

Section Corner to Sections 35 & 36, T27-5W. & Secs. 2 & 1, T28-5W.  
Found - Axle (with flange on Top) at Corner. - See Ren. #58 #158  
8" W.Oak S.34 $\frac{1}{2}$ °W. 63.3 ft., shows good scar, tree in good cond.  
5" W.Oak N.75 $\frac{1}{2}$ °W. 113.5 ft., shows good scar, tree in good cond.  
12" Bl.Oak S.60 $\frac{3}{4}$ °E. 59.5 ft., scribing "8" visible, Tree in good cond.  
9" Pine N.86°E. 185.3 ft. is dead & doan, scribing "BT" still  
visible on stump, stump rotting badly  
New BT: 30" Pine N.6°E. 122.2 ft. Mkd: T27S R5W S36 CS BT.  
Note - Corner monument is approx. 6" below ground surface in road ditch  
near South Deer Creek Grange Hall.  
C.S. 53/38 - 3-22-71  
F.O.K. V.E.T.

95

$\frac{1}{4}$  Corner Sec. 35, T26-5W. & Sec. 2, T27-5W.  
Found - Stump of W.Oak S.81°W. 321.4 ft., opnd. & fd. good scribing.  
48" Bl.Oak N.48°W. 87.1 ft. Faint scar visible. Did not open.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T26S  $\frac{1}{4}$  S35 R5W  
Office, 1964 T27S S2  
New BT's: 9" W.Oak S.20°W. 58.0 ft. Mkd:  $\frac{1}{4}$  S2 CS BT.  
12" W.Oak N.79°W. 85.6 ft. Mkd:  $\frac{1}{4}$  S35 CS BT.  
Note - Bearings not true for this corner, read with compas set  
for Var. 19° 30' E.

Milo E.  
Godfrey &  
Crew  
March 31,  
1964  
C. S. File  
No. 49/125

Milo E. Godfrey, Deputy  
Wh. Stoffel & Mike Stone  
January 1964  
C. S. File No. 53/33