

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 27. S. T. S. E. 6 W. R. W. W. M.

Sec. Corner between Secs. 7 & 18, T27-5W. & Secs. 12 & 13, T27-6W. 116  
Set by proportional measurement by placing 10" x 10" x 14" Sandstone, 12" underground, 3" under road ditch. Mkd. X on top, C. S. with 2 notches on N. face, from which S. W. corner of Lot 15, Fruitvale bears S.1°58'E. 1026.1 feet. N.E. corner of D.L.C. #56, T.27S R6W. bears S.28°24'E. 857.7 feet.

1/4 Corner to Sections 12, R6W. & Sec. 7, R5W. 117  
Set by proportional measurement by driving machine gun barrel 10" underground, tincollar, one brick on top three bricks placed around, 4" x 4" x 48" post, 24" in ground marked 1/4 S on North Face, C. S. on South face, S. 7 on East face and S.12 on West face from which N. E. Corner D.L.C. No. 37 T.27S R5W. bears N.75°12'E. 924.9 feet.

Sec. Cor. to Sections 1 & 12, T27-6W. & Secs. 6 & 7, T27-5W. 118  
Set by proportional measurement by driving 5/8" x 42" Iron Bolt, 15" under ground with Oak Chank 4" x 6" on top, from which A White Oak 12" diam. bears N.40°E. 75.6 ft. mkd: T27S R5W Sec. 6 CS BT.  
A White Oak 20" diam. bears N.46°W. 132 ft. mkd: T27S R6W/S1 CS BT.  
No trees near. 135

Township Corner - 119  
T26S  
R6W S36|S31 R5W  
S 1|S 6 Set from stump, scribe visible, T27S. in S.E. and stump hole in S.W.  
Set - 1" x 48" Pipe, 42" in ground with pile of Rock, 20" sq. base, 12" high from which:  
W.Oak 10" diam. bears S.55°W. 27.8 ft. mkd: T27S R6W S1 CS BT.  
W.Oak 6" diam. bears S.14°E. 15 ft. mkd: T27S R5W S6 CS BT.  
W.Oak 6" diam. bears N.73°E. 48 ft. Mkd: T26S R5W S31 CS BT.  
W.Oak 10" diam. bears N.50°W. 74.1 ft. Mkd: T26S R6W S36 CS BT.

N. W. Corner D. L. C. No. 55. 120  
Reset - Co. Surveyor's Brass Cap at Corner; Ren. No. 66.  
Cap had been pulled out - 4" X 4" Sq. Oak Stake & Mound of Stones are still at Corner.  
All Bearing Trees mentioned in former renewal, No. 66 and No. 30, are still in good condition, as follows:  
6" White Oak N.20 1/2°W. 87.5 ft. (1960 renewal #66).  
24" White Oak N. 1°E. 209.2 ft. (1940 renewal #80).  
24" White Oak N.9 1/4°E. 231.7 ft. (Stewart's renewal, apparently not recorded).

Mst. Easterly S.E. Cor. D.L.C. No. 55. 121  
Found - 3/4" Iron Bolt with square head. See Ren. No. 22.  
20" W. Oak S.49 1/2°W. 97.0 ft., shows very plain axe scar. Did not open.  
24" W. Oak S. 5° W. 116.5 ft., shows very plain axe scar. Did not open.  
Set - Brass Cap alongside I. Bolt Mkd: County Surveyor's Office, 1964  
T27S R6W E SE DLC 55  
Note - Did not mark any new trees. Both BT's. mkd. by Eppstein in 1935 are alive & in good condition.  
No trace of Original BT. could be found.

South 1/4 Corner Section 36 only. 122  
Found - 14" Bl.Oak N.11°W. 30.4 ft., opened & found good rev. scrbing. Did not find N. E. Tree.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1964  
T27S R6W 1/4 S 36  
New BT's: 13" Bl.Oak N.50°E. 34.9 ft. Mkd: 1/4 S36 CS BT.  
17" Bl.Oak N.77°E. 25.5 ft. Mkd: 1/4 S36 CS BT.  
Note - Corner lies on very steep N.W. slope above S. Umpqua River. (This corner is on N. Line T28S R6W).

Ben. B. Irving  
N. E. Richardson & Ernest Brown  
1934  
Vol. 4 Pg 50-58

#154  
Milo E. Godfrey,  
Deputy  
Wm. Stoffel  
Mike Darby  
Mike Stone  
March 31, 1964  
C. S. File  
49/79

Milo E. Godfrey, Deputy  
Wm. Stoffel - M. Stone & M. Darby  
May 1964  
C. S. File No. 49/79

RE-RENEWED SEE CORNER NO.

RE-RENEWED SEE CORNER NO.