

Douglas County Surveyor's Record of
Government Corners Renewed

T 27 T. S. R 6 R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

R. Ware L.S.#1005
For: C. Chapman
Dec. 1989
M 109-41

Center 1/4 Corner for Section 20
CORNER REPORT ONLY

186

Found - 3/4" iron pipe. (See M 35 - 39)
12" Oak bears S.68°W., 13.8 ft. scar showing. (Gee's record 14")
8" Oak bears N.51°15'E., 12.8 ft. scar showing. (Agrees exactly
with Gee's record, M35-39)

12/89

Section Corner for Secs. 5 and 4; and Secs. 32 & 33 of T.26-6

187

Found - A 3" x 8" x 24" stone set on end, top approx. 6" below ground.
(Rec. 2" x 8" x 18" in Ren. #105. Top 9" is broken off and
fractured into 3 pieces. (Probably broken when field was
plowed) No marks found on stone. Stone set in Ren. #18.
A 2 1/2" dia. DCSO brass cap on a 1 1/4" O.D. x 36" long split end
iron pipe is found laying on top of ground approx. 4 ft. south
of found stone. Top of BC/IP shows evidence of being hit by
a plow. Ren. #105

(Brg. & Dist. taken from top center of stone):

A bent metal fence post is found along east edge of stone.
(Source unknown)

10" now 20" dia. Myrtle with healed scars, we open in three
places, no blazes or scribing found, bears N.54 1/4°W., 113.7 ft.
(Rec. N.51°W., 113.7 ft.) Possible Northwest BT from Ren. #105.
No other original or Renewal BTs found.

Set - A 5/8" x 30" long iron rod is set 2 1/2 ft. below ground at ref-
erenced position of found stone. Stone is reset on end on top
of 5/8" I.R. at referenced out position. DCSO BC/IP is reset
0.2 ft. west of stone, along west edge of stone. The marks
"RESET 1990" are added to brass cap. Stone is set 4" below
ground, DCSO BC/IP protrudes 2" above ground.

New BTs - (Brg. & Dist. taken from top center of stone)
12" Cottonwood double blazed and scribed "T27S R6W S4 CS BT"
bears S.7 1/2°E., 276.1 ft.
28" Myrtle double blazed and scribed "T27S R6W S5 CS BT" bears
S.84 1/2°W., 301.8 ft.
18" Cottonwood double blazed and scribed "T26S R6W S32 CS BT"
bears N.20°W., 134.0 ft.

2/21/90

188

Section Corner for Secs. 9, 10, 15 and 16

Found - A 2 1/2" dia. DCSO brass cap on an iron pipe 15" below ground.
1984 renewal. Ren. #169
40" now 52" dia. B. Oak with a fully healed single blaze, bears
S.82 1/2°W., 185.0 ft. (agrees with record) Ren. No. 21
Southeast corner of concrete basement, bears N.70°W., 156.6 ft.
(Rec. N.68°W., 156.7 ft.) Ren. No. 21
18" now 29" dia. Sequoia with fully healed double blazes bears
S.70°W., 92.7 ft. (agrees w/record) Ren. No. 169

New Accessories:

5/8" iron rod with yellow plastic cap marked "Baughman Tech.
Serv.) protrudes 4" above ground, bears S.53°E., 194.6 ft.
3/4" I.D. iron pipe protruding 7" above ground bears S.4 1/4°E.,
394.5 ft.

No BO's or BTs in Northeast quadrant.

2/28/90

Section Corner for Secs. 16, 17, 20 and 21

189

CORNER REPORT ONLY

Found - A 1960 DCSO 2 1/2" dia. brass cap on a 1 1/4" O.D. iron pipe which
protrudes 18" above ground. Ren. #78
A 1 1/2" O.D. iron pipe protrudes 11" above ground bears S.62°E.,
0.7 ft. from DCSO BC/IP.
14" now rotted madrone stump of indeterminate size with a cluster
of new madrones growing from stump roots, bears N.80 1/2°E., 158.4'
(Orig. rec. N.88 1/2°E., 158.4 ft. - Ren. #78, N.83°E) Poss. Orig. BT
9" now 20" dia. B. Oak with a previously opened blaze, no scribing
visible bears S.47 1/2°E., 81.6 ft. (Orig. rec. S.45 1/4°E., 86.5 ft.
Ren. No. 78 S.45 1/4°E., 82.5 ft.) Orig. BT.
6" now 21" dia. W. oak with a fully healed single blaze, bears
N.41 1/2°W., 55.4 ft. (agrees with rec.) Orig. BT.

Douglas County
Surveyors Office
Randall Smith
Stephen Flause
Feb. 21, 1990
C.S. 64/5

Douglas County Surveyors Office
Randall Smith
Stephen Flause
C.S. 64/6

Feb. 28, 1990

March 1, 1990