

Douglas County Surveyor's Record of
Government Corners Renewed

27 T. S. 6 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

91

1/4 Section Corner to Sections 7 and 18.
Found - Orig. 9", now 14" B.Oak N.43 3/4° W. 27.7 ft. We open
& find good scribing "T".
Orig. S. E. BT. down & out of position.
Set Brass Cap at Corner Mkd: County Surveyor's 1/4 S 7 T27S
Office, 1961 1/4 S18 R6W
Note - N. S. & E. Fences.
New BT's: 16" B.Oak bears S.10°W. 15.5 ft. scribed 1/4 S18 CS BT.
18" R.Fir bears N.39°W. 26.0 ft. scribed 1/4 S 7 CS BT.

FD. S. C.
1/12/88
M 86-17
R. W. W. M.

92

1/4 Corner to Sections 18 and 19.
Found - Orig. 13" W.O. N. 5°E. 23.1 ft. We open & find good
reverse scribing "BT".
S. W. BT. not found.
Set Brass Cap at Corner Mkd: County Surveyor's Office, 1961
1/4 S18 T27SR6W
1/4 S19
Four Way Fence Intersection.
New BT's: 7" W.O. bears S.61°E. 24.6 ft. scribed 1/4 S19 CS BT.
5" W.O. bears N.12°E. 47.6 ft. scribed 1/4 S18 CS BT.

93

1/4 Section Corner to Sections 22 and 27.
Found - 2" Iron Pipe at Corner & at North & East Fence Corner.
No Orig. BT's. found. This pipe used for corner for
years. See C. S. File No. 32/240, 33/49 & M 19 - 20.
New BT's: 10" B.Oak bears N.43 1/2° W. 17.6 ft. scribed 1/4 S22 CS BT.
No trees near to South.

RE-RENEWED

#191

94

1/4 Corner to Sections 20 and 21.
Found - B. Oak, now 24", N.43 1/2°E. 72.6 ft., dead by standing,
cut open & found good scribing "BT".
Old Stump bears S.83°W. (instead of S.76°W.) 24.4 ft.,
no evidence of scribing.
Set Brass Cap Mkd: County Surveyor's Office, 1961
1/4 S20/S21 T27S R6W.
New BT's: 10" B.Oak N.32°W. 18.3 ft. Mkd. 1/4 S20 CS BT.
12" W.Oak N.16 1/2°E. 28.1 ft. Mkd. 1/4 S21 CS BT.
Corner is in old wooden fence line & 2 ft. South of present
wire fence running East & West.
A Fence Corner - Fences E. W. & N. Lies West of corner a
distance of 94 feet.

FD. OK 12/88
S. GOSSEN
M 86-17

95

1/4 Corner to Sections 23 and 24.
Found - Iron Pipe & Rock called for in Earlier Renewal. # 4
Rotten Fir Snag N.78 1/2°W. 7.3 feet.
Cedar N.26°E. 10.6 ft. is uprooted and down.
Set Brass Cap Mkd: County Surveyor's Office, 1961
alongside Rock & Pipe - 1/4 S23/S24 T27S R6W
New BT's: 6" B.Oak N.79°E. 40.6 ft. Mkd: 1/4 S24 CS BT.
10" Madrone N.10°W. 62.0 ft. Mkd 1/4 S23 CS BT.

96

Section Corner to Sections 20 - 21 - 28 - 29.
Found - 2 1/2" Galv. Iron Pipe Set By Stewart in 1922 in good cond.
All of Stewart's BT's. as follows: REN # 7
8" W.Oak, now 14", N.45°E. 50 ft. in good condition,
shows good scar.
24" W.Oak, now 24 1/2", S.67°E. 78 ft. (Orig. BT) nearly dead,
face rotted out.
18" W.Oak, now 18", N.30°W. 67.8 ft. Tree appears to
be dying, shows good scar.
18" W.Oak S.37 3/4°W. 88.4 ft., dead & partly rotten,
(Orig. BT.)
Rotted Stumps in place of the Orig. N.W. & N. E. BT's.,
check bearing & distance.
New BT's: 6" W.Oak N.36°W. 7.5 ft. Mkd: T27S R6W S20 CS BT.
9" W.Oak S.75 1/2°W. 17.8 ft. Mkd: T27S R6W S29 CS BT.
11" W.Oak S.11°E. 22.5 ft. Mkd: T27S R6W S28 CS BT.
Did not Set Brass Cap.

FD. 7/84
D. BENTE
M 97-31

FD. OK 12/88
S. GOSSEN
M 86-17

James W. Byron, Deputy County Surveyor
Milo Godfrey
Clete Putnam
January 1961
C. S. File No. 49/79