

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 27 S. T.S. R. 8 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21887

North 1/4 Corner to Section 32, T27 $\frac{1}{2}$ S., R.8W.  
Found - 1961 Cadastral Brass Cap, properly marked.  
Orig. BT's: Cedar 22" diam. S.72 $\frac{1}{2}$ °E. 46 lks., scribe visible  
but now a shattered stump. #51  
Hemlock 40" diam. S.36°W. 107 lks., scribe not  
visible, now a stump.  
New BT: Scribed: 6" diam. YEW S.41°E. 17.7 ft. "1/4 S32 BT".  
All of Section 32 has been clear cut. There are no other  
trees suitable for bearing trees.

April 18, 1973

28

Howard W. Johnstone  
For: Rsbrg. Lbr.  
C.S. File No.  
55/286

North 1/4 Corner Section 2.  
Set - A 2" Pipe with a Brass cap, from which:  
10" Hemlock bears N.18°E. 3.0 ft. (Weyco tag & "W" nail)  
7" Hemlock bears N.77 1/2°W. 13.7 feet. ( " " " )  
8" Hemlock bears S.68 1/2°W. 2.0 feet. ( " " " )

29

By:  
Craig L.  
Templin  
For:  
Weyerhaeuser  
Co.  
C.S. File  
No.  
55/285

West 1/4 Corner Section 2. *FD OK By Ken Hoffman 2/94 M118-46 For: Lone Rock Timber*  
Set - 2" Pipe with a Brass Cap, from which:  
26" Fir bears S.56°W. 17.5 ft. (Weyco tag & "W" nail)  
26" Fir bears S.78°E. 34.3 ft. (Wyco tag & "W" nail)  
Distances are horizontal distances to the center of the tree  
& bearings were taken on the "W" nail in the base of each  
tree. Lines were blazed and marked with 2"x8" aluminum tags  
nailed to trees on the property adjoining Weyerhaeuser Co.  
and by red and white striped engineer's flagging on the prop.line.

March 1973

30

Sec. Cor. Sec. 1; Sec. 36, T26-8; Sec. 31, T26-7; Sec. 6, T27-7  
Found - 40" D.Fir stump, orig. BT, face badly burned, scribes  
"BT" vis., bears S.32°W., 54.8 ft.  
36" D.Fir stump, prob. orig. BT, badly burned and  
rotted, bears N.35°W., 59.0 ft. (rec. N.40°W.,  
61.4 ft.)  
36" Cedar stump, prob. orig. BT. I re-scribed "T26S  
R7W S31 BT", bears N.20°E., 78.0 ft. (rec. 67.3 ft.)  
Set - Brass cap mkd. T26S, R8W S36; T26S, R7W S31; T27S,  
R8W S1; T27S, R7W, S6.  
New BT's - 6" D.Fir, scribed "T26S, R8W, S36 BT", bears N.64°W.,  
55.4 ft.  
8" hemlock, scribed "T27S, R7W S6 BT" bears S.62°E.,  
24.7 ft.  
8" D.Fir, scribed "T27S, R8W, S1 BT" bears S.34°W.,  
114.4 ft.

32

1/4 Cor. for Sec. 1; and Sec. 36, T26-8.  
Nor original evidence found.  
Set - Brass cap mkd. T26S, R8W, S36; T27S, R8W, S1, 1/4 1973.  
BT's - 6" D.Fir, scribed "S1 1/4S BT", bears S.88°W., 3.1 ft.  
5" D.Fir, scribed "S36 1/4 BT", bears N.56°E., 8.0 ft.

33

Sec. Cor. Secs. 1 and 2; and Sec.s 35 & 36 of T26-8.  
Found - 3/4" I.R. (Weyerhaeuser survey, C.S. 55/285)  
36" fir stump, prob. orig. BT, rotten and burnt,  
bears S.30°W., 7.3 ft.  
Probable orig. fir BT, now mound of rotten wood, bears  
N.20°W., 31.0 ft.  
Set - Brass cap alongside I.R. mkd. T26S, R8W, S35, S36 T27S,  
R8W, S2, S1 1973.  
New BT's - 14" D. Fir, scribed "T26S, R8W, S36 BT", bears  
N.11°E., 16.5 ft.  
24" D.Fir, scribed "T27S, R8W, S2 BT" bears S.41°W.,  
19.6 ft.  
12" D.Fir, scribed "T26S, R8W, S35 BT", bears N.65°W.,  
33.3 ft.  
16" D.Fir, scribed "T27S, R8W, S1 BT", bears S.88°E.,  
29.0 ft.

Shaner Engineering  
for Hub Lumber Co. and Weyerhaeuser Co.  
Dec. 21, 1973  
M 49 - 49