

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 27 T. S. R 8 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

34

1/4 Corner for Section 4 and Sec. 33, T26-8.
Set - Brass cap mkd. T26S. R8W, WM 1/4 S33; T27S R8W WM 1/4 S4 1974.
from which a:
24" Douglas fir, I scribed "1/4S BT" bears N.13 W., 22.0 ft.
24" Douglas fir, I scribed "1/4S BT", bears S.35 W., 26.9 ft.
No original evidence found.

6/24/74

35

Section corner for Secs. 3 and 4, and Secs. 33 and 34, T26-8
Set - PK nail on the face of a 15 ft. high rock cliff from which a:
Brass cap, I mkd. Witness corner, South 3 ft. to T26S R8W S33
S34; T27S R8W S4 S3 1974, bears North, 3.0 ft.
14" Cedar, I scribed "T26S R8W S34 BT, bears N.13 E., 17.9 ft.
30" Douglas fir, I scribed "T26S R8W S33 BT", bears N.50 W., 108.0 ft.
18" Douglas fir, I scribed "T27S R8W BT", bears S.8 E., 26.0 ft.
16" Douglas fir, I scribed "T27S R8W S4 BT", bears S.18 W., 33.2 ft.
No original evidence found, Panther Creek lies 20 ft. North. Area has been
badly burned and corner area may have been badly eroded by Panther Creek.

6/24/74

36

1/4 Corne for Sec. 3 and Sec. 34, T26-8
Set - Brass cap mkd. T26S, R8W, WM 1/4 S34, T27S R8W WM 1/4 S3 1974.
from which a:
26" Douglas fir, I scribed "1/4S BT" bears N. 27E., 5.7 ft.
22" Douglas fir, I scribed "1/4S BT", bears S.8 1/2 E., 16.0 ft.
No original evidence found.

6/24/74

37

Section corner for Secs. 3, 2 and Secs. 34, 35, T26-8.
Found - 1 1/2" I.P. & Set Brass cap alongside mkd. T26S R8W WM S34, S35
T27S R8W WM S3, S2 1974 from which a:
60" orig. Douglas fir BT stump with partial face, bears S.25 E.,
42.2 ft.
6" Yew, possible BT, down and rotting, bears S.10 W., 29.0 ft.
36" D.Fir stump scribes vis., bears S.81 E., 36.5 ft.
8" D.Fir BT, no scribes on face, I scribed "T26S R8W S35 BT",
bears N.58 E., 18.6 ft.
10" D.Fir bt faced but no scribes vis., I scribed "T26S R8 W
S34 BT". bears N.68 W., 13.1 ft.
8" Madrone BT bark scribes vis., bears S.87 W., 17.6 ft.
8" Hemlock BT, faced but no scribes, I scribed "T27S R8W S2 BT"
bears S.77 E., 10.7 ft.
Badly burned post with scribes vis. wired to pipe. Last 4 trees
have "Weyco" tags and "W" nails in root collars.

6/24/74

38

1/4 Corner for Sections 3 and 4.
Set - Brass cap mkd. T27S R8W WM 1/4 S4 S3 1974 from which a:
74" Douglas fir original BT now fire scarred stump, bears S.9 E 194.0 ft
50" Cedar original BT badly burned stump with probable face, bears
S55 W., 214.0 ft. (Record, 150.5 ft.).
84" Douglas fir, original line tree, now badly burned stump, bears
South, 278.0 ft. (Record 334.0 ft.)
48" Douglas fir original line tree now badly burned stump, bears North,
214.0 ft. (record, 194.0 ft.)
Stream, 4 lks. wide, course NW, bears south, 625.0 ft. (record, 594.0 ft)
New BT's - 14" Douglas fir, I scribed "S3 1/4S BT" bears S4 E., 11.9 ft.
18" Douglas fir, I scribed "S4 1/4 S BT" bears N.31 W., 19.1 ft.

39

West 1/4 Corner for Section 19 only.
Found - A 12" Yew which bears N.70°30'W., 56 lks. Visible scribing,
original bearing tree.
Set - a 3/4" I.P.
From which:
8" Hemlock, bears N.13°30'W., 44.6 ft.
24" Hemlock, bears S.31°30'E., 44.4 ft.

11/7/75

Shaner Engineering
for Hub Lumber Company

RM 2 - 63
June 24, 1974

Robert C. Adamek
For: Weyerhaeuser Co.
Nov. 1975
C.S. 58/76
M 58 - 54