

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 27 T. S. R 8 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Cont. - - - - -
Gregory Quibell, Deputy
Doug. Co. Surveyors
Office
Karen Reed
Terry Plouff
April 27, 1982
C.S. 61/30

(Sec. cor. for Secs. 28, 29, 32, & 33) 59
Set - At record bearing and dist. from found orig. 12" now 28"
Hemlock (S.65°E., 31.0 ft.), I SET a 1" x 30" I.P. with brass
cap attached marked "Douglas County Surveyor T27S S29 S28
S32 S33 R8W 1982". Record bearing and dist. for NE BT
(N.30°E., 3.3 ft.) hits decayed wood. Record bearing & dist.
for SE BT (S.46°E., 8.6 ft.) hits decayed wood.
I place unrecorded 1/2" I.P. alongside brass cap.
New Accessories:
"W" nail in face of 15" hemlock stump bears N.4°E., 24.9 ft. to
nail.
"W" nail in face of 38" hemlock stump bears S.60°E., 10.9 ft. to
nail.
"W" nail in side of orig. NW BT (28" hemlock stump) bears N.65°W.,
29.9 ft.
Sketch in C.S. file.

Gregory Quibell, Deputy, Doug. Co. Surveyors Office
Terry Plouff
John Powell
April 29, 1982
C.S. 61/30

John Powell
May 3, 1982
C.S. 61/36

4/27/82

Section corner for Secs. 19, 20, 30 and 29 60
Found - Unrecorded 1/2" I.P. firmly set protruding 3" out of ground.
From Which:
Orig. 48" now 53" fir with well healed double blaze bears
N.55°E., 58.6 ft. (rec. 55.4 ft.) Due to several large windfalls
my dist. was taken from approx. 10 ft. above ground at both
ends, which could account for difference noted.
Orig. 24" now 30" hemlock with scribed "R8W" visible in partially
healed blaze bears S.41°E., 71.4 ft. (Rec. 69.3 ft.)
Orig. 12" now 24" hemlock windfall lying in approx. correct location
I can't see tree from cor. due to several large down trees.
Orig. 24" hemlock stump with scribed "27S 8V" visible in
partially healed blaze, bears N.12°W., 29.7 ft.
Unrecorded 4" fir with Weyerhaeuser "W" nail bears S.22°E., 7.0 ft.
Set - At the location of the found 1/2" I.P. I SET a 1" x 30" I.P. with
brass cap attached and protruding 10" out of ground. Cap is mkd.
"Doug. County Surveyors Office T27S S19 S20 S30 S29 R8W 1982"
Sketch of accessories in C.S. file.

4/29/82

1/4 Corner for Secs. 21 and 28. 61
Found - Unrecorded 3/4" I.P. firmly set protruding 13" out of ground.
From Which:
Orig. 18" now 30" fir stump with good scar bears S.32°W., 44.4 ft.
(Rec. 42.9 ft.)
Orig. 12" maple stump, rotted and broken apart with possible
reverse scribed "B" showing inside stump bears N.60°W., 48.7 ft.
Set - Since the found 3/4" I.P. did not fit the fir BT well for distance
and since the maple BT is just below an old cat road and looks
like it could possibly have been pushed over or slid over due
to the road work, I SET a 1" x 30" I.P. with brass cap attached
at record bearing & dist. from fir BT (N.32°E., 42.9 ft.) This
position also fits the maple BT fairly well. (N.58°W., 48.7 ft.)
(rec. N.60°W., 48.7 ft.) Cap is mkd: "Douglas Co. Surveyor
T27S 1/4 S21 S28 R8W 1982"
I leave the found 3/4" I.P. in the position I found it. (N.32°E.,
1.6 ft. from set brass cap.)
New Accessories:
"W" nail in face of 30" fir stump (orig. BT) bears S.32°W., 41.6 ft.
"W" nail in face of 17" hemlock stump bears N.6°W., 13.8 ft.
"PK" nail in top of 15" hemlock stump bears N.89°W., 7.0 ft.
Sketch of accessories in C.S. file.

5/3/82

1/4 Corner for Secs. 23 and 26. 62
Found - Unrecorded 3/4" I.P. firmly set protruding 10" out of ground.
Orig. 28" fir now 33" stump with pitched over previously opened
face. "W" nail in edge of face. I open more of face and find
scribed "L8" visible under layer of pitch.
Orig. 30" fir BT appears to be destroyed by logging.
Set - At rec. bearing & dist. from orig. 28" now 33" fir stump (N.62°E.,
18.5 ft.) I SET a 1" x 30" I.P. with brass cap attached marked:
"Douglas Co. Surveyor" T27S 1/4 S23 S26 R8W 1982".