

**Douglas County Surveyor's Record of
Government Corners Renewed**

T. 27 S. T. S. R. 8 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97401

(Cont. from last page)

9" now 16" dia. Cedar, with a fully healed double blaze, bears N.66°E., 39.8' (agrees with rec.) 1958 DC SO Mon. Set-DC SO BC/IP returned to plumb position, protrudes 6" above ground.
Corner lies at the intersection of a N-S and east running fence lines.

UNRECORDED 1/4 cor. secs 25 & 36

Mon. Fd.- None
Bt's Fd.- 48" dia. 2 1/2' high D. Fir stump, with a W.T.C.O. corner tag nailed on top no blazes visible, tag reads "14.7' N.38°W. to N 1/4 cor T27S R8W S36 JFE 8-21-72 UNCO 7-11-52".
12" dia. D. Fir, with flagging protruding from a small healed blaze possible W Nail inside blaze. W.T.C.O. corner tag reads "15.6' S07 1/2° E., to S 1/4 T27S R8W S25".
(Note above trees mark an intersection)
14" dia. 12' high cedar snag, with axe marks W.T.C.O. tag reads "T27S R8W S36 N 1/4 HTH JFE 8-21-72 RJOH 8-72" this tree is approx south 8' from a calc. corner position determined from above trees.

Position of OBT'S fall at edge of cat road. Note this corner not renewed in 1983 by DC SO see C.S. 58/271

DO. CO. SURVEYORS
RANDALL SMITH &
STEPHEN FLAUSE
C.S. 64/74-32
May 14, 1997

Sec. cor. to 25, 26, 35, & 36

Mon. Fd.- 2 1/2" dia. Brass cap on a 1 1/2" O.D. iron pipe, protrudes 19" above ground.
Accessories Fd. -
10" now 14" dia. 1 1/2' high broken hemlock stump, with scribing visible on a partially healed blaze "BT", bears N.81°W., 22.4' (rec. N.83°W., 22.4').
7" now 16" dia. W. Fir, with a fully healed double blaze, bears S.49°E., 18' (rec. S.47°E., 18').
13" now 14" dia. 5 1/2' high hemlock stump, with scribing visible of an open blaze "T27S R8W S25 CS", bears N.44 1/2°E., 61.8' (rec. N.46°E., 61.8').
The only remaining original BT is a 24" now down 36" dia. D. Fir, with a previously opened blaze illegible scribing found. Root hole agrees with rec. "S.56 1/2°W., 42.9'". OBT.
Mon. Set- BC/IP is surrounded by a 1 1/2' dia. mound of stone.
New Accessories -
10" dia. D. Fir double blazed and scribed "T27S R8W S26 CS BT", bears N.74°W., 15.2'.
15" dia. D. Fir double blazed and scribed "T27S R8W S25 CS BT", bears N.79 1/2°E., 15.4'.
see previous ren. # 26

DO. CO. SURVEYORS
RANDALL SMITH &
STEPHEN FLAUSE
MAY 19, 1997
C.S. 64/74-34

*FD ok
By Tony
Hostetter
M. 140-72
Aug 2002*

1/4 Cor. Secs. 25 & 36

Found - 3 BTs marked by Weyerhaeuser company (according to WEYCO records 2 original GLO BTs were found with visible scribing in 1952. The corner position was monumented with a 1/2"- alloy pipe at that time. Subsequent records indicate that the bearing trees present now reference the corner position as marked by the 1/2" pipe, which has evidently been removed by logging. No evidence of the original BTs remain).
Set - 5/8"x36" rebar w/2 1/2" cap marked "S25 S36 1/4 LS1975 2002" from WEYCO BT information From which:
12" Fir, WEYCO tag, bears N.7 1/2°W., 15.6 feet.
50" Fir stump WEYCO tag bears S.38°E. 14.6 ft to face
14" Cedar, WEYCO tag bears S.20°W., 9.1 feet.
New BTs- 10" Fir, scribed "S25 1/4 BT" bears N.52°E., 22.3 feet to spike.
14" Fir, scribed "S36 1/4 BT" bears: S.40°E., 8.9 feet to spike. Previous ren. #83

Tony Hostetter
For: Seneca
Jones Timber Co.
Aug. 2002
M142-72

85 ~~83~~

84

85