

Douglas County Surveyor's Record of
Government Corners Renewed

T. 28 S. T. S. R. 2 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Section Corner to Secs. 30 & 31, T28-2W. & Secs. 25 & 36, T28-3W. **8**
Found - All Orig. BT's. S, E. BT. dead. All check record except dist.
to N.W. BT. should be 41.0 ft., not 27.7 ft. N.W. & S. E.
Bearing Trees show scribing.

Set - Brass Cap at Cor. Mkd: County Surveyor's

S25	S30
R3W	S36
S31	S31

 T28S
Office, 1962

New BT: 7" R.Fir bears S.58°E. 10.9 ft. scribed S31 CS BT.

Renew Corner

S36	S31
R3W	S1
S6	R2W

 T27S

Found - All Orig. BT's. All are now stumps. N.E. BT. shows good scrbing.
Also find Rock Mound at Corner.

Set - Brass Cap at Cor. Mkd: County Surveyor's

S36	S31
R3W	S1
S6	R2W

 T27S
Office, 1962

New BT's: 16" Cedar bears S.27°W. 72.0 ft. scribed S1 T28S R3W CS BT.
17" Laurel bears S.3°E. 17.0 ft. scribed S6 T28S R2W CSBT.
4" R.Fir bears N.10°W. 19.8 ft. scribed S36 CS BT.
9" R.Fir bears N.87°E. 50.1 ft. scribed S31 CS BT T27S R2W.

FOUND O.K. 11/68 VRT.

Renew East $\frac{1}{4}$ Corner for Section 1, T28-3W.

Found - Orig. 12", now 18" Fir N.80°W. 13.9 ft. shows faint bark scrbing.
Orig. 36" Fir, now down. N.65°E. 33.7 ft., shows bark scribing.

Set - Brass Cap at Cor. Mkd: County Surveyor's East $\frac{1}{4}$ S1 T28S
Office, 1962 R3W R2W

New BT's: 15" Fir bears S.61°W. 31.9 ft. scribed E $\frac{1}{4}$ S1 CS BT.
13" Cedar bears N.59 $\frac{1}{2}$ °W. 19.3 ft. scribed E $\frac{1}{4}$ S1 CS BT.

1961 Renewal by U. S. Plywood.

Found - $\frac{3}{4}$ " I. P. with alumium cap at Cor. Mkd:

S1	S7
R3W	S12
R2W	R2W

 T28S
U.S. P.C. Prop. Corner.

Orig. 30", now 36" F.Snag S.70°E. 30.4 ft., no scribing found. SEE #25
Orig. 30", now 40" Fir N.5°W. 38.3 ft., shows good bark scribing.

New BT's: 7" W.Fir N.15 $\frac{1}{2}$ °W. 46.9 ft. scribed T28S
(1961) 12" W.Fir S.16°W. 18.5 ft. scribed T28S R3W S12 BT.
13" W.Fir S.84°E. 16.6 ft. scribed T28S R2W S7 CS BT.

Note - This corner was renewed by U.S.Plywood 1961, but not recorded.
Also the corner below.

Renew C. C. between Sections 6 and 7, T28-2W. **12**

Found - Orig. 16", now 30" Cedar N.82°E. 31.7 ft. shows good scribing.
Stump Hole for Orig. S.E. BT.

Find $\frac{3}{4}$ " I.P. with Aluminum Cap at Corner. - SEE REN. #24

1961 BT's: 25" Cedar S.29°E. 42.2 ft. scribed T28S R2W S7 BT.
11" W.Fir N.34°W. 12.4 ft. scribed T28S R3W S1 BT.
7" Fir N.63°W. 43.0 ft. scribed T28S R2W S6 BT.

Closing Corner between Section 7 and 18, T28-2W. **11**

Found - Aluminum Cap on Pipe at Corner set by U. S. Plywood, 1962. REN. #27
Also find both Orig. BT's, in good condition, show scars.

New BT: 21" Fir bears N.32°W. 26.1 ft. scribed S12 T28S R3W CCBT.

Renew Corner to Sections 12 and 13 only, T28-3W. **14**

Found - All Orig. BT's., except S.E. BT. Orig. 10", now 30" Cedar N.50°W.
6.0 ft. shows scar. I do not open.

Orig. 8", now 14" Fir N.50°E. 2.0 ft. opened to old face,
scribing destroyed, see record of 1910 survey.

Orig. 12", now 30" Cedar shows scar.
Set - Brass Cap at Cor. Mkd: County Surveyor's

S12	S13
R3W	R2W
T28S	T28S

New BT's: 8" R.Fir bears S.37°W. 34.4 ft. scribed S13 T28S R3W CS BT.

James W. Byron, Deputy County Surveyor
John Powell
WM. Stoffel
July 11, 1962
C. S. File No. 52/126

RE-RENEWED SEE CORNER NO # 117

RE-RENEWED SEE CORNER NO # 121

RE-RENEWED SEE CORNER NO # 114

FD OK 3/68
8444 ENG 1183419