

Douglas County Surveyor's Record of
Government Corners Renewed

T. 28 S. T. S. R. 2 W. R.W.W.M.

ROBE-CHARMAN CO., EUGENE, ORE., 21881

32

V.R. Tracy
& Crew
May, 1966
C. S. File
No.
54/26

Section Corner to Sections 28 - 29 - 32 - 33.
Found - Orig. 8", now 15" Hemlock S. 28° E. 22.4 ft. Open from
backside & find "R2W S33 BT" scribe & reverse.
Orig. 16", now 30" Fir N. 36° E. 8.5 ft., shows good scar.
We do not open.

N. W. & S. W. BT's. are gone.
Set - Brass Cap Mkd: County Surveyor's Office, 1966
T28S

S 29	S 28
S 32	S 33

 R2W
New BT's: 15" Hemlock S. 28° E. 22.4 ft. (Orig. BT) Mkd: T28S R2WS33 CS BT.
20" D. Fir S. 8° W. 13.7 ft. Mkd: T28S R2W S32 CS BT.
24" D. Fir N. 52° W. 50.8 ft. Mkd: T28S R2W S29 CS BT.
May 18, 1966

33

Section Corner: 11, 14, and 10.
(Area around section corner logged and burnt)
Found: Orig. BT: 42" D. Fir, now stump, N. 64° E. 16.1 ft., Orig. scribe vis.
Orig. BT: 32" Cedar, now 23" Cedar Stump, S. 45° E. 39.9 ft.,
(Orig. Face burnt out, rescribed)
Set: Reset: 2 1/2" Brass Cap, See Ren. #28
28" Doug. Fir Stump N. 69° W. 11.3 feet.

34

Section Corner: 10, 15, & 14.
(Area around section corner logged and burnt)
Found: Orig. BT, 42" Hemlock, now 52" Hemlock Stump, S. 57 1/2° W. 12.7 ft.,
Orig. scribe visible, rescribed.
Orig. BT: 24" Hemlock Snag, burnt to stub, N. 12° W. 29.0 ft.
Scribed 9-9-63: 8" Yew - destroyed.
Set - Reset 2 1/2" Aluminum Cap, See Ren. #29.
36" Doug. Fir Stump, N. 50° W. 64.0 ft.

35

1/4 Sec. Corner, Section 10 only, T28S R2W.
Area around 1/4 corner has been logged & the Orig. BT's. destroyed.
Before logging, I buried 3/4" x 36" Iron Rod at 1/4 Corner from Orig. BT's.
From 3/4" x 36" Rod, Set:
2 1/2" Aluminum Cap.
54" Doug. Fir Stump, N. 63° W. 48.5 ft.
40" Cedar Stump, S. 48° W. 15.3 ft.

36

1/4 Corner to Section 11 only, T28-2W.
Area around 1/4 corner has been logged & the Orig. BT's. destroyed.
Before logging, I buried 3/4" x 36" Iron Rod at 1/4 Corner at
location of 2" Brass Cap.
From 3/4" x 36" Rod; Set: Orig. 2" Brass Cap.
72" Doug. Fir Stump, N. 44° E. 69.4 ft.
48" Cedar Stump, N. 83° E. 13.3 ft.

37

Section Corner: 9, 10, 15, 16.
Found: 22" Doug. Fir, N. 42° E. 120.5 ft.)
17" Doug. Fir, N. 21 1/2° W. 150.5 ft.) See Ren. #30
18" Doug. Fir, S. 39 1/2° W. 135.0 ft.) #153
Set: 2 1/2" Aluminum Cap.
(This corner falls in a rock pit.)

MICROFILM TO HERE 10/67

38

Section Corner to Sections 29 - 30 - 31 - 32.
Found - 30" D. Fir, now stob, N. 63° E. 99.0 ft., scribe visible "T28S R2W".
30" D. Fir, now stob, S. 69° E. 51.5 ft., scribe visible "T28SR2W S32BT"
26" D. Fir, now stob, N. 68° W. 67.0 ft. (Rec. 56.8') scribe visible.
12", now 34" Yellow Pine S. 34° W. 73.1 ft., shows good scar.
Stone at corner, no marks visible.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1968
T 28 S R 2 W

S 30	S 29
S 31	S 32

(continued over)

Thomas E. Shrum, Jr.
U. S. Plywood Corp.
July, 1966
C. S. File No. 55/7

John M. Powell
Frank Jones & W. Penley
Feb. 8, 1968
C. S. File No. 54/26