

Douglas County Surveyor's Record of
Government Corners Renewed

T. 28 S. T. S. R. 2 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97101

46

1/4 Corner to Sections 14 and 23.

Found - 1923 GLO Brass Cap, properly marked,
22", now 24" W. Fir, alive, N. 20° E. 29.7 ft., shows good scar.
We do not open.

10", now 16" Hemlock, alive, brkn. top about 40 ft. up, S. 20° W.
18.5 ft., shows good scar. We do not open.

New BT's: 8" Hemlock S. 67° W. 9.8 ft. mkd. "1/4 S23 CS BT".

10" D. Fir N. 23° W. 6.7 ft. mkd. "1/4 S14 CS BT".

This corner lies on moderate W. slope approx. 400 ft. W. of USFS Road
Rd. #2834, line tag on 17" Hemlock on E. side of road.

RE-RENEWED SEE CORNER NO. #145

Vernon "Ray" Tracy
Jack Heritage & V. Perron
July 11, 1968
C. S. File No. 54/26

47

Section Corner to Sections 27 - 28 - 33 - 34.

Found - Old Decayed Wooden Post at Corner Point.

Orig. 14", now 20" Fir, alive, N. 77° E. 16.5 ft., shows good scars.
We do not open.

Orig. 8", now 10" Fir Snag, S. 44° E. 5.9 ft., shows good scars.
We do not open.

Orig. 5" (?), now 22" Pine, alive, S. 29° W. 4.6 ft., scribe marks
visible in narrow unhealed portion of upper scar.
We Rescribe "T28S R2W S33 CS BT".

Orig. 12", now 16" Fir, alive, N. 20° W. 7.3 ft., shows good scar.
We do not open.

Set - Brass Cap at Cor. MKd: County Surveyor's Office
1968

T 28 S	R 2 W
S 28	S 27
S 33	S 34

New BT: 8" Cedar S. 53° E. 16.8 ft. mkd. T28S R2W S34 CS BT.

This corner lies on moderate E. slope. 10/1970 FOUND O.K. C.S. 54/40

7/11/68

SECT. 68

48

North 1/4 Corner to Section 1 only, T28-2W.

Found - 1923 GLO Brass Cap under log and bent over.

Orig. 48", now 50" Fir, alive, S. 26° E. 139.9 ft., blzd, no scribe visible.

Orig. 84", now 85" Fir, dead, S. 43° W. 49.5 ft., open & fd. "1/4 BT" scribe.

Reset - Brass Cap at Cor. Point & Remove Portion of Log.

New BT's: 80" D. Fir S. 23° W. 43.0 ft. mkd: "1/4 S1 CS BT".

15" R. Fir S. 62° E. 116.6 ft. mkd: "1/4 S1 CS BT".

This corner lies on northerly slope in dense vine maple thicket.

Vernon "Ray" Tracy
J. Heritage & V. Perron
October, 1968
C. S. File No. 54/40

49

Cl. Corner to Sec. 1, T28-2W and Sec. 6, T28-1W.

Found - No trace of corner stone called for at Cl. Cor.

Orig. 18", now 36" Fir, alive, S. 71° E. 49.5 ft., shows good scar.

Orig. 12", now 24" Fir, alive, S. 79° W. 41.6 ft., shows good scar.,
We open & find scribe marks.

Set - Brass Cap at Cor. MKd: County Surveyor's Office, 1968

T27S	R2W	S 1	S 6	R1W
T28S	R2W	S 1	S 6	

New BT's: 20" D. Fir S. 10° W. 7.9 ft. mkd: "T28S R2W S1 CC CS BT.

14" D. Fir S. 42° E. 14.2 ft. mkd: T28S R1W S6 CC CS BT.

This corner lies on steep S.W. slope about 413 ft. W. of Standard
Corner of T27S, R's. 1W. and 2W.

Cl. Corner to Sections 1 and 2, T28-2W.

Found - 1923 GLO Brass Cap, properly marked, in place.

Orig. 9", now 30" Fir, alive, S. 5° W. 75.2 ft., shows good scar.

Orig. 6", now 24" Fir, alive, S. 48 1/2° E. 147.2 ft., shows good scar.

New BT's: 14" D. Fir S. 73° W. 12.3 ft. mkd: T28S R2W S2 CC CS BT.

15" D. Fir S. 34° E. 5.0 ft. mkd: T28S R2W S1 CC CS BT.

This corner lies on steep easterly slope in second growth fir.

RE-RENEWED SEE CORNER NO. #129

50

North 1/4 Corner to Section 2 only, T28-2W.

Found - 1923 GLO Brass Cap, in place and properly marked.

40", now 46" Fir, dead, S. 41° E. 35.6 ft., scribe visible, "S2 BT".

10", now 13" Yew, alive, S. 16° W. 18.5 ft., good condition, scribe vis.

New BT: 7" D. Fir S. 26 1/2° E. 25.0 ft. mkd: "1/4 S2 CS BT".

This corner lies on south slope about 310 ft. west of Angle Point on
south line of section 35, T27-2W, see corner below.

75

51