

Douglas County Surveyor's Record of
Government Corners Renewed

T. 28 S. T. S. R. 2 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Angle Point Section 31 and 6, T28-2W. (S. of $\frac{1}{4}$ Corner) 59
Set - 2 $\frac{1}{2}$ " diam. Aluminum Cap, "A.P. T27S R2W S6 S31 T28S. #118
10" D. Fir, S. 65° E. 10.1 ft., "A.P. S 6, B.T. R.E. 4287".
10" D. Fir, N. 02° W. 33.3 ft., "A.P. S31, B.T. R.E. 4287".

Angle Point Section 6 and 31, T27-2W (S. of NE Cor. Sec. 6) 60
Set - 2 $\frac{1}{2}$ " diam. Aluminum Cap, "A.P. T27S R2W S6 S31 T28S. #130
6" Madrone N. 03° W. 27.7 ft. mkd: "A.P. S31 B.T. R.E. 4287".
6" D. Fir S. 43° W. 23.1 ft. mkd: "A.P. S6 B.T. R.E. 4287".

$\frac{1}{4}$ Corner to Section 6 and 5. 61
Set - 2 $\frac{1}{2}$ " diam. Aluminum Cap, mkd: " $\frac{1}{4}$ S6 S5, USPC Prop. Cor. R.E. 4287".
6" D. Fir S. 56° W. 12.3 ft., " $\frac{1}{4}$ S6 B.T. R.E. 4287".
6" D. Fir S. 68° E. 10.9 ft., " $\frac{1}{4}$ S5 B.T. R.E. 4287".

Center $\frac{1}{4}$ Corner to Section 6. 62
Set - 2 $\frac{1}{2}$ " diam. Alumin Cap mkd: "U.S.P.C. Prop. Cor. T28S R2W S6 RE4287".
72" D. Fir N. 32° W. 35.4 ft. mkd: "S6 B.T. R.E. 4287".
34" D. Fir S. 81° W. 42.5 ft. mkd: "S6 B.T. R.E. 4287".

$\frac{1}{4}$ Corner Section 6 only, T28-2W. (West Side). 63
Set - 2 $\frac{1}{2}$ " diam. Aluminum Cap Mkd: T28S R2W S6 R.E. 4287.
24" Madrone N. 46° E. 54.4 ft. Mkd: S6 BT. R.E. 4287.
26" Madrone S. 79° E. 82.3 ft.

Closing Corner Sections 5 & 4. 64
Found - Unrecorded $\frac{3}{4}$ " I.P. set from one O.B.T.
Orig. 12" now 20" Laurel S. 68°W. 11.2 Ft. alive- opened & found
S R. 2 scribe & Reverse. No trace O.B.T. to S.E.
~~DO NOT SET BRASS CAP. We mark new BTS~~
18" Chinquapin S. 20°W 31.5 Ft. Mkd. T28S R 2 W S4 CC CS BT
30" D. Fir S. 62° E 34.7 Ft. Mkd. T 28S R 2 W S4 CC CS BT
20" Laurel S. 68°W 11.2 Ft. Remark O.B.T. CC S5 CS BT.
The A.P. Cor. (old S.C. of S32 & 33 27.2) Bears East 96.3 Ft. #135
6-12-69

Closing Corner Sections 5 & 4 T 28 R 2W 65
Found - Unrecorded $\frac{3}{4}$ " I.P. set from one O.B.T.
Orig. 12" now 20" Laurel S. 68°W. 11.2 Ft. alive- we open &
find S. R. 2 scribe & Reverse. No trace O.B.T. to S. E.
~~DO NOT SET BRASS CAP Mark new BTS~~
18" Chinquapin S. 20°W 31.5 Ft. Mkd. T 28 S R 2 W S 5 CC CS BS
20" Laurel S. 68° W. 11.2 Ft. Remark O.B.T. CC S5 CS BT
The A.P. Cor. old(S.C. of 32 & 33 27.2) Bears East 96.3 Ft. 6-12-69

Renew Angle point on S. Lines 32, T27-2 66
Found - Unrecorded $\frac{3}{4}$ " I.P. at Cor. point & o.B.T.s as Follows:
Orig. 12" now 20" cedar S. 62°E. 5.3 ft. Open & found scribe
Orig. 8" now 12" Hemlock N. 12°W 13.2 Ft. Down & Decaying
Previously opened blaze rotted away. $\frac{3}{4}$ " I.P. in good cond.
~~DO NOT SET BRASS CAP - Mk. new BTS: 18" Cedar N. 35° E. 23.9 ft. mkd: "AP CS BT".~~
22" Cedar S. 18° E. 6.3 ft. mkd: "AP CS BT".
This cor. lies on moderate southerly slope in old growth
timber.
Note - This corner located at point for N $\frac{1}{4}$ corner Sec. 5, T28-2
6-12-69

Thomas E. Shrum, Jr.
For U.S. Plywood, Corp.
December, 1968
Map File M 37 - 17

M 37 - 17
(see above)

Vernon "Ray" Tracy
J. Heritage & Vernon Perron
6-12-69
C. S. File No. 54/40

RE-RENEWED, SEE CORNER NO. #118
RE-RENEWED, SEE CORNER NO. #130
RE-RENEWED, SEE CORNER NO. #120
RE-RENEWED, SEE CORNER NO. #119
RE-RENEWED, SEE CORNER NO. #135
RE-RENEWED, SEE CORNER NO. #133