

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 28 S. T. S. R. 2 W. R. W. W. M.

Section Corner to Sections 20 - 21 - 28 - 29.  
Found - 12", now 16" Cedar, N. 26° E. 8.6 ft. scribe visible.  
10" Yew, now down, S. 33° E. 17.2 ft., scribe visible.  
18" Cedar, now dead, S. 42° W. 33.7 ft., scribe visible.  
No trace of N. W. Bearing Tree.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1971

T 28 S	R 2 W
S 20	S 21
S 29	S 28

New BT's: 15" Hemlock N. 9° W. 49.3 ft. scribed "T28S R2W S20 CS BT".  
6" Hemlock S. 9° E. 51.5 ft. scribed "T28S R2W S28 CS BT".  
22" Hemlock S. 11° W. 70.0 ft. scribed "T28S R2W S29 CS BT".

2/10/71

John M. Powell  
W. Penley & J. Heritage  
C.S. File No. 54/26

1/4 Corner to Sections 21 and 28.

Found - 10", now 15" Cedar, S. 14° E. 10.6 ft., shows good scar.  
7", now 11" Hemlock, N. 21° W. 8.6 ft., opened for scribe.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1971

T 28 S	R 2 W
1/4	S 21
	S 28

New BT: 16" Hemlock N. 33° E. 16.3 ft. scribed "1/4 S21 CS BT".

2/10/71

MARCH 71

1/4 Corner to Sections 28 and 33.

Found: 24" Cedar, now 32", S. 13° E., 35.0 ft. Shows very good scar.  
10" Hemlock, now 16", N. 55° E., 5.9 ft. Shows very good scar.

Note: As trees hit bearing & dist. also hit call of one chain east of creek, I do not open.

Set: Brass Cap at 1/4 cor. mkd. County Surveyor's Office, 1971

T 28 S	R 2 W
1/4	S 28
	S 33

All trees in good shape & tagged.

7/30/71

JAN 1972

John M. Powell  
W. Penley  
J. Heritage  
V. Perron  
C. S. File 54/26

North 1/4 Corner Section 2 only.

Found - All BT's as recorded in Ren. #51.

No trace of 1923 GLO Brass Cap due to Cat. fire trail.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1972

1	T 27 S	R2W
4	S 2	T28S

No New Bearing Trees Marked.

This corner lies 310 ft. W. of Angle Point on N. side of Cat. Fire Trail and on S. side of clearcut unit.

6/28/72

JAN 1973

Vernon R. Tracy

C.S. File No. 54/40

1/4 Corner Section 31 only.

Found - 2" D. Fir, now 12", S. 8° W., 22.2 ft. Shows scar.

1 1/2" D. Fir, now 11", S. 55° E., 10. 2 ft.

Also Truck axle at 1/4 Corner. Ren. No. 1

Due to trees south of township line and not scribed, I scribe,

New BT's - 13" D. Fir, N. 46 1/2° E., 29.6 ft. scribed 1/4 S31 CS BT.

4" Cedar, N. 86° E., 2.9 ft. scribed 1/4 S31 CS BT.

3/14/73

John M. Powell  
J. Heritage  
G. Commons  
C. S. File 56/25  
March 14, 1973

Section Corner, Sections 6 & 5 only, T. 29-2.

Found - 1" I. Pipe at corner. Ren. No. 2

3" D. Fir, now 7", S. 41° E., 19.0 ft. scribe visible "S5".

3" D. Fir, now 8", S. 1° W., 45.5 ft. Shows scar.

NE and SE BT's other than the above, cut.

New BT - 7" @. Fir, North 18.1 ft. scribed T28S R2W S31 CS BT.

All trees tagged.

3/14/73

1/4 Corner, Section 6 only T29-2.

Found - 1917 GLO Brass cap at 1/4 Corner.

14" D. Fir, now stump, S. 14° E., 40.9 ft. shows good scar.

18" D. Fir, now stump S. 80° W., 23.1 ft.

New BT's - 30" Laurel, S. 63° E., 39.2 ft. scribed 1/4 S6 CS BT.

6" Live oak, S. 65° W., 53.4 ft. scribed 1/4 S6 CS BT.

78