

Douglas County Surveyor's Record of
Government Corners Renewed

T. 28 S. T. S. R. 3 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97501

113

Closing Corner to Sections 6 and 7, T28-2W.

Found - 18" Cedar S.21°E. 56.4 ft.

31" Cedar N.84°E. 34.0 ft.

(SEE # 74 for Sept. 1962 visit)

Set - 2½" Aluminum Cap and: 21" Cedar S.28½°E. 42.5 ft.

9" W. Fir N.35°W. 12.5 ft.

7" W. Fir N.62½°E. 44.0 ft.

114

S. Corner to Sections 1 and 12 only.

Found - 41" Fir N. 3°W. 40.0 ft.

24" Fir S. 51°E. 14.0 ft. #152

39" Fir N.28°E. 28.0 ft.

36" Fir Stump S.87½°W. 21.2 ft. See #73 Also

Set - 2½" Aluminum Cap &: 11" W. Fir S. 14½°W. 18.2 ft.

13" W. Fir S. 83°E. 17 ft.

11" W. Fir N. 15°W.

115

¼ Corner to Section 7, T28-2W.

Set - 2½" Aluminum Cap & 18" Hemlock N.68°E. 26.4 ft.

22" Cedar S.54°E. 46.2 ft.

116

Closing Corner to Sections 7 and 18, T28-2

Found - 32" Fir S. 59°E. 30.0 ft.

21" Fir N. 81½°E. 57.8 ft.

Set - 2½" Aluminum Cap and 20" Fir N. 33°W. 26.3 feet. See Also #75

117

¼ Section Corner: Sections 10 and 11.

Found: ¾" Iron Rod - Iron Rod was set by me from Orig. BT's. in 1957. Subs. logging destroyed all BT's. I now replace iron rod with 2½" alum. cap & reference.

Set: 2½" Aluminum Cap

14" Cedar, S. 31° W., 25.9 ft. Mkd: ¼ S10 BT.

28" D. Fir stump N. 23° E., 41.5 ft. Mkd: ¼ S11 BT.

118

Renewed Corner

T27S

R4W S 36 / S 31 R3W

T28S

Found - Wooden Stake at Corner. See Ren. Cor. No. 25

20" Laurel N. 22°W. 12.5 ft. scribed "S36 T27S R4W CS BT" in 1961, Alive & in good condition.

32" Laurel N. 50°E. 13.0 ft. scribed "S31 T27S R3W CS BT" in 1961 Alive & in good condition.

Other Two Original Bearing Trees no longer showing scribe marks.

Drive - ¾" Iron Rod at Corner in place of Wooden Stake.

119

South ¼ Section Corner: Section 34 only, T27S R3W.

Found - 4" x 4" x 6' Cedar Post

Doug. Fir Stump N. 45° W., 24.0 feet (burned off)

Doug. Fir Stump S. 40° E., 26.0 feet (burned off)

Set - 2½" Aluminum Cap

10" Cedar, N. 34½° W., 30.9 feet, Mkd: ¼ SC S34 BT.

8" Madrone, N. 63° W., 35.2 feet, Mkd: ¼ SC S34 BT.

120

¼ Section Corner: Sections 3 and 4, T28S R3W.

Found - ¾" Iron Rod

32" Doug. Fir Stump, N. 45½° W., 28.4 feet.

4" x 6" aluminum reference tag - 1957.

Set - 2½" Aluminum Cap

34" Doug. Fir Stump, S. 87° E., 36.0 feet, Mkd: ¼ S 3 BT.

33" Doug. Fir Stump, S. 01° W., 35.5 feet, Mkd: ¼ S 4 BT.

Thomas E. Shrum, Jr.
For U. S. Plywood Corp.
June 1962
Map File M 25 - 7

Thoms E. Shrum, Jr.
For U.S. Plywood
Jan. 1963
O.S. File
No. 51/254

Milo E. Godfrey
& Crew
Oct. 11, 1963
C. S. File
No. 53/33

Thomas E. Shrum, Jr.
For U. S. Plywood, Inc.
April 1963
C. S. File No. 51/254

RE-RENEWED, SEE CORNER NO. #152

RE-RENEWED, SEE CORNER NO. #147

RE-RENEWED, SEE CORNER NO. #167