

Douglas County Surveyor's Record of
Government Corners Renewed

T. 28 S T. S. R. 3 W. R.W.W.M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

135

Corner for Secs. 31 and 32 only. (South)

Found - A 1" I.P. with 1962 County brass cap properly marked. Ren. #50

A 15" now 34" D. Fir bears N.9°E., 42.2 ft. with a well healed double blaze.

A 10" now 18" D. Fir bears N.32°W., 50.8 ft. (Rec. 52.8 ft.) with visible scribing "8 SR 3 W" in a chopped open, partially healed blaze.

No monument set. Stamped "CC" on cap to read "County Surveyors Office"

T 28 S R 3 W
CC
S 31 S 32
1962

R. B. Kimberling
F. C. Silagy
Jan. 5, 1978
C.S. 59/46

No new accessories.

Jan 78

136

Standard Corner for Secs. 13 and 14

Found - 2 1/2" Alum. cap on a 1" I.R. Cap is 10" above ground surface & firmly set. Orig. corner stone is lying alongside. Stone is marked with 2 notches on one face & one notch on a face 90° from previous notched face. Ren. #15

A 36" Hemlock stump bears N.67°W., 42.6 ft. scribing visible "S14 RE4 28T BT".

A 42" Fir stump bears N.15°30'E., 32.6 ft. scribing visible "S13 RE 428T".

A 42" Fir stump bears N.37°E., 32.8 ft. No scribing or healed blazes visible.

A 42" D. Fir stump bears S.55°E., 44.2 ft. No scribing or healed blazes visible.

A 18" Yew snag bears S.12°15'E., 96.0 ft. scribing visible, "S23 RE 4 28T BT".

New BT's- A 5" D. Fir bears N.14°45'W., 46.2 ft. scribed "X BT" on a double blaze.

A 5" D. Fir bears S.62°W., 73.7 ft. scribed "X BT" on a double blaze.

No other trees of sufficient suze available.

Corner lies 100 ft. South of F.S. Rd. #2806 in clearcut.

5/25/78

137

1/4 Corner for Secs. 28 and 27.

Found - The orig. corner monument, a granite stone, 10" x 12" x 16" in size, firmly set 11" in the ground, with faint "1/4" chiseled on the west face.

An orig. 24" now 34" D. Fir, alive with well healed single blaze bears East 6.6 ft.

An orig. 24" now 27" D. Fir alive with well healed single blaze bears N.34°W., 21.8 ft.

Due to proposed logging in this area, we bury the corner stone one foot deep at the corner point. No other corner monument set.

New Accessories:

A "P-K" masonry nail set in a notch along the SE base of a 32" D. Fir bears S.58 1/2°W., 37.6 ft.

A "P-K" masonry nail set in a notch along the SE base of the orig. NW bearing tree, a 27" D. Fir bears N.35°W., 20.1 ft.

A "P-K" masonry nail set in a notch along the SW base of a 22" I. Cedar, bears N.42°E., 63.4 ft.

A "P-K" masonry nail set in a notch along the westerly base of the orig. East BT, a 34" D. Fir bears S.86°E., 6.0 f.

8/10/78

138

Section corner for 5 and 4 only. T.29-3

Found - 3/4" Iron pipe. Ren. #40

I Set - A brass cap alongside mkd. 5, 4, T29S R3W 1978

From which:

16" now 20" Madrone BT scribes vis. bears S.45°E., 13.5 ft.

10" D. Fir, I scribe "T29S R3W S5 BT" bears S.33°W., 54.5 ft.

46" D. Fir orig. BT snag, face chopped out bears S.50°E., 24.4 ft.

44" D. Fir, orig. BT, blowdown, bears S.70°W., 21.8 ft.

36" D. Fir orig. BT, blowdown bears N.20°E., 14.5 ft.

4" Madrone BT, bears West, 5.2 ft.

9/25/78

Bruce A. Shaner
LS #430
For: Longview
Fibre Lbr.
Sept. 25, 1978
M 73 - 52

Dennis Gaylord
U.S.F.S.
Deputy, Doug. Co.
Surveyors Office
Witness: Randall
Lopez
May 25, 1978
C.S. 60/11

Gary Langlitz
Stephen Flause
Doug. Co. Surveyors
Office
August 10, 1978
E.S. 59/30
MOVED TO
CS 63/129-11

RE-RENEWED CORNER NO. #158

RE-RENEWED CORNER NO. #168

See c.s. 63/129-11 for 3/31/88 CORNER REPORT. LOGGING STILL PENDING.