

**Douglas County Surveyor's Record of  
Government Corners Renewed**

T. 28 T. S. R. 3 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97401

Roseburg Resources  
Sept. 1991  
C.S. 63/129  
M. Smalley L.S. 2354

1/4 corner to secs. 27 & 28  
Bt's Fd. - 36" Fir Stump, bears S.57°W., 37.6' from corner. **171 168**  
24" Fir Stump, bears N.31°W., 20.1' from corner.  
Mon. Set - 5/8" x 48" Iron rod with Aluminum Cap  
No live tee available for new BT's. Shrum date unknown not of record.  
Corner is down hill from the 28-3-27 road in a recently logged clearcut.  
See C.S. 64/71-9 for corner renewal of 35/36  
See Renewal # 137

Douglas County Surveyors Office  
Randall Smith & Stephen Flause  
10/12/95  
C.S. 64/64-3

**169**  
1/4 COR OF SECS. 34 & 35  
Mon Fd. - 2 1/2" dia DCSO Brass cap a 1 1/2" O.D. Iron pipe protruding 17" above ground.  
6"x8"x14" granite stone with the marks "1/4" on south face is found along south edge of BC/IP. (orig. corner stone) Note: corner stone noted as not found in ren #83.  
Bt's Fd. - 24" now 36" dia. 2' high burnt cedar stump with evidence of a lower blaze no scribing visible, bears S.35°W., 7.3' to blaze, metal FC post near, center bears S.41°W., 7.9'.  
10" now 28" dia. 1' high burnt cedar stump, no blaze or scribing, center burnt out, bears S.76°E., 29' to center.  
10" now 10" dia. D.Fir, with unhealed double blaze, scribing visible "1/4 S35 BT" bears N.62°E., 1.7'.  
New Bt's - 36" dia. 2 1/2' high D.Fir stump, with an 8" long boat spike set through a Bt tag, near center of stump, top of boat spike is stamped "BO 1", boat spike bears S.12 1/2°E., 18.4'.  
40" dia. 3' high D.Fir stump, with an 8" long boat spike set through a BT tag, near center of stump, top of boat spike is stamped "BO 2" bears N.88°W., 88'.  
corner is approx 45' east of a gravel road in a burnt clear cut.  
metal fence post 1' north of BC/IP  
See Renewal # 83

Douglas County Surveyors Office  
Randall Smith & Stephen Flause  
Jan. 21, 1997  
C.S. 64/71-10

**170**  
Sec. cor. to 1, 2, 11, & 12 see previous ren. #121  
Mon. Fd. - 2 1/2" Dia. Alum. cap on a 1" O.D. iron pipe protrudes 10" above ground. markings on top of cap orientated west (set by Thomas Shrum date unknown). **US PROPERTY COR.**  
T28S R3W  
S 2 | S 1  
S11 | S12  
RE 4278  
3/4" I.R. noted in ren. #98 by DCSO not seen.  
Accessories Fd. -  
14" now 27" Dia. 4' high D.Fir stump, with an unhealed double blaze, scribing visible "T28S R3W S12 BT", bears S.33°E., 28.4'. OBT  
10" now 10" dia. 2' high rotted D.Fir stump, with scribing visible "T28S R3W S11 CS BT", bears S.19°W., 26'.  
8" now 10" dia. Yew, with an unhealed double blaze, scribing visible "S2 CS BT", bears N.5°W., 28.8'.  
6" now 14" dia. W.Fir, with a fully healed double blaze, scribing bears N.72 1/2°E., 10.3'.  
24" now rotted W.Fir Stump no blazes or scribing visible, bears N.13 1/2°E., 11.2'.  
8" now 10" dia. Yew, with an unhealed double blaze, scribing visible "S12 BT", and alum. tag in lower blaze "RE 4287", bears S.57°E., 19.8'.  
New Accessories -  
14" dia. D.Fir double blazed and scribed "T28S R3W S2 CS BT", bears N.62°W., 17.3'.

see next Pg